# This document courtesy of:



Data Weighing Systems, Inc.

# Contact Us

For immediate assistance call 1-800-750-6842




**Operating Instructions** 

# **Sartorius LA Reference**

LA Models

Electronic Analytical and Precision Balances



# **Intended Use**

The LA Reference Series from Sartorius offers precision balances for measurement of mass (weight). The balances in this series have capacities ranging from 0.1 mg to 64 kg.

A broad range of special performance features make the LA Reference balances ideal for use as measuring and test equipment in ISO or GLP quality management systems. These features include:

- The fully automatic self-calibrating and adjustment function, isoCAL (timeand temperature-dependent)
- reproTEST for quick determination of the standard deviation to check the reproducibility of results
- ISO/GLP-compliant recording capability for printouts
- Password-protected menu lock

LA Reference balances meet the highest requirements on the accuracy and reliability of weighing results through the following features:

- Efficient filtering-out of vibration
- Stable and reproducible results
- Excellent readability under any lighting conditions
- Rugged, durable weighing system

LA Reference balances save work and speed up simple routine applications through:

- Ultrafast response times
- Built-in application programs, including Application 1:
  - Toggling between two weight units
  - Counting
  - Weighing in percent
  - Animal weighing
  - Recalculation
  - Calculation

2

- Density determination
- Differential weighing
- Air buoyancy correction
- Diameter determination

- Application 2:
- Checkweighing
- Time-controlled functions

# Application 3:

- Totalizing \_
- Formulation Statistics
- - with the following additional functions:
  - Second tare memory
  - Identification codes
  - Product data memory
  - SQmin function
  - Manual data storage in application level 3
  - DKD uncertainty of measurement
- Automatic initialization when you switch on the balance
- Easy input of alphanumeric sample, lot and balance IDs
- Flexible, easy-to-use display and control unit
- Optional connectivity for control through an on-line computer

## Hotline:

For advice on the use of these applications, just call or fax your local Sartorius office. For the address, please visit our Internet website at: www.sartorius.com

# Contents

- Intended Use 2
- 2 Contents
- **Safety Precautions** 3
- 3 **Operating Design**
- 7 Getting Started

## Configuration

- 12 Setting the Language
- Navigating in the Setup Menu 13
- Entering Date and Time 14
- Setting the Balance Functions 15
- Balance Functions (Overview) 16
- 18 Setting the Device Parameters
- 18 Entering a Password
- Setting the Application Parameters 22
- Selecting the Printout Function 30
- 31 Printout Parameters (Overview)
- **Printout Configuration** 32
- Device Information 34

# Operation

- 35 **Basic Weighing Function**
- **Device** Parameters 38
- Calibration/Adjustment 40
- Application Programs 49
- Toggle between Two Weight Units 49
- 51 Counting
- Weighing in Percent 54
- 57 Animal Weighing
- Calculation 61
- **Density Determination** 63
- 68 Differential Weighing
- 79 Checkweighing
- **Time-controlled Functions** 84
- Totalizing 86
- 90 Formulation
- 93 Statistics
- **Additional Functions** 97
- 97 Second Tare Memory
- Individual Identification Codes 99
- Saving Values Manually 103
- Product Data Memory 104
- 106 **SQmin Function**
- 108 DKD Uncertainty of Measurement
- 110 **Combining Applications**
- Examples of Application 111 Combinations
- 113 Data Output Functions
- 122 Pin Assignment Chart
- **Error Codes and Messages** 124
- **Care and Maintenance** 127 128 Instructions for Recycling

#### **Overview** 129

Index

Appendix

143

145

146

- 129 General Views
- 133 Specifications
- Accessories (Options) 140 141 Declaration of Conformity EC Type Approval

Plates and Markings

Entering the General Password

# **Safety Precautions**

# **Operating Design**

This balance has been constructed in accordance with the European Directives as well as international regulations and standards for operation of electrical equipment, electromagnetic compatibility, and stipulated safety requirements. Improper use or handling, however, can result in damage and/or injury.

Read these operating instructions thoroughly before using your balance to prevent damage to the equipment. Keep these instructions in a safe place.

Follow the instructions below to ensure safe and trouble-free operation of your balance:

- ▲ Do not use this balance in a hazardous area/location
- ▲ Make sure that the voltage rating printed on the AC adapter is identical to your local line voltage
- The only way to switch the power off completely is to disconnect the AC adapter
- Type of protection for the housing:
   Balances with a readability ≤ 0.1 mg
  - Balances with a readability ≤ 0.1 mg comply with IP42
     LA64001S, LA34001S, LA16001S,
  - LA64001S, LA34001S, LA16001S, LA34001P and LA34000 meet IP44 requirements
  - Additional balances with a readability
     ≤ 1 mg comply with IP54
- AC adapters meet IP20 requirements
   Protect the AC adapter from contact with liquid.
  - Connect only Sartorius accessories and options, as these are optimally designed for use with your LA Reference balance.
- Meaning (ABC) Alphabetic keys Please see section on "Text Input"
- On | off key Turns the balance on and off or switches it to the standby mode
- (Setup) Menu settings Accesses and exits the Setup menu
- (1) Toggles to the next application program
- CF Clear function Deletes keypad input Interrupts a calibration and adjustment routine in progress Quits application programs
- Print key Outputs displayed values or data logs to the serial communications and | or printer port

When cleaning your balance, make sure that no liquid enters the balance housing; use only a slightly moistened cloth to clean the balance.

Do not open the balance housing. If the seal is broken, this will result in forfeiture of all claims under the manufacturer's warranty.

In case you have any problems with your balance:

 contact your local Sartorius office, dealer or service center

## **Operating Design**


The balances in the LA Reference Series consist of a weighing cell and a display and control unit. In addition to the choice of power supply (via AC adapter or external rechargeable battery pack), your balance also has an interface port for connecting a printer, computer or universal remote control switch. The display and control unit and the weighing cell can be set up separately. Operation of LA Reference balances follows a uniform "philosophy" which is described in this manual. Where not expressly indicated otherwise, the uses described in this manual apply to verified and verifiable balance versions (indicated by the suffix "-OCE" in the model number), as well as the standard version.

## **Combination of Several Applications**

You can combine the use of various application programs to meet your more complicated requirements. To select application programs one after the other, press () (toggle function).

#### Keys

Your LA Reference balance is operated either by using the keys on the display and control unit or via a connected PC. Operation by means of the balance keys is described in the following.



Enters a decimal point

- 1 ... 9 0 keys See the section on "Numeric Input"
- (Tare) Tares the balance

Numeric Input To enter numbers: press  $1 \dots 9 0$ 

To store numbers entered: press the corresponding function key directly below the soft key label

To delete an entire numeric input digit by digit: press the  $\bigcirc$  key

Text Input To enter numbers: see the section on "Numeric Input"

- To enter letters or characters: press the (ABC) key
- > Letters are displayed in the bottom line for selection
- To select a different letter: press the corresponding soft key to change the letter shown
- To select the letter | character shown: press the corresponding function key below the soft key label
- > The selected letter is shown on the display
- Enter the next letter | character, if desired, as described above
- $\bigcirc$  To exit the letter input mode (e.g., if the last character entered is a letter): press the (ABC) key
- To store a word: press the corresponding function key (soft key), such as **I D**
- To delete an input character by character: press the CF key
- To delete user data: enter  $\bigcirc$  or a space and save


# **Operating Design**

# Function Keys (Soft Keys)

The current function of soft keys is indicated in the bottom line of the display (footer).

Texts (abbreviations) or symbols can be displayed.

Texts (Examples) Cal: Start calibration | adjustment S ID: Save ID



The function keys are numbered from right (F1) to left (F6).

## Symbols

The bottom line shows the following symbols:

- Sack to the initial state (in the Setup menu: exit Setup)
- Go to the higher selection level
- Show sub-items under the active item
- Move upward in the input | output window
- Move downward in the input | output window
- J Set the selected menu parameter

# Labeled Keys


These keys always have the function indicated, but are not available at all times. Availability of these functions depends on the current operating status and menu settings.

There are two fundamentally different types of display:

- display for weights and calculated values
- display for menu parameter settings (setup)

# Operation

**Display for Weights and Calculated Values** This display is subdivided into 9 areas.



Line for Metrological Data: When the balance is used in legal metrology, the following metrological specifications of the balance are shown here:

- Max Maximum capacity (upper range limit) of the balance
- Min Minimum capacity (lower range limit) of the balance
- $\mathbf{R} \mathbf{1}$  Display when  $\mathbf{e} = \mathbf{d}$
- to R4
- Verification scale interval
- d Readability | scale interval

On standard balances, only Max and d are displayed.

#### Bar Graph:

The bar graph indicates how much of the balance's capacity is "used up" by the current load; during checkweighing, it indicates the control limits.

# Bar Graph:

The bar graph indicates how much of the balance's capacity is "used up" by the current load; during checkweighing, it indicates the control limits.

The following symbols may be displayed:

- 0% Lower load limit
- 100% Upper load limit
- Bar graph showing 10% intervals
- Minimum for checkweighing
- = Target for checkweighing
- + Maximum for checkweighing

Plus/Minus Sign, Stability Symbol: A plus or minus sign (+ or –) is shown here for a weight (or a calculated value, such as that for counting), or the **O** symbol indicating that a verified balance<sup>1</sup>) has been zeroed or tared.

Line for Measured Values: This area shows the weighed or calculated value and the alphanumeric input.

Note Concerning Verified Balances Approved for Use as Legal Measuring Instruments in the EU\*: For verified balances that have a verification scale interval e which is greater than the scale interval d, the last digit on the display is bordered.

# Unit and Stability:

When the balance reaches stability, the weight unit or calculated unit is displayed here.

When the  $\triangle$  symbol is displayed here, the value indicated in the readout cannot be used in legal metrology.

- \* including the Signatories of the Agreement on the European Economic Area
- Verification scale interval "e" is equal to scale interval "d"

Tare Memory, Calculated Values: The symbols displayed here indicate when there is a value in one of the tare memories or when the value shown is a result of calculation rather than direct measurement.

These symbols are as follows:

- ▲ Calculated value
- **NET1** Net value | tare memory
- NET2 used by an application program (e.g., formulation, second tare memory)

Application Pictograms: The pictograms displayed here indicate the application(s) selected. The pictogram is displayed inversely (white on a black background) when the corresponding application is active.

For example, the following symbols may be displayed simultaneously:

- . The counting application is active
- ☆ Checkweighing is also active
- Data record

Text Line:

Additional information is displayed here (e.g., operator guidance prompts, name of the active program, etc.)

# Soft Key Labels:

The current functions of the soft keys above the function keys (arrow keys) are indicated here; during calibration | adjustment, this line shows up- and down-arrows ( $\land$  and  $\lor$ ) for selecting calibration and adjustment functions.

# Display for Menu Parameter Settings (Setup)

This display is divided into three sections.

Line for Operating State

Soft Key Labels

Status Line:


The status line of shows the function of the display screen page. In the Setup menu, the current menu "path" is shown here.

Setup Menu Example: "Balance/scale functions":

SETUP BAL.FUNC.

Input and Output Window This window contains either detailed information (e.g., on the active application) or a pick list. A selected item is displayed inversely (white characters on a black background). You can also enter information in an active field in this window using the alphabetic and numeric keys.

Setup Menu Example, "Device parameters, Adapt filter":



The following symbol may be displayed in the input and output window:

• this symbol marks the saved menu setting

Soft Key Labels See the description "Function Keys (Soft Keys)" on the previous page To set a parameter:

- Press the 
   or 
   v soft key repeatedly until the desired setting is selected (displayed inversely)
- Confirm your selection: press the + soft key

To change the numeric value of a parameter:

- Press the 
   or 
   v soft key repeatedly, if necessary, until the desired setting is selected (displayed inversely)
- Enter a new value or character: use the 0 1 ... 9 • keys or the ABC key and enter the desired letters
- Confirm your selection: press the + soft key

To exit Setup: press the < < soft key

# Input

**Bar Code Scanner or Keyboard Input** You can use a bar code scanner or an external keyboard to input alphanumeric values. These inputs are processed in the same manner as keypad inputs on the display and control unit of the bal-

ance. Bar code and keyboard inputs are only displayed; they cannot activate any function.

To assign a bar code scanner or keyboard input to a function, press one of the following soft keys:

- Lot
- Samples
- Measured values
- Sample number
- Tare value
- Initial weight
- Backweighed value
- Sample ID

# Foot or Hand Switch Input

You can connect a foot switch or a hand switch to the balance to have this device perform a keypad function (such as  $\bigcirc$ F or  $\bigcirc$ Tarc).

# PC Input

You can use a computer to control the functions of the weighing cell and display and control unit via the communications port (see the "Data Output Function" section in the chapter entitled "Operation").

# **Data Output**

Your LA Reference balance is equipped with an interface port for connecting your choice of the following:

- Printer
- Peripheral device (e.g., computer)
- Universal remote control switch

# Printer

You can configure the print functions to meet your individual requirements by selecting the corresponding menu code.

You can have printouts generated automatically, or by pressing  $(\overline{a})$ ; dependent on or independent of the stability or time parameters; with or without IDs; and as standard or ISO/GLP-compliant printouts.

ISO: International Organization for Standardization

GLP: Good Laboratory Practice

See the section on "Data Output Functions" in the chapter entitled "Operation" for a detailed description of data output options.

# **Interface Port**

Instead of a printer, you may choose to connect a different peripheral device, e.g. a computer (PC). With an on-line PC you can control both the weighing cell and the display unit of the LA Reference balance.

Request messages are sent via the interface to initiate functions in the weighing cell and in the display unit. Some of the functions generate response messages.

See the chapter entitled "Operation" under the section on "Data Output" for a detailed description of the interface port.

# **Error Codes**

If you press a key that has no function, or which is blocked at a certain point in an application program, this error is indicated as follows:

- a double-beep is sounded as an acoustic signal if the key has no function
- a double-beep is sounded and a message is displayed for 2 seconds in the text line if the key function is not available at that time

The response to an operator error is identical in all models of the LA Reference series. See the chapter entitled "Error Codes" for a detailed description.

# **Storing Settings**

# **Storing Parameter Settings**

The settings configured are stored in the balance's non-volatile memory. The most recent parameter settings are active when you switch on the balance.

# Saving Parameter Settings

You can assign passwords in order to block access to:

- Weighing parameters
- Device parameters
- Application parameters
- Factory settings

# **Getting Started**

# Storage and Shipping Conditions

 Do not expose the balance to extreme temperatures, jolts, impacts, vibration or moisture.

# **Unpacking the Balance**

- After unpacking the balance, check it immediately for any visible damage as a result of rough handling during shipment.
- If this is the case, proceed as directed in the chapter entitled "Care and Maintenance," under the section on "Safety Inspection."

It is a good idea to save the box and all parts of the packaging until you have successfully installed your balance. Only the original packaging provides the best protection for shipment. Before packing your balance, unplug all connected cables to prevent damage.

Important Note Concerning Verified Balances Approved for Use as Legal Measuring Instruments in the EU\*: Provided that an official seal is required for the verified balance, a control seal is affixed to the balance. This seal will be irreparably damaged if you attempt remove it. If the seal is broken, the validity of the verification will become void and you must have your balance re-verified.

# **Equipment Supplied**

The equipment supplied includes the components listed below:

# LA balances with a readability of 0.1 mg

- Balance with display and control unit
- AC adapter
- Dust cover
- Bushing
- Shield plate
- Shield disk
- Weighing pan
- USB interface cable

# LA balances with a readability of 1 mg

- Balance with display and control unit
- AC adapter
- Dust cover
- Shield disk
- Pan support
- Weighing pan
- Glass draft shield cylinder
- Draft shield cover
- USB interface cable

### LA8200S, LA8200P, LA 6200S, LA 4200S, LA 2200S, LA 820, LA 420, LA 2200P, LA 5200P

- Balance with display and control unitAC adapter
- Dust cover
- Pan draft shield
- Weighing pan
- USB interface cable

## LA 12000S, LA 6200, LA 4200, LA 2200, LA 12000P

- Balance with display and control unit
- AC adapter
- Dust cover
- Weighing pan
- USB interface cable

# LA balances with a capacity $\ge 16$ kg

- Balance with display and control unit
- AC adapter
- Dust cover
- Weighing pan
- Dust cover for the display and control unit
- USB interface cable

# Installation Instructions

When choosing a location to set up your balance, observe the following so that you will be able to work with added speed and accuracy:

- Avoid placing the balance in close proximity to a heater or otherwise exposing the balance to heat or direct sunlight
- Protect the balance from drafts hat come from open windows or doors
- Do not expose the balance to extreme moisture over long periods
- Avoid exposing the balance to extreme vibrations during weighing
- Set up the balance on a stable, even surface
- Protect the balance from aggressive chemical vapors

# **Conditioning the Balance**

Moisture in the air can condense on the surfaces of a cold balance whenever it is brought into a substantially warmer place. If you transfer the balance to a warmer area, make sure to condition it for about 2 hours at room temperature, leaving it unplugged from AC power.

 including the Signatories of the Agreement on the European Economic Area

# Setting up the Balance


- Preparing Balances with Analytical Draft Shield Chambers
- Place the components listed below on the balance in the order given:
- Bushing (pan adapter)
- Shield plate
- Shield disk
- Weighing pan


# Preparing Balances with a Round Glass Draft Shield


- Place the components listed below on the balance in the order given:
- Dust cover
- Protective disk; turn counter-clockwise until it stops and is secure
- Pan support
- Weighing pan
- Glass draft shield cylinder
- Draft shield cover


- Preparing Balances with a Rectangular Weighing Pan and a Weighing Capacity ≤ 12 kg
   Place the components listed below on the balance in the order given:
- Dust cover
- Weighing pan draft shield (only for balances with a readability of 0.01 g)
- Weighing pan

Preparing Balances with a Rectangular Weighing Pan and a Weighing Capacity ≥ 16 kg
Place the weighing pan on the balance










# Separate Operation of the Display Unit

- Turn the balance on its side and lay it on a padded surface to avoid damage to the weighing system
- Use a screwdriver to remove the 2 screws from the display unit retainer
- Remove the display unit
- > Cable lengths
  - LA balances with a weighing capacity  $\leq$  12 kg: 55 cm
  - LA balances with a weighing capacity > 12 kg: 80 cm
- $\bigcirc$  See the chapter entitled "Accessories" for information on longer cables
- $\bigcirc$  If you wish to use a longer cable, it must be installed by an authorized Sartorius service technician


# Options for Mounting the Display Unit for LA Balances with a Weighing Capacity $\geq\!16~kg$

The display unit can be mounted as follows:

- on the short side of the weighing cell (factory mounting)
- on the back (long side) of the of the weighing cell
- Turn the weighing cell over
- Remove the fastening screws from the display unit retainer
- Remove the fastening screws from the plate that covers the cable raceway (channel) and remove the plate



• Thread the cable through the raceway and replace the cover plate



9

# Connecting the Balance to AC Power

- Check the voltage rating and the plug design
- If they do not match the rating or standard you use, contact your Sartorius office or dealer Use only
  - Original Sartorius AC adapters
- AC adapters with a registered approval rating from a national testing laboratory
- $\bigcirc$  To use a main feeder cable from the ceiling or to mount a CEE plug, you will have to make arrangements
- See the chapter entitled "Accessories" for information on using an IP65-protected industrial AC adapter or an external rechargeable battery pack with your balance
- Insert the right-angle plug into the jack and then tighten the screws
- Then insert the plug of the AC adapter into a wall outlet (mains)

# Charging the Rechargeable Battery for Saving Data:

All data is saved in the battery-backed memory. When initially operating the balance, leave it connected to AC power for one day to charge the battery. When the balance is disconnected from AC power, the balance-generated data will remain stored for approximately three months. In the standby mode, data is retained in the memory via the power supply. Be sure to print out data before storing your balance for a relatively long period.

## **Safety Precautions**

The AC adapter rated to Class 2 can be plugged into any wall outlet without requiring any additional safety precautions. The ground or earth terminal is connected to the balance housing, which can be additionally grounded, if required. The data interface is also electrically connected to the balance housing (ground).

#### Note:

This equipment has been tested and found to comply with the limits pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with these instructions, may cause harmful interference to radio communications.

For information on the specific limits and class of this equipment, please refer to the Declaration of Conformity. Depending on the particular class, you are either required or requested to correct the interference.

If you have a Class A digital device, you need to comply with the FCC statement as follows: "Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense." If you have a Class B digital device, please read and follow the FCC information given below: However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.
   Before you operate this equipment, check which FCC class (Class A or Class B) it has according to the Declaration of Conformity included. Be sure to observe the information of this Declaration.


#### **Connecting Electronic Peripheral Devices**


• Make absolutely sure to unplug the balance from AC power before you connect or disconnect a peripheral device (printer or PC) to or from the interface port.


## Warmup Time

To ensure accurate results, the balance must warm up for at least 30 minutes the first time it has been connected to AC power and each time after it has been unplugged from AC power and reconnected. Only after this time will the instrument have reached the required operating temperature.

- Using Verified Balances Approved for Use as Legal Measuring Instruments in the EU\*:
  The balance must warm up for at least 24 hours after initial connection to AC power or
- after a relatively long power outage. It needs to warm up for at least 30 minutes each time after it has been disconnected from AC power.
- $\bigcirc$  For balances with a readability of  $\le 0.1$  mg: wait until the automatic calibration/ adjustment routine has ended. Requirements: see page 47







**Fastening an Antitheft Locking Device: Balances with a Weighing Capacity**  $\leq$  **12 kg** To fasten an antitheft locking device, use the lug located on the rear panel of the balance.

• Secure the balance at the place of installation, e.g., with a chain or a lock.

# Leveling the Balance


Purpose:

- To compensate for unevenness at the place of installation
- To achieve perfectly horizontal positioning of the balance for consistent reproducibility

Always level the balance again any time it is moved

**Leveling Balances with a Weighing Capacity**  $\leq$  **12 kg** Only the 2 front feet are used for leveling.

- Retract the 2 rear feet (only for models with rectangular weighing pan)
- Turn the 2 front feet as shown in the illustration until the air bubble is centered within the circle of the level indicator
- > Several leveling steps are usually required.
- When weighing heavy samples (or when the YDH 01 LP display arm is attached): Extend the 2 rear feet until they touch the surface on which the balance rests



# Leveling Balances with a Weighing Capacity ≥ 16 kg


• Adjust the four leveling feet until the air bubble is centered within the circle of the level indicator

#### Setting the Language

> See the "Setting the Language" section in the chapter entitled "Configuration"

# Setting the Date and Time

> See the "Entering Date and Time" section in the chapter entitled "Configuration"



# Configuration

# Purpose

You can configure the balance to meet individual requirements by entering user data and setting parameters in the Setup program.

The Setup menu contains the following submenus:

- Balance functions
- Device parameters \_
- Application parameters
- Printout functions
- Device information
- Language \_
- Factory settings \_

# Setting the Language


You can choose from 5 languages for the information display:

- German
- \_
- English (factory setting) English with U.S. date | time format
- French \_
- Italian \_
- \_ Spanish

# Configuring the Balance for Use in Legal Metrology

Set the menu access switch as described below to configure the following functions for use of the balance in legal metrology:

- Display: Verification scale interval: ∈; lower limit of the weighing capacity: Min
- External calibration blocked \_
- Preparation:
- Remove the cap from the back of the balance housing
- Move the switch (1) upwards



When the switch is in the upper posi-> tion, the Setup menu is locked and the balance can be used in legal metrology

When the switch is in the lower position, the menu is accessible

> Note: Do not move Switch 2

# Example: Setting the Language to "U.S. Mode"

Step	Press key (or follow instructions)	Display/Output
1. Select "Setup" menu	Setup	SETUP Balance/scale functions Device parameters Application parameters Printout Info << v >
2. Select "Language" and confirm	Repeatedly press v soft key, then > soft key	SETUP LANGUAGE Deutsch oEnglish U.SMode Frangais Italiano <<
3. Select "U.S. mode"	v soft key	SETUP SPRACHE Dleutsch English U.SMode Frangais Italiano <<
4. Save language	J soft key	SETUP LANGUAGE Deutsch OEnglish U.SMode Français Italiano << ^ v J
5. Exit the Setup menu	< < soft key	Max 62009 d= 0.019 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0

Navigating in the Setup Menu (Examples): Example: Adapting the balance to "Extreme vibration"

Step	Press key(s) (or follow instructions)	Display/Output
1. Select Setup menu	(Setup)	SETUP Balance/scale functions Device parameters Application parameters Printout Info << v >
2. Confirm "Balance/scale functions"	> soft key	SETUP BAL.FUNC. Calibration/adjustment Adapt filter Application filter Stability range Taring << < v >
3. Select menu item "Adapt filter" and confirm	∨, then > soft key	SETUP     BAL.FUNC.     ADAPT FILT.       Minimum vibration     Normal vibration       Strong vibration     Extreme vibration       <
4. Select menu item "Extreme vibration"	∨ soft key	SETUP     BAL.FUNC.     ADAPT FILT.       Minimum vibration     oNormal vibration       Strong vibration     Extreme vibration       <
5. Confirm menu item "Extreme vibration"	₽ soft key	SETUP     BAL.FUNC.     ADAPT FILT.       Minimum vibration     Normal vibration       Strong vibration       oExtreme vibration       <
6. If required, select further menu items	< ♥ ∩ > soft keys	
7. Save setting and exit Setup Menu	< < soft key	

# Example: Entering date and time

Step	Press key(s) (or follow instructions)	Display/Output
<ol> <li>Select Setup menu; select "Device parameters"</li> </ol>	(Setup), then ♀ soft key and > soft key	SETUP DEVICE Password User ID Clock Interfaces Display << <
2. Set clock	press ♥ repeatedly, then press >	SETUP DEVICE CLOCK Time: 15.06.10 Date: 12.09.97
3. Enter the time	$ \begin{array}{c} 1 \\ 1 \\ \hline 0 \\ \hline 3 \\ 0 \end{array} $	<         <            SETUP         DEVICE         CLOCK           Time:         11.12.30           Date:         12.09.97
<ol> <li>Set the time according to your local clock</li> </ol>	ہ soft key	ESC         J           SETUP         DEVICE         CLOCK           Time:         11.12.42           Date:         13.03.00
5. Enter the date	$ \begin{array}{c} 1 \\ 3 \\ \hline 3 \\ 0 \end{array} $	
6. Store the date	₊J soft key	
7. Enter other data, if desired	< ∨ ∧ > soft keys	
8. Exit Setup menu	< < soft key	

# Configuration

# Setting the Balance Functions (BAL.FUNC.)

# Purpose

This menu item enables you to configure the balance functions, i.e., to meet individual requirements by selecting predefined parameters in the Setup menu. You can block access to the menu by assigning a password.

## Features

The balance functions are combined in the following groups (1st menu level):

- Calibration/adjustment
- Adapt filter
- Application filter
- Stability range
- Taring
- Auto zero
- Weight unit 1
- Tare/zero at power on
- Factory settings: only wah.
   param. (only the balance functions)

#### **Factory Settings**

Parameters: The factory settings are identified by the symbol "o" in the list starting on the next page.

# Preparation

Show available balance functions:

- Select Setup menu: press the (Setup) key
- > SETUP is displayed

SETUP	APPLICAT	TION
Application		> Toggle wt.units
Application		Counting
Application		Percent weigh.
Extra func.		Animal weish.
Extra func.	(F5)	Calc., density
< Menu		

 Select "Balance/scale functions": press the > soft key

If you already assigned a password:

- > The password prompt is displayed
- If access is blocked by a password: enter the password using the numeric/alphabetic keys.
- $\bigcirc$  If the last character of the password is a letter: conclude input by pressing  $\bigcirc$  ABC
- Confirm your password and have the balance functions displayed: Press the J soft key.
- > Balance functions are displayed:

SETUP BAL.FUNC.							
Calibration/adjustment							
Adapt filter							
Application filter							
Stability range							
Taring							
11		6		14	2		

- To select the next group: press the ♥ soft key (down arrow)
- To select the next sub-item within a group: press the ⇒ soft key (right arrow)
- To select the previous group: press the soft key (left arrow)
- $\bigcirc$  To confirm: press the  $\downarrow$  soft key

# **Extra Functions**

- Exit the Setup menu: press the < < soft key
- > Restart your application
- Print parameter settings:
- When the balance functions are displayed, press 📳
- Printout (example) Texts with more than 20 characters are cut off

# SETUP


BAL.FUNC. Calibration/adjustm CAL/iso TST key fun Internal cal./adju Cal/adjustm seq Cal. with adjustm au isoCAL-function 0ff Start autom. adjus isoCAL Print GLP/GMP adju Automatic if GLP is selected Parameter for exte Wt. ID (W ID): Cal./adjust.-wt: 5000.00 g Adapt filter Normal vibration Application filter Filling mode Stability range 2 digits Taring After stability Auto zero 0ff Weight unit 1 Grams /g

etc.

## **Balance Functions (Overview)**


o factory setting

 $\sqrt{}$  user-defined setting(s)



\* = not applicable to verified balances

\*\* = only external calibration is possible for verified balances



\* = not applicable to verified balances

# Setting the Device Parameters (DEVICE)

# Purpose

This menu item enables you to configure the balance to meet individual requirements by selecting predefined menu parameters in the Setup menu. You can block access to the menu by assigning a password.

#### Features

The device parameters are combined in the following groups (1st menu level):

- Password
- User ID
- Clock
- Interfaces
- Display
- Keys
- Extra functions
- Factory settings: only device parameters

#### **Factory Settings**

Parameters: The factory settings are identified by the symbol "o" in the list starting on the page after next.

# Preparation

Display available device parameters

- Select the Setup menu: press Setup
- > SETUP is displayed:

SETUP Balance/scale functions							
Device parameters Application parameters							
Printout Info							
< <				V	>		

 Select "Device parameters": use the V and > soft keys

If no password has been assigned, anyone can access the Setup menu device parameters

If a password has already been assigned: The password prompt is displayed

- > The password prompt is displayed
- If access is blocked by a password: enter the password using the numeric and/or alphabetic keys
- If the last character of the password is a letter: conclude input by pressing the (ABC) key
- Press ↓ to confirm the password
- > Device parameters are now displayed:

SETUP	DEVICE		
Password			
User ID Clock			
Interfaces			
Display			
< <	<	~	>

- To select the next group: press the ♥ soft key (down arrow)
- To select the next sub-item within a group: press the ⇒ soft key (right arrow)
- To select the previous group: press the
   soft key (left arrow)
- Press ↓ soft key to confirm the selected menu item

#### **Entering or Changing a Password**

- Let's assume that a password with 8 characters max. has already been assigned to access the Setup device parameters
- Select the Setup menu: press
- > SETUP is displayed
- Select parameters: Use the V and Soft keys
- > The password prompt is displayed:

SETUP		PRINTO	UT		
		define			
		itput o			value
Output to interface ports					
Line format					
ISO/GLP/GMP printout					
100, 01					

- $\bigcirc$  Enter the password
- Press the J soft key to confirm your password and view the device parameters
- Write down your password here for easy reference:
   Password = .....
   If you assign a password and then forget what the word is:
- Enter the General Password (see Appendix)
- Press the +J soft key to confirm and display the password
- > The parameters are displayed
- Select the device parameter "Password": If necessary, repeatedly press ∨ or ∧ , until you see
- > Password: and any existing password

SETUP		PRINTO		APPLIC	ATION			
	Stability parameter							
Print on request then tare Auto print upon initalization Configured printout								
		C		v	>			

- To confirm: press the + soft key
- Exit the Setup menu: press the < < soft key</li>


> Restart the application

## **Extra Functions**

- Exit the Setup menu: press the << soft key
- > Restart the application
- Print the parameter settings:
   If the device parameters are displayed: press
- > Printout (example)

SETUP DEVICE \_\_\_\_\_ User ID User ID: Interfaces Serial communicati SBI Baud rate 1200 baud Number of data b 7 data bits Parity 0 d d Number of stop b 1 stop bit Handshake-mode Hardware handshake after 1 char Function external Print key Function control 0utput Display Contrast 2 Background White Digit size 10mm + bar graph +text display Application symbo 0 n Keys CF function in ap Clear all applicati CF function for i Delete last charact Block key functio All keys unblocke


etc.



For the display, keys and extra functions, see next pages

<sup>1</sup>) not if "None" is selected for parity<sup>2</sup>) only if 7 data bits selected

<sup>3</sup>) only if 8 data bits selected



# Setting the Application Parameters (Application)

# Purpose

This menu item enables you to configure the balance, i.e., adapt the balance to your individual requirements by selecting from a list of parameter options in a menu. You can block access to this menu by assigning a password.

### Features

The simple weighing function is available at all times. You can select one from each of the following application groups. This means a number of combinations are possible.

Application 1 (basic settings)

- Toggle weight units
- Counting
- Weighing in percent
- Animal weighing
- (averaging)
- Calculation
- Recalculation
- Density determination
- Differential weighing
- Air buoyancy correction and air density determination
- Diameter determination
- Application 2 (control functions) Checkweighing
- Time-controlled functions

Application 3 (data records)

- Totalizing
- Formulation \_
- Statistics

In addition, you can assign 2 extra functions to each of the soft keys, in some cases (depending on the Setup configuration):

- Second tare memory
- Identification codes
- Manual storage in app. 3 memory (M+ key)
- Product data memory
- SOmin function\*
- DKD uncertainty of measurement\*

Auto-start application when the balance is switched on

Factory settings: only application parameters

# **Factory Settings for the Parameters**

The factory settings are identified by the symbol "o" in the list starting on page 23.

# Preparation

Display available application parameters:

- Select the Setup menu: press the Setup key
- SETUP is displayed



Select parameters: repeatedly press the ∨ and ≥ soft keys

If you have already assigned a password:

- > The password prompt is displayed:
- $\bigcirc$  If access is blocked by a password: enter the password using the numeric/alphabetic keys
- $\bigcirc$  If the last character of the password is a letter: conclude input by pressing (ABC)
- Confirm your password and have the application parameters displayed: press the J soft key
- The application menu is displayed: APPLICATION

SETUP

Applicatio	n 1 (bas	ic set	tings)	
Applicatio				ns)
Applicatio			rds)	
Extra func				
Extra func	<u>tion (Fa</u>	)/		
	C		U	2

- $\bigcirc$  To select the next group: press the v soft key (down arrow)
- $\bigcirc$  To select the previous item of a group: press the  $\land$  soft key (up arrow)
- $\bigcirc$  To select the next sub-item within a group: press the  $\Rightarrow$  soft key (right arrow)
- $\bigcirc$  To select the previous group: press the < soft key (left arrow)
- $\bigcirc$  To confirm: press the  $\downarrow$  soft key

# **Extra Functions**

- Exit the Setup menu: press the << soft key
- > Restart your application
- Print parameter settings:
- When the balance/scale functions are displayed, press 🖉
- > Printout (example) Texts with more than 20 characters are truncated


# SETUP


SEIUP	
Applicatio	n
Application 1	(basi
	0 f f
Application 2	(cont
	0 f f
Application 3	• · ·
	0ff
	• • •
Extra function	
	0 f f
Extra function	(F5)
	0 f f
Auto-start app	. whe
hate start app	0 f f
	011

\* must be activated by service technician


# **Application Parameters (Overview)**

o factory settings  $\sqrt{}$  user-defined setting(s)







\* = How to run this application is described in detail in our Factory "FC...." Installation and Operating Instructions. Request your copy directly from Sartorius or download it from the Internet (www.sartorius.com; see "download")




\* = Setting can only be changed when the program is initially run and when the  $\mu a$ . Sea. key option is set to "No"




\* = How to run this application is described in detail in our Genius "ME" Installation and Operating Instructions. Request your copy directly from Sartorius or download it from the Internet (www.sartorius.com; see "download")





- Extra Functions - for other extra functions, see next page



# Selecting the Printout Function (PRINTOUT)

# Purpose

This menu item enables you to configure the printout to meet your individual requirements by selecting predefined menu parameters in the Setup menu. Printouts of weights and other measured or calculated values and IDs enable you to document your data. You can select the particular data you wish to print. To prevent changes to your settings, you can block access to the menu by assigning a password.

## Features

The device parameters are combined in the following groups (1st menu level):

- Application-defined output
  - Configured printout
  - FlexPrint
- Automatic output of displayed values
- Output to interface port
- Line format
- ISO/GLP/GMP printout
- Identification (identifier)
- Factory settings printout only

#### **Factory Settings**

Parameters: The factory settings are identified by the symbol "o" in the list on the next page.

# Preparation

Display available printout parameters

- Select the Setup menu: press Setup
- > SETUP is displayed:

SETUP								
	Balance/scale functions							
	Device parameters							
	Application parameters							
Printe	Printout							
Into								
< <				V V	>			

● Select "Printout": use the ∨ and ≥ soft keys

If no password has been assigned, anyone can access the printout parameters in the Setup menu

If a password has already been assigned:

- > The password prompt is displayed
- If access is blocked by a password: enter the password using the numeric and/or alphabetic keys
- If the last character of the password is a letter: conclude input by pressing the (ABC) key
- $\bullet$  Press  $\downarrow$  to confirm the password
- > Printout parameters are now displayed:

SETUP		PRINTOU			
		defined			
Automat	tic ou	tput of	disp	laved	value
Output	to in	terface	port	S	
Line fo					
ISO∕GLF	P/GMP	printou	t		

- To select the next group: press the ♥ soft key (down arrow)
- To select the previous item of a group: press the soft key (up arrow)
- To select the next sub-item within a group: press the > soft key (right arrow)
- To select the previous group: press the
   soft key (left arrow)
- $\bigcirc$  To confirm: press the  $\downarrow$  soft key

## **Extra Functions**

- Exit the Setup menu: press the < < soft key
- > Restart your application
- Print parameter settings:
   When the printout parameters are displayed, press <a>[7]</a>
- > Printout (Example)

SETUP PRINTOUT Application defined Stability paramete With Stability Print on request t 0 f f Auto print upon in All values Configured printou Indiv.: Printout Comp.: Printout Total: Printout FlexPrint 0 f f Automatic Output of Stability paramet Without stabili Stop auto print Not possible Time-dependent aut 1 display update Output to interface Serial communicat: Application-defined output Line format For other apps/GLP (22 characters) ISO/GLP/GMP printou 0 f f Identification Lot (L ID): ID1: ID1


etc.

# Configuration

# **Printout Parameters (Overview)**

o factory setting

 $\sqrt{\text{user-defined setting}}$ 



- 1) = when the balance is used in legal metrology, this setting may be configured for control purposes only; printout of values is not permitted
- $^{2}$ ) = Autoprint when load change is >10 d and stability is reached: no printout until residual difference in load value >5 d
- <sup>3</sup>) = to enable automatic output of the displayed value, the corresponding option ("Automatic output of displayed value" must be activated here, under "Stability parameter"
- <sup>4</sup>) = These settings may not be changed on verified balances

# **Printout Configuration**

# Purpose

This menu item enables you to configure individual printout formats. With the formulation, totalizing and statistics application, you can also define the values to be included on the total printout when the MR key is pressed.

Under "Setup > Printout > Applicationdefined output > Configured printout", you can configure individual, component or total data records that contain the items in each application that are available for printouts. Configure these printouts after you have configured the applications, because some entries in the data record depend on the particular application.

#### Features

- Maximum items in a data record: 60
- Separate configuration of printout formats for individual weights, components, total, backweighing and statistics

Automatic printout of application data: e.g., results from animal weighing or density application (Setup menu: Application 1: Density: Printout: All data) OK values from checkweighing application, time-controlled printouts, 2nd tare memory

- Component printout: For results from totalizing, formulation or statistics applications, press
   M+ or M- (Setup: Application 3: ..., Printout of individual components: On)
- Total printout: For totalizing, formulation or statistics applications, press MR
- Backweighing printouts or records: automatically generated after backweighing or manually by pressing the
   key when the result is displayed at the end of backweighing
- Statistics printout or output:
   To generate, press the <a></a>
   key when the statistics are displayed

Printouts for Differential Weighing: These printouts can be generated as standard or configured (user-defined) reports.

You can configure the following printouts:

- Individual printout
- Backweighing printout
- Statistics printouts

Printouts are generated in one of two ways:

- at the request of the user by pressing the (a) key (print on request)
- automatically, if configured in the Setup menu [Application parameters: Application 1: Differential weighing: Generate printout: Auto]

You can turn off automatic printout generation in the Setup menu [Application parameters: Application 1: Differential weighing: Generate printout: None]

- Data records are deleted after you haved switched to a different application or activated or de-activated an extra function in the application parameters of the Setup menu
- A new pick list for a data record is created based on the currently active application programs and extra functions
- Printout items can be deleted individually
- No printout is generated when the following setting is configured: Setup: Printout: Line format: For raw data (16 characters)
- Print item "Form feed" for footer: Advance to beginning of next label in the "YDP01IS-Label" and "YDP02IS-Label" [printer] interface mode
- Extra Functions
- Exit printout configuration: press < < soft key</p>
- > Restart application

Printing "Select" and "List" Settings

- LIST: print the currently selected list
   SELECT: printout items that can still be selected
- When the select bar is on LIST or SELECT: press the <a>key</a>
- > Printout (Example)

# Example:

Configure an Individual Printout for Counting Application to Include Dotted Line, Date/Time, Piece Count and Net Weight

Settings (changes in the factory settings required for this example): Setup: Application parameters: Application 1: Counting Exit the Setup menu: press the < < soft key Then call Setup again: Printout: Application-defined output: Configured printout

Step	Press key(s) (or follow instructions)	Display/Output
1. Select Setup menu, then "Printout"	(Setup), then ✓ repeatedly and > soft key	SETUP PRINTOUT Replication-defined output Automatic output of displayed value Output to interface ports Line format ISO/GLP/GMP printout << < v >>
<ol> <li>Confirm "Application-defined output"</li> </ol>	> soft key	SETUPPRINTOUTAPPLICATIONStabilityparameterPrinton request then tareAutoprintuponinitalizationConfiguredprintout<
<ol> <li>Select and confirm "Configured printout"</li> </ol>	↓ soft key 3x and > soft key	PRINTOUT APPLICATION CONFIG Indiv.: Printout f. app./weishins << < < >>
4. Confirm "Indiv. printout"	> soft key	LIST INDIU.PRT SELECTION Blank line Form feed Date/time C< Delete
5. Select "Blank line"	>, ∨, ↓ soft keys	LIST INDIV.PRT SELECTION Blank line Form feed Istevtime CC C C A V J
6. Select "Date/time"	♀ soft key twice, then ┙ soft key	LIST INDIV.PRT SELECTION  Date/time Blank line Form feed Imme GLP header << < < < ^ v J
7. Select "Piece count"	♀ soft key repeatedly, then ↓ soft key	LIST INDIV.PRT SELECTION Net (N) Date/time Gross (G#) Piece count Ref.quantity Ref.quantity Tanget << < < < < < < v J
8. Select "Net (N)"	☆ soft key repeatedly, then ↓ soft key	LIST INDIV.PRT SELECTION ID1 Date/time ID2 Piece count ID3 Net (N) ID4 GPoss (G#) << < < ^ y J
9. Exit "Printout" configuration	< < soft key	
10. Perform weighing operations, then print	Ē	14.01.2000 09:19 Qnt + 598 pcs N + 2003.13 g

# **Device Information**

## Purpose

This menu item enables you to have information displayed about the specific balance ("device"), as well as "FlexPrint" information.

# **Displaying Device Information**

- Select the Setup menu: press the Setup key
- > "SETUP" is displayed:

ACT

ISETUP								
Balance/scale functions								
Device								
Application parameters								
Printout								
Info								
< C C				<b>V</b>	>			

- Select "Info": Repeatedly press the ♥ soft key, then press the > soft key
- > Device information is displayed:

SETUP INFO	
Version no.:	01-35-18
Bal. ver. no.:	00-20-12
Model:	LA5200P
Serial no.:	70906913

• Print device information: Press the  $(\overline{a})$  key

> Printout (Example)

```
23.02.2000
                  13:02
Model
                LA5200P
               91205355
Ser. no.
Vers. no.
              01-35-18
(Version of the operating program)
ΙD
             BECKER123
(User-ID)
               _____
SETUP
          INFO
               DEVICE
 Version-no.:
              01-35-18
 (Version of the operating program)
 Wgh. sys. vers:
              00-20-12
 (Version no. of the weighing cell)
 Model:
                LA5200P
 Serial no.:
               91205355
Next mainten.:
            01.01.2004
Service phone:
           00495513080
SQmin:
             100.00 g
```

- Return to SETUP overview: press the < soft key
- Exit Setup menu: press the Soft key
- > Original settings are restored

## **Factory Settings**

Each parameter category has a factory setting. In the Setup menu, you can restore all factory settings by confirming the selection YES.

The following settings are not restored:

- Language
- Password
- Display contrast Time (clock)

# **Display Flexprint Information**

- Select the Setup menu: press the Setup key
- > "SETUP" is displayed:

SETUP							
Balance/scale functions							
Device parameters							
Application parameters							
Printout							
Info							
< <				V	>		

• Select "Info": press the 😺 soft key repeatedly and then the > soft key

SETUP		INFO	 	
Devic. FlexI	≥ infor	mation		
FIEXI	110			
		-		

- Select "FlexInfo": press the V soft key and then the > soft key
- > The FlexPrint information is displayed, with print instruction file name, software ID and version number:

- $\bigcirc$  To select a particular print file name with software ID (for example, ID403), if desired: press key ♥ or ∩ as required
- > If the display shows **ID**---: The weight block for legal metrology is not printed by this print file.
- > Display of version number: V.xx.xx.xx Created by Sartorius: V.S.xx.xx.xx
- Return to SETUP overview: press the < soft key
- Exit Setup menu: press the << soft key
- > The device returns to the previous mode

# Operation

# **Basic Weighing Function**

## Purpose

The basic weighing function is always accessible and can be used alone or in combination with an application program (Toggle between Weight Units, Counting, Weighing in Percent, etc.).

- Features
   Taring the balance
- Assigning IDs to weights
- Printing weights
- Printing ID codes for weights

Factory Settings Tare: After stability

Manual/auto print mode: Manual with stability

Line format: For other apps/GLP (22 characters)

# **Soft Key Functions**

Cal Initiate calibration/ adjustment routine


- **isoCAL** Press to start isoCAL routine
- **S I D** Store ID entered

# **Below-Balance Weighing**


A port for a below-balance weighing hanger is located on the bottom of the balance.

Balances with a capacity  $\leq 12$  kg:

• Open cover plate (1) on the bottom of the balance




• Attach the sample (e.g., using a suspension wire) to the hook (2).



 If necessary, install a shield for protection against drafts

Balances with a weighing capacity  $\ge 16 \text{ kg:}$ 

• Use a screwdriver to open the cover plate on the bottom of the balance



- Attach the hook ordered directly from Sartorius
- If necessary, install a shield for protection against drafts

Important Note Concerning Verified Balances Approved for Use as Legal Measuring Instruments in the EU\*: The below-balance weighing port may not be opened or used when an approved balance is being operated as a legal measuring instrument.

## Preparation

- Turn on the balance: Press 🕡
- > The Sartorius logo is displayed
- If it is time for the next maintenance, the following appears:

NEXT M Date: Servic	AINTEN e phon		01.0 00495	1.2005
Service phone.				

To exit this screen: press the  $\leq \leq$  soft key

- Call your nearest Sartorius Service Center to schedule a maintenance appointment
- $\bigcirc$  To tare the balance, if desired: Press  $\textcircled{\sc{Tare}}$
- > The O symbol is displayed when a verified balance is tared or zeroed (± 0.25 digits).

Important Note Concerning Verified Balances Approved for Use as Legal Measuring Instruments in the EU\*: The type-approval certificate for verification applies only to non-automatic weighing instruments; for automatic operation with or without auxiliary measuring devices, you must comply with the regulations of your country applicable to the place of installation of your balance.

 The temperature range indicated on the verification ID label must not be exceeded during operation

Example: MD BF 100 ① 0...+40 °C

 including the Signatories of the Agreement on the European Economic Area

	Additional Functions In addition to the functions:	Calibration ● Press C = 1	Important Note Concerning Verified Balances of Accuracy Class ①:
-	alphanumeric input	> See the section on "Calibration/Adjust- ment" for further instructions.	To avoid measuring errors, the respective air density must be allowed for.
-	taring (not during alphanumeric input)	inclue for further instructions.	The following formula is used to calculate the mass of the sample:
-	printing		·
	you can also access the following functions from the weighing		$m = n_w \frac{1 - \rho_L / 8000 \text{ kg m}^{-3}}{1 - \rho_L / \rho}$
	application:		m = mass of the sample
-	calibration (not during alphanumeric input)		$n_w = weight readout$
_	setup		$\rho_L$ = air density during weighing
_	turning off the balance		$\rho$ = density of the sample

**Practical Examples** Example W1: Simple weighing

Step	Key (or instruction)	Display/Output
<ol> <li>If necessary, tare the balance (<b>O</b> symbol: balance is tared, – verified balances only)</li> </ol>	Tare	Max4200 9 0% 
2. Enter sample ID	see Example W2	
3. Determine sample weight (Example)	Place load on balance	Max4200 a d= 0.01a 0% mm.m.m.m.m.m.m.m.m.m. + 223 1.56 9 Ca1
4. Print weight value	Ē	S ID ABC123 N + 2231.56 g

# Example W2 Enter "ABC123" as sample ID

- Note:The sample ID generally applies to one weighing operation onlyThe ID is deleted after data output

Step	Key (or instruction)	Display/Output
Initial status (balance unloaded) (ID can also be entered while balance is loaded)		Max4200 9 d= 0.019 0% 0.0 0 0 0.0 0 0 Cal
1. Select alphabetic input	ABC	Max4200 s d= 0.01s 0%
2. Select the required letter group	ABCDEF soft key	ABCDEFGHIJKLMNOPQRSTUVWXYZ/=-?∷#*"&■ Max4200 a d= 0.01a 0%
		A B C D E F
<ol> <li>Enter the letter "A" (To delete a letter:</li> </ol>	Ĥ soft key (℃F)	Max4200 a d= 0.01a 0% A
4. Select the letter group and enter "B"	ABCDEF soft key B soft key	ABCDEFGHIJKLMNOPQRSTUVWXYZ/=-?:#*"& Max 210 9 0% 4=0.01m9 100% ABCDEFGHIJKLMNOPQRSTUVWXYZ/=-?:#*"&
<ul><li>5. Select the letter group and enter "C"</li><li>(If only letters are entered, conclude input:</li></ul>	ABCDEF soft key C soft key (ABC)	Max4200 9 d= 0.019 0% ABC ABCDEFGHIJKLMNOPQRSTUVWXVZ/=-?:#*"&
6. Enter the numbers 1, 2 and 3		ABC123
<ul> <li>7. Store the ID (max. 20 characters)</li> <li>The next printout will include the sample ID</li> </ul>	S ID soft key	Max4200 a d= 0.01a 0% d= 0.01a 0.0 0 g

# **Device Parameters**

### Password

You can enter a password to block access to the operating menu and to the functions for ID code input and exact calibration weight input.

For details, see "Setting the Device Parameters" in the chapter entitled "Configuration".

### **User ID**

You can enter your own personal password (20 characters max.)

### Clock

ISO/GLP/GMP printouts in particular must be generated with the date and time stamp of the specific measurement. This date and time stamp is optional on other printouts.

For details, see "Setting the Device Parameters" in the chapter entitled "Configuration".

### Interface

### Purpose

This item enables you to set the parameters for the following interfaces:

- Serial interface port
- External switch function

Serial communications port You can set the serial communications port to use for the following modes:

- SBI
- XBPI
- YDPO1IS
- YDP02 - YDP03
- 1DF03
- YDPO1IS-Label - YDPO2IS
- YDPO2IS-Label
- Universal
- YDPO4IS
- YDPO4IS-Label

### Universal Remote Switch

You can connect an external universal remote switch (foot switch) to one of the two serial ports. Then you can assign one of the following functions to be performed when the switch is activated:

- Print key
- Tare key
- Cal key
- F1 function key
- CF key
- F2 function key
- Bar code scanner, PC keyboard (Special adapter necessary/ Order no. YCC01-0024M01)

### "PC Keyboard" Functions

The alphanumeric key codes implemented are for a German keyboard layout only ("Z" in the first row instead of "Y", for example). Some of alphanumeric keys are used with the [Shift] key: a-z, A-Z, 0-9, Space,,,,\+#<>!"\$@% &t/();=:\_?\*"

### Function key:

PC keyboard	Balance
F1	Tare key
F2	Setup key
F3	Soft key 6
F4	Soft key 5
F5	Soft key 4
F6	Soft key 3
F7	Soft key 2
F8	Soft key 1
F9	Display
F10	Escape
F11	🖉 key (print)
F12	Tare key
Return	Soft key 1
Backspace	Escape
Up Cursor	Soft key 3
Left Cursor	Soft key 4
Down Cursor	Soft key 2
Right Cursor	Soft key 1
POS1 (HOME)	Soft key 6
ESC	Escape
PRINT	🕘 key

The "Num Lock" und "Caps Lock" keys are not supported. There is no countryspecific option for switching these keys to a different function.

### **Control Port Function**

You can connect either a checkweighing display or an external universal switch to the serial communications port on the balance (factory setting).

To do so, you need to configure the interface for input or output.

Pin Assignment Chart of the Female Interface Connector

- Pin Function: Input
- 15 (*E*) key; see "Universal switch"
- 16 Tare key
- 17 Soft key 6 (Cal)
- 18 Soft key (F1)
- 19 CF key

Pin Function: Output

- 15 "External switch" (see above)
- 16 Control port 1: lighter
- 17 Control port 2: equal
- 18 Control port 3: heavier
- 19 Control port 4: "set"

For further information on the pin assignment chart, see the section on "Pin Assignment Charts" in the chapter entitled "Overview".

### Display


You can configure the display for your individual needs.

The contrast can be adjusted in 5 levels: Contrast

Characters can be displayed in black on white or vice versa: Background



You can blank out either the bar graph or the text line or both: Digit size



### 13mm

You can blank out the display of application symbols: Application symbols

### Keys

You can assign different functions to the CF key for deleting input and applications.

When you delete applications, you can delete either the data stored for all applications or just selected data. CF function in application

When you delete input, you can either delete all the data input in a field, or only the last character entered. CF function for inputs

You can block key functions; you can choose whether to block all keys (except  $\textcircled{\sc blue}$  and  $\fbox{\sc blue}$  , or just the alphanumeric keys.

Block key functions

**Extra Functions** Acoustic Signal

An acoustic signal is emitted when you press a key. When the key pressed is allowed, the signal is a single beep-tone; when it is not allowed, this is signaled by a double-beep (key does not initiate a function). In the Setup menu, you can configure whether

- the acoustic signal should sound (**On**)
- the acoustic signal should not sound (0ff)

### Power-On Mode

You can configure the balance so that when a power supply is connected,

- the scale is off (Off/on/standby or
- the scale switches on automatically (Auto on)

You can also configure the scale to go into the standby mode (Off/on/standby) when it is turned off.

After you turn on the scale, a self-test of the functions is run (TEST is displayed in the text line and the bar graph is shown)

### **MP8 Interface Emulation**

### Purpose

With the MP8 interface emulation function, you can connect peripheral devices of the MP8 generation that have separate AC power supplies (such as the 73822... Data Control terminal, a YFC ..., or a YDI 50 Z Data Input dedicated keyboard, for example) to your LA balance.

### Features

- The balance can be used only to determine weights.
- The interface communicates exclusively in the MP8 binary protocol.
- Select the application program and the program index for MP8, as well as individual application parameters, in the Setup menu.

### Preparation

- Activate the MP8 emulation mode\*:
- Press (Setup)
- Select the factory settings and confirm: press the  $\vee$  soft key repeatedly and then the  $\Rightarrow$  soft key
- Select Reset to MP8: press v soft key and > soft key
- Select Yes and press ↓ to confirm
- The balance is restarted
- follow the same procedure to return from MP8 emulation back to factory setting

### **Factory Settings**

Each parameter category has a factory setting. To restore the factory settings, select this item in the Setup menu and select YES to confirm.

The following parameters are not restored to factory settings when you activate this function:

- Language
- Password
- Display contrast Time (clock)

# **Calibration/Adjustment**

### Purpose

Calibration is the determination of the difference between the weight readout and the true weight (mass) of a sample. Calibration does not entail making any changes within the balance.

Adjustment is the correction of this difference between the measured value displayed and the true weight (mass) of the sample, or the reduction of the difference to an allowable level within maximum permissible error limits.

### **Available Features**

You can configure whether the calibration mode

- will be activated according to the specific setting (external/ internal) or
- can be selected by the user after pressing the Cal soft key: Selection mode.

Your balance can be calibrated externally (Balance menu: CAL key function; menu item Ext. cal./adj.; factory-def. wt. or Ext. cal./adj.; userdefined wt.) or internally (Internal cal./ adjustment).

External calibration can be performed with a user-defined weight Ext. cal./adj.; user-defined wt.

The adjustment can be performed automatically following calibration:

- Cal., then auto adjust.or - if desired, the adjustment operation can
- In desired, the adjustment operation can be started manually after calibration: Cal., then manual adjust

You can have the balance automatically display an adjustment prompt after a certain time interval has elapsed since the last calibration/adjustment or when the ambient temperature changes by a defined amount.

You can also configure the balance to perform calibration and adjustment automatically (isoCAL) when the pre-set time and/or temperature limit is reached On and reset application and On without resetting app.

You can have the calibration/ adjustment results documented in a ISO/GLP/GMP-compliant printout; see page 116.

### **Factory Settings**


Calibration/adjustment mode: Selection mode Calibration/adjustment sequence: Calibrate, then auto adjust isoCAL function (automatic initiation of cal./adj. sequence): On without resetting app.

Start automatic adjustment: isoCAL

Print GLP/GMP calibration/adjustment record: Automatic if GLP is selected

Releasing Access to External Calibration in Verified Balances of Accuracy Class ①

- Remove the covering plate from the back of the balance housing
- Move Switch 1 in the direction of the arrow



- Switch down: external calibration accessible Switch up: external calibration blocked
- > Note: Do not move Switch 2

### For service technicians only: External Calibration in Verified Balances of Accuracy Class I

- External calibration is blocked when the balance is used in legal metrology
- > External calibration can only be released after removing the verification control seal, in which case the validity of the verification becomes void and the balance must be re-verified
- External calibration can now be performed

Preparation

- Select the balance function for "calibration/adjustment": press Setup
- To select the Balance/scale functions: press the > soft key
- Select Calibration/adjustment: press the > soft key

Calibration/ adjustment	CAL key function		Ext. cal./adj.: default wt. Ext. cal./adj.: user-defined wt. Internal cal./adjustment Key blocked reproTEST* Selection mode					
	<ul> <li>Cal/adjustment ———</li> <li>sequence</li> </ul>	0	Calibrate, then auto adjust Calibrate, then manual adjust					
	<ul> <li>isoCAL function</li> </ul>	e o	Off Only adjustment prompt On and reset application On without resetting app.					
	<ul> <li>Start automatic adjustment</li> </ul>	o	User-def. Adj. time1 adjustment times Adj. time2 Adj. time3 isoCAL					
	<ul> <li>Print GLP/GMP ————————————————————————————————————</li></ul>	0	Automatic if GLP is selected On request, from record memory					
	Parameter for external weight		Weight ID (Wt. ID) Cal./adj. wt.:					
<b>C</b>								

o = factory setting

• Save settings and exit Setup menu: press the << soft key

\* = How to run this application is described in detail in our "Genius ME" Installation and Operating Instructions. Request your copy directly from Sartorius or download it from the Internet (www.sartorius.com; see "downloads")

**Preparation** Example: Set the parameters for calibration and adjustment; e.g., with manual calibration/adjustment, isoCAL off

Step	Press key(s) (or follow instructions)	Display/Output
<ol> <li>Switch on the balance, if not already on</li> </ol>	U	Sartorius logo and self-test Max6200 9 0% 6
2. Select the Setup menu	Setup	SETUP Balance/scale functions Device parameters Application parameters Printout Info << v >
3. Select "Balance/scale functions"	> soft key	SETUP BAL.FUNC. Calibration/adjustment Adapt filter Application filter Stability range Taring <<
4. Select "Calibration/adjustment"	≯ soft key	SETUP BAL.FUNC. CAL./ADJ. CAL/isoTST key function Cal/adjustment sequence isoCAL function Start automatic adjustment Print GLP/GMP adjustment record <<
5. Select CAL key function	⇒ soft key	BAL.FUNC.       CAL./ADJ.       CAL KEY         Parameter for external weight         Ext. cal./adj.;       user-defined wt.         Key blocked       oSelection mode         <
<ol> <li>Select desired function and confirm (e.g., "Internal cal./adj.")</li> </ol>	小 soft key, repeatedly, if necessary ↓ soft key	BAL.FUNC. CAL.∕ADJ. CAL KEY OExt. cal.⁄adj.; factory-def. wt. Ext. cal.⁄adj.; user-defined wt. Key blocked Selection mode <<
7. Exit CAL key function	< soft key	SETUPBAL.FUNC.CAL./ADJ.CAL/isoTSTkey functionCal/adjustment sequenceisoCAL functionStart automatic adjustmentPrint GLP/GMP adjustment record<
8. Select "Cal./adjustment sequence"	₩ soft key	SETUP     BAL.FUNC.     CAL./ADJ.       CAL/isoTST     key function       Cal/adjustment     sequence       isoCAL     function       Start     automatic       Adjustment     record       Print     GLP/GMP       <

Step	Press key(s) (or follow instruction	s) Display/Output
9. Confirm calibration and adjustment sequence	> soft key	BAL.FUNC. CAL./ADJ. CAL/ADJ SEQ OCalibrate, then auto adjust Calibrate, then manual adjust
		$\mathbf{o}$ = last setting selected
10. Select other settings, if desired and confirm (e.g., Calibration with manual adjustment)	v and J soft keys	BAL.FUNC. CAL./ADJ. CAL/ADJ SEQ Calibrate, then auto adjust oCalibrate, then manual adjust
11. Exit Cal./adjustment sequence	< soft key	SETUP BAL.FUNC. CAL./ADJ. CAL/isoTST key function Cal/adjustment sequence isoCAL function Start automatic adjustment Print GLP/GMP adjustment record << < < >
12. Select isoCAL function	v soft key	SETUPBAL.FUNC.CAL./ADJ.CAL/isoTST key function Cal/adjustment sequenceisoCAL functionStart automatic adjustment Print GLP/GMP adjustment record<
and confirm	> soft key	BAL.FUNC. CAL.∕ADJ. isoCAL FCT. Off Only adjustment prompt On and reset application oOn without resetting app. <<
	• = last setting selected	
13. Select other settings, if desired and confirm (e.g., turn off isoCAL function)	<ul> <li>∧ soft key repeatedly</li> <li>↓ soft key</li> </ul>	BAL.FUNC. CAL.∕ADJ. isoCAL FCT. OOff Only adjustment prompt On and reset application On without resetting app. <<
14. Save settings and exit the Setup menu	< < soft key	Max6200 a d= 0.01a 0% d= 100% <b>0.0 0 a</b>

Cal

Т

Т

Т

Selecting the Calibration/ Adjustment Parameter The setting Selection mode must be selected in the Setup menu under "Balance functions: Calibration/adjustment: CAL key function" (factory setting). After pressing the Cal soft key, you can choose from among the following settings by pressing the Select soft key:	<ul> <li>External calibration/adjustment with the preset calibration weight: Ext. cal./adj.; factory-def. wt.</li> <li>External calibration/adjustment with a calibration weight determined by the user: Ext. cal./adj.; userdefined wt.</li> <li>Internal calibration/adjustment Internal cal./</li> </ul>	• Start the desired routine: Press the Cal soft key again
	adjustment - Reproducibility test	
	reproTEST	

In the selection mode: Perform external calibration followed by automatic adjustment with the factory-set weight

Configuration: factory settings

Step	Key(s) (or instruction)	Display/Output
1. Select Calibration	Cal soft key	Max4200 9 d= 0.019 0% d= 0.019 100% d= 0.019 100% d= 0.019 100% d= 0.019 100% d= 0.019 10% d= 0.01910% d= 0.019 10% d= 0.01910% d= 0.019 10% d= 0.01910% d= 0.019 10% d= 0.01910% d= 0.
2. Select external calibration/adjust- ment with factory-defined weight	2×Select soft key	Max4200 9 d= 0.019 0% 0% 100% D.D.D.J.S Start d= 0.019 100% 0.019 0.019 100% 100% 100% 100% 100% 100% 100% 1
3. Start external calibration/ adjustment	Start soft key	0% 100% 100% A
<ol> <li>Place the weight on the balance (e.g., 2,000.00 g) Minus sign -: Weight too low Plus sign + Weight too high no plus/minus sign: Weight o.k.</li> </ol>	Place weight on balance	0% <b></b>
This is displayed after calibration, for approx.10 seconds: (on verified balances, the difference betv the displayed weight and the true weigh is displayed) After adjustment, the following is displa	t (mass)	0%
<ol> <li>Unload the balance (ISO/GLP/GMP printout: see page 116)</li> </ol>		Max4200 a 0% - d= 0.01a + 2000.009

Cal

### Internal Calibration/Adjustment

First set either Internal cal. / adjustment or Selection mode (factory setting) in the Setup menu under "Balance functions: Calibration/adjustment: CAL key function."

Inside the balance housing is a built-in motorized calibration weight.

The internal calibration/adjustment sequence is as follows:

- Select the calibration function: Press the Cal soft key and then the Start soft key
- > The internal calibration weight is applied automatically
- > The balance is calibrated
- > If the setting Calibrate, then auto adjust is selected in the Balance menu, the balance is now automatically adjusted
- > If the setting Calibrate, then manual adjust is selected in the Balance menu, you can end "Internal cab/ adjustment" now; to start it, press the Start soft key without adjusting the balance (see "Calibration and Adjustment Sequence", next column)
- > The internal calibration weight is removed
- > (ISO/GLP/GMP printout: see page 116)

**Calibration and Adjustment Sequence** In the Setup menu, you can configure the balance so that:

- calibration is always followed automatically by adjustment Calibrate, then auto adjust (factory setting) or
- you have the choice of ending the sequence or starting adjustment after calibration Calibrate, then manual adjust If no deviation is determined in calibration, or the deviation is within the tolerance limits dictated by the degree of accuracy you require, it is not necessary to adjust the balance. In this case, you can end the calibration/ adjustment sequence after calibration. There are 2 softkeys active at this point:
- Start to start adjustment
- End to end the sequence

# External Calibration/Adjustment\* with a User-Defined Calibration Weight First set either Ext. cal.<adj.;user-defined wt.or Selection mode (fac-

wt. or Selection mode (factory setting) in the Setup menu under "Balance functions: Calibration/adjustment: CAL key function."

Define the Calibration Weight

You can define a weight for calibration/ adjustment. External calibration/adjustment must be performed with weights that are traceable to a national standard and that have error limits which are at least 1/3 of the required tolerance of the display accuracy.

See page 44 for the external calibration/ adjustment sequence. For this example, select external calibration/adjustment with a user-defined weight. The balance has a factory-set weight value (see "Specifications").

To reset a user-defined calibration weight to the original factory setting:

○ Enter the factory-defined value manually (see "Specifications")

Step	Press key(s) (or follow instructions)	Display/Output
1. Select Setup menu	Setup	SETUPAPPLICATIONApplication 1=> Tossle wt.unitsApplication 2CountinsApplication 3Percent weish.Extra func. (F4)Animal weish.Extra func. (F5)Calc., densits<
2. Select "Balance/scale functions"	≥ soft key	SETUP BAL.FUNC. Calibration/adjustment Adapt filter Application filter Stability range Taring << < v >
3. Select "Calibration/adjustment"	≥ soft key	SETUP BAL.FUNC. CAL./ADJ. CAL/isoTST key function Cal/adjustment sequence isoCAL function Print GLP/GMP adjustment record Parameter for external weight << < < >>
<ol> <li>Select parameter for external weight</li> </ol>	♥ soft key 5 × > soft key	BAL.FUNC. CAL./ADJ. PARAMETER Wt. ID (W ID): Cal./adj. wt.: 100.00000 9
5. Select "Cal./adj. wt."	♥ soft key	BAL.FUNC. CAL./ADJ. PARAMETER Wt. ID (W ID): Cal./adj. wt.: 100.00000 9 << <
6. Enter calibration weight (e.g., 5000 g) and save	(5) $(0)$ $(0)$	3000 = last setting selected BAL.FUNC. CAL./ADJ. PARAMETER Wt. ID (W ID): Cal./adj. wt.: 200.00000 9 ESC
7. Save the calibration weight	لم soft key	BAL.FUNC. CAL./ADJ. PARAMETER Wt. ID (W ID): Cal./adj. wt.: 200.00000 9
8. Exit the Setup menu	< < soft key	

### isoCAL:

Automatic Calibration and Adjustment First set either On and reset the application or On without resetting the app. (factory setting) in the Setup menu under "Balance functions: Calibration/adjustment: CAL key function". The "isoCAL" display automatically begins flashing if the ambient temperature changes in relation to the temperature at the time of the last calibration/ adjustment, or after a defined time interval has elapsed. The balance is telling you that it wants to adjust itself.

This automatic calibration prompt is triggered when:

- The change in temperature or the elapsed time interval is greater than that shown in the table at the right
- The balance status does not correspond to Setup configurations
- No number or letter input is active
- The load has not been changed within the last 2 minutes
- The balance has not been operated within the last 2 minutes
- The load on the balance does not exceed 2% of the maximum capacity
- When you turn on the balance after it had been disconnected from power (only on verified balances with a readability of ≤0.1 mg)

When these requirements are met, C is displayed in the measured value line.

If the balance is not operated and the load is not changed, internal calibration and adjustment starts after 15 seconds have elapsed.

# Automatic Calibration and Adjustment at Set Times\*

In the Setup menu (see p. 41 for the menu path) you can enter up to three different times of day for automatic calibration/adjustment.

When one of these times is reached, the balance will display the flashing calibration prompt ("isoCAL"). Calibration/adjustment is not performed if the balance is off (standby mode) or in the Setup mode at the time set for calibration.

If the balance is being operated at the time set for automatic calibration/ adjustment, the calibration/adjustment sequence is prompted afterward. Automatic calibration/adjustment is prompted at set times when:

- The set time is reached
- The balance is not in Setup mode
- No alphanumeric input is active
- (e.g., equation for calculation)The load has not been changed within the last 2 minutes
- The balance has not been operated within the last 2 minutes
- The load on the balance does not exceed 2% of the maximum capacity

In the Setup menu, you can configure the balance so that after calibration and adjustment

- the application program is restarted
   On and reset the
   application
- the application program remains at its previous status On without resetting the app.

LA12000S, LA12000P, LA6200, LA4200, LA2200, LA34000

Also in Setup, you can configure the balance so that it displays a calibration prompt, but does not perform the calibration/adjustment functions automatically Only adjustment prompt

Switching Off the isoCAL Function in Precision Balances with a Readability ≥1 mg Used as Legal Measuring Instruments in the EU\*:

Automatic calibration and adjustment is also performed even when Off or Only adjustment prompt is set in the Setup menu.

Limited temperature range:

- Balances of accuracy class ①: +15°C to +25°C (59°F to 77°F)
- Balances of accuracy class I:
- +10°C to +30°C (50°C to 86°C)
- Standard temperature range: - 0°C to +40°C (32°F to 104°F)
- You can switch off the automatic adjustment function on verified balances with a readability  $\ge 1$  mg:
- after modification by the Sartorius Customer Service
- > Subsequently the balance can only be used when the ambient temperature range is within legally defined limits.
- The isoCAL function cannot be switched off on balances with a readability ≤0.1 mg
- \* including the Signatories of the Agreement on the European Economic Area

Model	when the temperature changes by	e after a time interval of			
LA310S, LA230S, LA230P, LA120S, LA3200D, LA1200S, LA2000P	1.5°C	4 h			
LA620S, LA620P, LA6200S, LA4200S, LA5200P, LA8200S, LA8200P	2°C	6 h			
LA220S, LA2200S, LA2200P, LA34001P, LA34001S, LA64001S	4°C	12 h			
LA820, LA420, LA16001S,	4°C	24 h			

These values are also factory set in the verified or verifiable models (with the model number suffix -OCE).

Fully automatic adjustment is initiated under the following conditions:

### **Block Printout**

You can have the results of a calibration/ adjustment procedure printed out. You can configure whether the printout is generated as soon as the procedure is completed, or whether a number of calibration/ adjustment procedures (up to 50) are collected for a block printout.

### Loading Stored Data:

Data for the block printout are stored in battery-backed memory. These data remain in memory for approx. 3 months after the equipment is disconnected from AC power. Make sure to generate a printout before disconnecting the equipment for a long period of time.

### Block Printout of Calibration/Adjustment Data

With the following Setup menu configuration, you can store the data from up to 50 calibration/adjustment procedures and have them printed on request:

### isoCAL printout On request, from record memory

When the memory contains 50 data records:

additional records are output automatically If at least one block printout data record has been configured, the following soft keys are available after you press the Cal soft key: Info The number of records is displayed in the text line PrtPro Print accumulated records

DelPro Delete accumulated records; records can only be deleted after a printout has been generated. If a password has been assigned in the Setup: Input menu, you must enter either the configured password or the General Password before you can delete the records.

For internal calibration/adjustment, the initialization mode of the procedure is displayed in the **Start** line.

M S V I	o e D -	d r -		_	n n -	0 0 –	s - -	A _	R -	т -	-	7 0 _	I L 0 1	U A 4 -	S 4 1 3 -	2 9 5 -	0 9 -	0 1 1	S 4 8 -
2 S D E	4 t x	• f t	0 r f e	4 t r	: n	1 + a	9 l c	9 0	7 c m	a p	l	0 i e	b t	m O r e	1 1 a d	2 n t	: g i	0 a o	3 l n
S D I	t i n	a f t	r f e	t r	: n	+ a	ι		i a	s d	o j	C O u e O	A • s	L O t	/ 1 m	t e	e g n	1 m t	0 p
I D	n i	t f	e f	r •	n	а +	l c	0	a m	d p	j l	d 0 u e 0	s t	t e O	m d O	e	n g	t	
D	i	f	f			+	C	0		Ρ	Ľ	0 u e 0		0	0		g		
2 S W N D E	7 t o i x	a m f t	0 r D f e	4 t r	:	1 + a	9 L c	9 2 0	7 , cm	0 a p	0 L	E 0 0 i e 0	x ••bt	t O C r e	1 • 0 1 a d	1 c t	: a g j		
1	3	•	– 0 e	5	-	- 1 -	- 9 -	- 9 -	- 7 -	-	-	_	_	_	_ 0 _	_ 9 _	-	_ 1 _	- 7 -

GLP header

List of Calibration/Adjustment Procedures:

Example 1: External calibration

Example 2: isoCAL triggered by difference in temperature

Example 3: isoCAL at defined time

Example 4: Internal calibration/adjustment triggered manually

Example 5: External calibration/adjustment

GLP footer

# **Application Programs**

### **Soft Key Functions**

Start Start application program

Weigh. Toggle to basic weighing functions

Using Verified Balances as Legal Measuring Instruments in the EU\*: All application programs can be selected on balances verified for use in legal metrology. Calculated values can be indicated as follows:

- Percent = %
- Piece counting (Counting) = pcs
- Computed value  $= 0, \Lambda$

# Auto-Start Application When the Power Goes On

In the Setup menu, you can select whether the last application active before you turn off the power starts automatically when the power is turned on again (Setup: Application parameters: Auto-start app. when power goes on: On)

### Toggle between Two Weight Units II1 II2

### Purpose

With this application program you can switch the display of a weight value back and forth between two weight units by pressing a soft key.

You can use the "Toggle between Two Weight Units" application in combination with a program chosen from Application 2 (checkweighing, time-controlled functions) and one from Application 3 (totalizing, formulation, statistics) as well as with the extra functions.

### **Available Features**

Toggling the displayed weight

- Setting the display accuracy
- Other features as for the basic weighing function

Factory Settings Weight unit 1: Grams /9

Display accuracy 1: All digits

Weight unit 2: Grams /9

Display accuracy 2: All disits

 including the Signatories of the Agreement on the European Economic Area

### Preparation

Balances used as legal measuring instruments: grams and kilograms are the only weight units available

Standard balances: The following weight units are available in both ranges:

Conversion factor	Display/ Printout	Line for metrological data
1.0000000000	g	g
0.0010000000	kg	kg
5.0000000000	ct	ct
0.00220462260	lb	lb
0.03527396200	OZ	OZ
0.03215074700	ozt	ozt
0.02671725000	tlh	tlh
0.02645544638	tls	tls
0.02666666000	tlt	tlt
15.43235835000	GN	GN
0.64301493100	dwt	dwt
1000.00000000000	mg	mg
1.12876677120	/lb	lb
0.02645547175	tlc	tlc
0.26670000000	mom	Μ
5.0000000000	К	К
0.08573333810	tol	tol
0.06578947437	bat	bat
0.21700000000	MS	MS
	1.000000000           0.0010000000           5.000000000           0.00220462260           0.03527396200           0.03215074700           0.02671725000           0.02645544638           0.02666666000           15.43235835000           0.64301493100           1000.000000000           1.12876677120           0.2645547175           0.2667000000           5.0000000000           0.0857333810           0.06578947437	Conversion factor         Printout           1.0000000000         g           0.00100000000         kg           5.0000000000         ct           0.00220462260         lb           0.03527396200         oz           0.03215074700         ozt           0.02645544638         tls           0.02666666000         tlt           15.43235835000         GN           0.64301493100         dwt           1000.0000000000         mg           1.12876677120         /lb           0.2667000000         mom           5.00000000000         K           0.266773333810         tol           0.06578947437         bat

- Turn on the balance: Press
- Select the Toggle Weight Units application in the Setup menu: press (Setup)
- Select Application parameters: press the v soft key 2 x, then the > soft key once
- Application 1 (basic settings): press the > soft key
- Select Toggle wt. units: (repeatedly) press the  $\land$  or  $\lor$  soft key
- Confirm Toggle wt. units: press the > soft key

	Weight unit 1 ———	
_	Display accuracy 1 — o	All digits Reduced by 1 digit for weight change Reduced by 1 digit *
	Weight unit 2	see above
L	Display accuracy 2 — o	All digits Reduced by 1 digit for weight change Reduced by 1 digit *

o = factory setting

= not for verified balances used as legal measuring instruments

see also "Application Parameters (Overview)" in the chapter entitled "Configuration"

• Save settings and exit the Setup menu: press the << soft key

### **Additional Functions**

In addition to the functions for:

- alphanumeric input,
- taring (not during alphanumeric input),
- printing (NUM print; S ID), you can also access the following functions from this application:

Calibration/AdjustmentPress the Cal soft key

- > See "Calibration/Adjustment" for further instructions
- Press (1)
- > See the section on the corresponding application program for further instructions
- Setup (setting parameters)Press Setup
- > See "Configuration" for further instructions

- Press (₩)
- > The balance shuts off

### **Practical Example**

Toggle the Display From Grams [g] (1st Unit) to Troy Ounces [ozt] (2nd Unit) Settings (changes in the factory settings required for this example): Setup: App: Application 1: Toggle wt. units: Weight unit 2: Troy ounces /ozt

Step	Key (or instruction)	Display/Output
1. Toggle back to weight unit 1, if necessary ( <b>U1</b> : Weight unit 1)	3	Max4200 9 0% <b>182 1.489</b> TOGGLE UNITS: Cal ozt
<ul><li>2. Change weight unit to Troy ounces [ozt] (U2: Weight unit 2)</li></ul>	ozt soft key	Max 135 of 0%

3. Change weight unit to Grams [g]

១ soft key

# Counting .....

### Purpose

With the Counting program you can determine the number of pieces of approximately equal weight.

You can use this application program in combination with a program chosen from Application 2 (checkweighing, time-controlled functions) and one from Application3 (totalizing, formulation, statistics) as well as with the extra functions.

### Features

- Optional balance configuration in Setup for automatically initializing this application and loading the most recent reference sample quantity "nRef" and average piece weight "wRef" when you switch on the balance (this is the automatic setting when the balance is initialized; Setup menu: Application parameters: Auto-start app. when power goes on: On)
- Reference sample quantity "nRef" entered manually
- Average piece weight "wRef" entered manually
- Storage of the current weight value for the preset reference sample quantity "nRef", to be loaded when the Counting program is initialized
- Setting the accuracy when the reference sample weight "wRef" is stored for calculating a piece count
- Automatic output of the quantity and sample weight via the data interface port after initialization or reference sample updating while running the Counting program (Select Setup: App: Basic settings: Printout configuration: Auto print upon initialization: All values)
- Toggling between piece count and weight value by pressing the Count. or Weish. soft key
- Toggling between counting and additional applications using the (1) key (for example, checkweighing)

### **Factory Settings**

Accuracy when calculating piece weight: Display accuracy

Reference sample updating: Automatic

### **Soft Key Functions**

Store value input as reference nRef sample quantity wRef Store input value as reference sample weight Reference updating criteria Opt. met; reference updating can be performed Count. Toggle to the Counting application Weigh. Toggle to the weighing mode Start Store current weight value for the preselected piece count

### Preparation

To calculate a piece count, the average weight of one piece must be known. This average piece weight can be entered into the Counting program in one of three ways:

- Enter the average piece weight using the numeric keys and store it;
- The last reference sample quantity entered is loaded and displayed when you turn on the balance. Place the same number of parts on the balance and initialize the Counting program;
- When the automatic initialization parameter (see previous page), is on (Setup: > Printout: Application-defined output: Autoprint upon initialization: All values; see page 34), the balance goes into the "counting" mode when you turn it on and loads the last average piece weight and corresponding reference sample quantity that were entered or calculated.

### Reference Sample Updating


You can have the average piece weight updated during counting (with the piece count displayed) if "AWP update" is set to "manual" or "automatic" in the Setup menu. Manual updating can only be performed when the  $U \bowtie date$  soft key is displayed. Reference sample updating must be completed before using an application program from Application 3.

The Opt. soft key is displayed when:

- the balance has stabilized (stability symbol displayed)
- the current piece count is not more or less than double the original piece count
- the current piece count is less than 100
- the internally calculated piece count (e.g., 17.24) differs from the nearest whole number (in this case: 17) by less than  $\pm 0.3$

Reference updating can be repeated several times with an approximately doubled piece count.

- $\bigcirc$  To perform reference updating: press the **Opt** soft key
- $\bigcirc$  Turn on the balance: press
- > Sartorius logo is displayed
- Select the Counting application in the Setup menu: press Setup
- Select the Application parameters: press the v key 2x, then the > soft key once
- Select Application 1 (basic settings): press the > soft key
- Select Counting: repeatedly press the ∧ or ∨ soft key
- Confirm Counting: press the > soft key



o = factory setting

see also the "Application Parameters (Overview)" in the chapter entitled "Configuring the Balance"

• Save settings and exit the Setup menu: press the << soft key

### **Additional Functions**

In addition to the functions for: alphanumeric input,

- alphanument input
- taring (not during alphanumeric input),
- printing,

you can also access the following functions from this application:

Calibration/Adjustment
Press the Cal soft key

> See "Calibration/Adjustment" for further instructions

Toggling to the Next Application

- Press 🗐
- See the section on the corresponding application program for further instructions
- Setup (Setting Parameters) Press (Setup)
- > See "Configuration" for further instructions
- Turning Off the Balance
- Press 🕖
- > The balance shuts off

**Practical Example** Determining an Unknown Piece Count; Weighing in the Preset Reference Sample Quantity

Settings (changes in the factory settings required for this example): Setup: App: Application 1: Counting: Average piece weight updating: Manual Setup: Printout: Application-defined output: Auto print upon initialization: All values

Step	Key (or instruction)	Display/Output
1. Delete previous setting if necessary	3	Max4200 a d= 0.01a 0%
2. Prepare a container for the parts to be counted	Place the empty container on the balance	+ 50.059 COUNTING: nRef = 10 pcs Cal Start
3. Tare the balance	Tare	Max4200 9 d= 0.019 0%
4. Place the reference sample quantity on the balance (example: 10 pcs, each weighing 2.148 g)	Place the displayed number of parts in the container	Ma×4200 9 d= 0.019 0%
5. Determine the average piece weight (number of decimal places displayed depends on the balance model)	Start soft key	Max4200 9 d= 0.019 0% ↓ ↓ ↓ ↓ 100% ▲ COUNTING: wRef = 2.14800 9 Cal ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓ ↓
6. If necessary, increase the number of parts and perform reference sample updating (example: 7 additional pieces)	Place additional parts in the container Opt. soft key	Max4200 s 0% m = 100% ■ +
7. Weigh uncounted parts	Place parts to be counted in the container	Ma×4200 9 d= 0.019 0% mmm + IS3 pcs COUNTING: wRef = 2.15800 9 Cal Wei9h.
8. If desired, print total piece count (here: 153 pcs)	Ē	Qnt + 153 pcs

# Weighing in Percent %

### Purpose

This application program allows you to obtain weight readouts in percent which are in proportion to a reference weight.

Alternatively, you can have the value displayed as a difference in percent between the weight on the balance and the reference weight, or as a special ratio1 or ratio2.

You can use the "Weighing in Percent" application in combination with a program chosen from Application 2 (checkweighing, time-controlled functions) and one from Application 3 (totalizing, formulation, statistics) as well as with the extra functions.

### **Available Features**

- Reference percentage "pRef" loaded from long-term memory when you turn on the balance
- Optional balance configuration in Setup for automatically initializing this application and loading the most recent reference percentage "pRef" entered with reference weight "Wxx%" when you turn on the balance (Setup: App: Auto start application when power goes on: On).
- Value displayed as:
- Residual quantity (portion)
- Difference (deviation)
- Ratio1Ratio2
- depending on the selected Setup menu code.
- Reference percentage "pRef" entered manually
- Store the current weight as the reference percentage weight "Wxx%" for initializing the weighing-in-percent application program
- Reference weight "Wxx%" entered manually
- Storage parameter (rounding-off factor) for storing the reference weight "W100%" in percentage calculation can be configured
- Configuration of decimal places displayed with a percentage
- Optional configuration for having the reference weight "Wxx%" and reference percentage automatically output via the data interface port after initialization (print application parameters) (Select Setup: Printout: Application–defined output: Auto print upon initialization: All values)
- Toggle the display between percentage and weight readout by pressing the Weish. or Perc. soft key
- Toggle between the weighing-in-percent program and other applications (e.g., checkweighing) by pressing (1)

### **Factory Settings**

Storage parameter: Display accuracy Digits displayed with percentage: 2 disits Display calculated value: Residue

### Soft Key Functions


рRef	Store value input as reference percentage
W××%	Store input value as reference sample weight
Perc.	Toggle to the Weighing-in- percent application
Restar	Start next weighing operation

- Weigh. Toggle to the weighing mode
- Start Store current weight value for preselected percentage

### Preparation

To calculate a value in percent, the reference percentage must be known. This value can be entered into the weighing-in-percent program in one of three ways:

- The last reference percentage entered is loaded and displayed when you turn on the balance. Place the corresponding weight on the balance and initialize the weighing-inpercent program;
- With automatic initialization switched on (Setup: App: Auto start application when power goes on: On), the balance goes into the "weighing in percent" mode when you turn it on and loads the last reference percentage entered as well as the corresponding reference weight;
- Enter the reference weight using the numeric keys and store it ( $H \times \times \times$  soft key).
- Turn on the balance: Press
- > Sartorius logo is displayed
- Select the Weighing in percent application in the Setup menu: Press Setup
- Select Application parameters: press the v soft key 2x, then the > soft key once
- Select Application 1 (basic settings): press the > soft key
- Select Percent weish.: repeatedly press the ∧ or ∨ soft key
- Confirm Percent weigh.: press the > soft key



o = factory setting

see also the "Application Parameters (Overview)" in the chapter entitled "Configuration"

• Save settings and exit the Setup menu: press the << soft key

### Equations

The following equations are used for the corresponding calculations:		
Residue (weighing in percent)	=	Current weight / 100% weight × 100%
Loss (percent-DIFF:)	=	(Current weight – 100% weight) / 100% weight × 100%
Ratio1 (percent-Ratio 1:)	=	(100% weight – current weight) / current weight × 100%
Ratio2 (percent Ratio 2:)	=	100% weight / current weight × 100%

### **Additional Functions**


In addition to the functions for:

- alphanumeric input,
- taring (not during alphanumeric input),
- printing,
  - you can also access the following functions from this application:
  - Calibration/Adjustment
- Press the Cal soft key
- > See "Calibration/Adjustment" for further instructions
  - Toggling to the Next Application
- Press (1)
- > See the section on the corresponding application program for further instructions
- Setup (setting parameters)
   Press Setup
- > See "Configuration" for further instructions
  - Turning Off the Balance
- Press 🕪
- > The balance shuts off

### Examples

Weighing in Percent with Reference Weight Taken From Weight on Balance

Settings (changes in the factory settings required for this example): Setup: App: Application 1: Weighing in percent Setup: App: Printout: Application-defined output: Auto print upon initialization: All values



# Animal Weighing <sup>⊗</sup>

### Purpose

Use this program to determine the weights of unstable samples (e.g., live animals) or to determine weights under unstable ambient conditions. In this program, the balance calculates the weight as the average of a defined number of individual weighing operations. These weighing operations are also known as "subweighing operations."

You can use the "Animal Weighing" application in combination with a program chosen from Application 2 (checkweighing, time-controlled functions) and one from Application 3 (totalizing, formulation, statistics) as well as with the extra functions.

### **Available Features**

- Animal weighing started manually or automatically
- Automatic start:
  - when a defined threshold has been exceeded (Minimum load threshold: 10; 20; ...; 500; 1,000 display increments)
  - when three successive subweights lie within a user-defined tolerance range (calm; normal; active; 0.1%; 0.2%; ...; 50%; 100% of the animal/object)
- Manual start:
  - also possible when the load is under the minimum load threshold
  - when three successive subweights lie within a user-defined tolerance range (calm; normal; active; 0.1.%; 0.2%; ...; 50%; 100% of the animal/object)

- Optional balance configuration in the Setup menu for automatically initializing this application when you turn on the balance
- Number of weighing operations for calculation of an average  $(\mathbf{m} \mathbf{D} \in \mathbf{f})$  can be entered before the beginning of each animal weighing operation
- The factor for calculation of the result can be entered before the beginning of each animal weighing operation
- The number of subweighs remaining to be performed is indicated in the text display during weighing
- Arithmetic average displayed as a result in the pre-set weight unit (identified by the 🗥 symbol).
- Optional multiplication of the arithmetic average by a user-defined factor Mul.

A circle "o" is displayed as weight unit and  $Mu1 = \times \times \times$  is shown in the text line

- Toggling between the animal weight and the calculated value by pressing the ×Net soft key and the ×Res soft key
- Automatic output of results via the interface port:
  - Number of weighing operations mDef
  - Multiplication factor Multiplication
- Automatic output of results (printout) via the interface port: Weighing result ×Net. Calculated result ×Res The following options have to be selected: Setup: Printout: Applicationdefined output: Auto print upon initialization: All values
- The unload threshold is equal to onehalf the minimum balance capacity
- Return to weighing mode by unloading the balance; i.e., when the load is below the unload threshold

### **Factory Settings**

Animal activity: 5% of the animal/object

### Start: Automatic

Minimum load for automatic storage: 100 display increments

Decimal places in result display: 2 decimal places

### Printout:

Average weight only

### **Soft Key Functions**

New. Automatic start:

- Unload balance and weigh next animal, if desired
- Press key to start next
  - subweigh
  - Manual start:
  - Start next subweigh
- mDef Store user-defined number of subweighs for averaging
- Mu 1 Store user-defined factor as multiplication factor for calculating the arithmetic mean
- ×Net Toggle to the animal weight
- ×Res Toggle to the calculated animal weighing result


### **Printout for Animal Weighing**

Upon completion of the averaging process, you can have the results printed out automatically. You can also have both the weight and the calculated result printed.

mDef Mul xNet xRes	+ +	10 0.347 153.00 53.91	g o
mDef:		bers of subwe ations for ave	
Mul:	Multi	plication fact	tor
xNet:	Resul	t of averagin	g
xRes:	Calcu	lated result	

### Preparation

- Turn on the balance: Press
- > Sartorius logo is displayed
- Select the Animal weighing application in the Setup menu: Press Setup
- Select Application parameters: press the V soft key 2x, then the > soft key once
- Select Application 1 (basic settings): press the > soft key
- Select Animal weigh.: ^ or ∨ soft key repeatedly
- Confirm Animal weigh.: > soft key



o = factory setting

see also the "Application Menu (Overview)" in the chapter entitled "Configuration"

• Save settings and exit the Setup menu: Press the < < soft key

### Additional Functions

In addition to the functions for:

- alphanumeric input,
- taring (not during alphanumeric input),
- printing,

you can also access the following functions from this application:

Calibration/Adjustment

- Press the Cal soft key
- > See "Calibration/Adjustment" for further instructions

Toggling to the Next Application Press গ্রি

- See the section on the corresponding application program for further instructions
- Setup (setting parameters)
   Press (Setup)
- > See "Configuration" for further instructions

Turning Off the Balance

- Press ທ
- > The balance shuts off
- The display goes blank, then OFF/Standby is displayed with backlighting

### **Practical Example**

Determining Animal Weight With Automatic Start of 20 Subweighing Operations for Averaging; Automatic Printout of the Number of Subweighing Operations and of the Animal Weight

Settings (changes in the factory settings required for this example): Setup: App: Application 1: Animal weighing: Animal activity: Active Setup: App: Application 1: Animal weighing: Printout: Average and calculated values Setup: App: Printout: Auto print upon initialization: All values

Step	Key (or instruction)	Display/Output
1. Delete previous setting if necessary	CF	
2. Prepare a container (cage)	Place empty cage on the balance	Max4200 9 d= 0.019 0% mmm
3. Tare the balance	Tare	Max4200 9 d= 0.019 0% mmmn
<ol> <li>Enter number of subweighing operations for averaging</li> </ol>	20	Max4200 9 d= 0.019 0% mmmm
5. Save number	mDef soft key	Max4200 9 d= 0.019 0% mmmnn - 100%⊠ ANIMAL WEIG.: mDef = 20 Cal     Start
6. Weigh the first animal	Place 1st animal in cage	weight value fluctuates due to animal activity Max4200 9 d= 0.019 0% mmmmmm • • • • • • • • • 100% • • • • • • • • • • • • • • • • • • •
7. Start automatic animal weighing	Start soft key	Max4200 9 d= 0.019 0% mmmmmmm • • • • • • • • • • • • • • •
The balance delays starting the subweighing operation until three successive subweights lie within the range defined for an "active" animal	When this criterion is met, the subweighing series begins	Max4200 3 d= 0.013 0% mmmmmm = 100%

Step	Key (or instruction)	Display/Output
After 20 subweighing operations the arithmetic average (xNet) is display		Max4200 9 d= 0.019 0%
(mDef: no. of subweighs Mul: calculation factor ×Net: arithm. average, net value ×Res: calculated value)		mDef 20 Mul 1 xNet + 69.72 g xRes + 69.72 o
8. Unload the balance	Remove animal from cage	Max4200 9 d= 0.019 0%
9. If desired, weigh next animal	Place animal in cage	Max4200 9 d= 0.019 0% mmmmm ■ ■ ■ ■ ■ ■ 100% ■ ANIMAL WEIG.: mDef = 20 Cal
Next weighing series begins automatically		Max4200 s d= 0.01s 0%∎ = = = ■ = = = ■ 100%⊠

Мах4200 э 0%		d= 0.019 • • 100%
♣ ANIMAL WEIG.: m	= 20	9
Cal	19 18	
	1	

# Calculation -

### Purpose

With this application program you can calculate a weight value using an algebraic equation. This can be used, for example, to determine the qsm weight (grams per square meter) of paper.

You can use the "Calculation' application in combination with a program chosen from Application 2 (checkweighing, time-controlled functions) and one from Application 3 (totalizing, formulation, statistics) as well as the extra functions.

### **Available Features**

- You can store an equation and configure the Setup menu to initialize this program automatically with the stored equation (Setup: App: Basic settings : Auto start upon initialization: On)
- The o symbol is displayed to indicate a calculated vale. The equation used is displayed in the text line
- If no equation was entered, the weight value is displayed
- Toggle between the weight readout, equation input and display of the calculated result by pressing the corresponding soft keys (or press CF) to toggle between weight and calculated value)
- The are four operators (+, -, \*, /) and one factor (weight value) available when you enter an equation
- Max. equation length: 28 characters
- Pressing CF will delete either the equation or the last character entered, depending on the configuration in the Setup menu (Setup: Device: Keys: CF function for input: Delete last character)
- The calculated result is displayed with the number of decimal places configured in the Setup menu. Not all decimal places are displayed if the result is longer than the display allows. If there are more digits before the decimal point than the display can show, an error message is displayed.
- The equation is stored in non-volatile memory

### **Factory Settings**

Decimal places in calculated result: 2 decimal places


### Soft Key Functions

Equat. Toggle to equation

- Enter an addition operator in the equation
- Enter a subtraction operator in the equation
- Enter a multiplication \* operator in the equation
- Enter a division operator in the equation
- Weight Enter a weight value in the equation
- Start Start calculation
- Weigh. Toggle to the weighing mode

### Preparation

- Turn on the balance: Press (10)
- > Sartorius logo is displayed
- Select the Calculation application program in the Setup menu: Press (Setup)
- Select the Application parameters: press the v soft key 2 x, then the > soft key once
- Select Application 1 (basic settings): press the > soft key
- Select Calculation: press the ∧ or ∨ soft key, repeatedly, if necessary
- Confirm Calculation: press the > soft key



### o = factory setting

see also the "Application Parameters (Overview)" in the chapter entitled "Configuration"

• Save settings and exit the Setup menu: press the << soft key

**Practical Example** Calculate the gsm weight of paper: determine the gsm of a sheet of A4 paper with the dimensions 0.210 m  $\times$  0.297 m = 0.06237 m<sup>2</sup>. The gsm weight is a product of the division of the weight by the surface area.

Settings (changes in the factory settings required for this example):

Setup: App: Application 1: Calculation

Step	Key (or instruction)	Display/Output
1. Turn on the balance and configure the settings as indicated above		
2. Delete previous setting if necessary	Œ	
3. Tare the balance	Tare	Max4200 9 d= 0.019 0% 0.009 EQUAT.: Cal Equat.Start
4. Select equation input	Equat. soft key	Max4200 9 d= 0.019 0%
5. Enter weight value Enter division sign Enter the surface area of a sheet of A4 paper	We ight soft key $\checkmark$ soft key $\bigcirc 0 6 2 3 7$	Max4200 9 d= 0.019 0% <b>= ₩/0.06237</b> Enter equation + - * / Weight Start
6. Turn on the calculated result display	Start soft key	Max4200 g d= 0.01g 0% 0 00% 000 00% 000 000 000 000 000 00
7. Determine the gsm weight	Place A4 sheet	Max4200 a d= 0.01a 0%


## **Density Determination**

### Purpose


With this application you can determine the density and volume of solid, pasty, liquid or powdered samples. You can use the "Density Determination" application in combination with a program chosen from Application 2 (e.g., checkweighing, timer functions) and one from Application 3 (totalizing, formulation, statistics) as well as the extra functions.

### Available Features


- Choose from 2 methods for determining density of solids:
- Buoyancy, or



- displacement.



 Density determination on pasty or powdered samples using the pycnometer method



- Density determination on liquids using the liquid density method
- Choice of liquids for buoyancy:
  - Water
  - Ethanol
  - Other liquids (user-definable)
- Reference values can be entered using the numeric keys
  - Weight of sample in air (Wa)

Weight of sample in liquid, or weight of reference liquid when using the pycnometer (Wfl)
 Weight of sample and reference

liquid when using the pycnometer (Wr)

- Long-term storage of parameters:
  - Temperature
  - Buoyancy correction
  - Air density
  - Density of reference liquid
  - Expansion coefficient
  - Plummet volume

### Factory Settings Method: Buoyancy

Liquid causing buoyancy: Water

No. of decimals for display of vol. density: 2 decimals

Printout: None

Wа

### Soft Key Assignments


Store weight of sample in air

- W f 1 With liquid density, buoyancy and displacement methods:
  - Store weight of sample in liquid
  - With pycnometer method:Store weight of reference liquid
- ۲ With pycnometer method: Store weight of sample and liquid
- Start Start a new measurement routine
- Param. Toggle to parameter input mode (depending on method selected)
- **Densit** Display the density (the parameters set remain effective for the next measurement)
- WeishDisplay the weight<br/>(the parameters set remain<br/>effective for the next meas-<br/>urement)
- Uol. Display the volume (the parameters set remain effective for the next measurement)

Buoyancy:	<b>Equations Used to Determine Density:</b> Rho = (Wa × (Rhofl – LA)) ÷ ((Wa – Wfl) × Corr) + LA
	For the buoyancy method, a factor of 0.99983 (factory setting) is used to allow for the buoyancy caused by the bars of the sample holder of the YDK 01 (LP) Density Determination Kit. This factor is yielded by allowing for this equation: buoyancy of bars = $2 \times d^2 \div D^2$ (Wa – Wfl)
	The equation takes the following variables into consideration: the number of wires or bars, the wire/bar diameter of the sample holder, and the inner diameter of the vessel used. The factor 0.99983 is yielded by $1 - 2 \times d^2 \div D^2$
	where: 2 = number of wires/bars d = wire/bar diameter (0.7 mm*) D = inner diameter of the vessel (76 mm*)
	If you are using different vessels or other density kits, press the Param. soft key to enter any necessary changes in this calculation factor.
	To determine the density of a solid according to the buoyancy method with our YDK 01 (LP) Density Determination Kit, make sure to use the beaker with a 76 mm diameter.
Displacement:	$Rho = (Wa \times (RhofI - LA)) \div (WfI \times Corr) + LA$
	For the displacement method, a factor of 1.00000 (factory setting) is used to allow for the buoyancy caused by a wire suspended in the liquid.
	If you are using different vessels or other density kits, press the Param. soft key to enter any necessary changes in this calculation factor.
	The equation takes the following variables into consideration: the number of wires or bars, the wire/bar diameter of the sample holder, and the inner diameter of the vessel used. This factor is yielded by: Corr = $1 - \chi \times d^2 \div D^2$
	where: $\chi$ = number of wires d = wire diameter D = inner diameter of the vessel
with:	Rhofl = density of the reference liquid Wa = weight of sample in air Wfl = weight of the sample in liquid/buoyancy of sample Corr = correction for buoyancy produced by the immersed wires or bars of the sample holder: 0.99983 for the buoyancy method 1 for the displacement method LA = correction for air buoyancy = 0.0012 g/ccm
Pycnometer: where:	Rho = $(Wa \times (Rhofl - LA)) \div (Wfl + Wa - Wr) + LA$ Rhofl = density of the reference liquid Wa = weight of the sample Wfl = weight of the reference liquid Wr = weight of sample + the reference liquid LA = correction for air buoyancy = 0.0012 g/ccm

### Preparation

- Turn on the balance: Press
- > Sartorius logo is displayed
- Select the Density application in the Setup menu: Press Setup
- Select the Application parameters: press the v soft key 2x, then the > soft key once
- Select Application 1 (basic settings): press the > soft key
- Select **Densitu**: press the ∧ or ∨ soft key, repeatedly, if necessary
- Confirm Density: press the > soft key



o = factory setting

see also the "Application Parameters (Overview)" in the chapter entitled "Configuration"

• Save settings and exit the Setup menu: press the << soft key

\* = How to run this application is described in detail in our "Genius ME". Installation and Operating Instructions. Request your copy directly from Sartorius or download it from the Internet (www.sartorius.com; see "download")

### Additional Functions

In addition to the functions for:

- alphanumeric input,
- taring (not during alphanumeric input),
- printing,

you can also access the following functions from this application:

- Calibration/Adjustment
- Press the C = 1 soft key
- > See "Calibration/Adjustment" for further instructions
  - Toggling to the Next Application
- Press 🗐
- > See the section on the corresponding application program for further instructions
- Setup (setting parameters)
- Press (Setup)
  See "Configuration"
- for further instructions
  - Turning Off the Balance
- Press 🕖
- > The balance shuts off

**Practical Example** Buoyancy: Determine the Density of Samples of a Solid Using the Buoyancy Method. Reference Liquid: Water.

Settings (changes in the factory settings required for this example): Setup: App: Application 1: Density

Step	Key (or instruction)	Display/Output
1. Delete previously stored values if necessary		Max 6200 9 d= 0.019 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0
2. Change configurations, if necessary	Param. soft key	DENSITY: Temperature : Temp <mark>+ 20.0</mark> °C Buoyancy corr: Corr + 1.000000
3. Position the sample holder (immersed)		Air density : LA + 0.001200 y/
4. Tare the balance	Tare	Max 6200 9 d= 0.019 0%## 100%@ DENSITY: Temp=+20.0 °C Cal   Param. Wa
5. Determine the weight of the sample in air: place sample on the weighing pan		Max 6200 a d= 0.01a 0% <b>#</b> <b>+ IS.029</b> DENSITY: Temp=+20.0 °C Cal   Param.  Wa
6. Store weight value	₩a soft key	Max 6200 9 d= 0.019 0%## <b>IS.D29</b> DENSITY: Temp=+20.0 °C Cal    Param.    Wf1
7. Determine the weight of the sample in liquid place samplein the sample holder		Max 6200 9 d= 0.019 0% <b>########</b> <b>  3.2 4 9</b> <u>DENSITY: Temp=+20.0 °C</u> Cal   Param.   Wf1
8. Store weight Density of sample is displayed	Wfl soft key	Max 6200 9 d= 0.019 0% mmmmm
9. Display volume of sample	Vol. soft key	Max 6200 9 d= 0.019 0% ∰nnmmm
10. Display weight	W <b>ei</b> ฮh soft key	Max 6200 a
11. Repeat procedure with next sample, if desired	d Start soft key	DENSITY: buoyancy Cal     Param. Weigh Start

### **Practical Example**

Displacement: Determine the Density of Samples of a Solid Using the Displacement Method.

Reference Liquid: Ethylene glycol. Temperature: 23°C (73.4 °F). Set the density at 20°C (68°F) to 1.113 g/cm<sup>2</sup> and the volume expansion coefficient at 20°C (68°F) to 0.00064 grd<sup>-1</sup>.

Settings (changes in the factory settings required for this example): Setup: App: Application 1: Density: Method: Displacement

Setup: App: Application 1: Density: Liquid for buoyancy: User-definable

Ste	ep	Key (or instruction)	Display/Output
1.	Delete previously stored values if necessary	(CF)	Max 6200 9 d= 0.019 0%∎ 100%⊡ <b>+ DENSITY:</b> Rhofl=+1.000 g/ Cal    Param.  Wa
2.	Change configurations: Temperature: 23.0 Density of ref. liquid: 1.113 Expansion coefficient: 0.000640	Param. soft key	DENSITY:         Temperature       Temp + 23.0 °C         Buoyancy corr:       Corr + 1.000000         Air density       LA + 0.001200 y/         Ref.lig.dens.:       Rhofl         1.113 y/         Expan.coeff.:       b         0.000640
3.	Place the container with the reference liquid on the balance		
4.	Tare the balance	Tare	Max 6200 9 d= 0.019 0%
5.	Determine the weight of the sample in air: place sample on the weighing pan		Max 6200 s d= 0.01s 0%
6.	Store weight value	₩a soft key	Max 6200 9 d= 0.019 0%
7.	Determine the weight of the sample in liquid: place sample in the sample holder		Max 6200 s d= 0.01s 0%
8.	Store weight Density of sample is displayed	Ы́f1 soft key	Max 6200 9 d= 0.019 0%
9.	Display volume of sample	Ųol. soft key	Max 6200 s d= 0.01s 0%
10	. Display weight	Weish soft key	Max 6200 9 0%
11	. Repeat procedure with next sample, if desired	Start soft key	DENSITY: displacement Cal    Param.Densit Start

# Differential Weighing +

### Purpose

This application enables you to compare samples before and after a given treatment (such as drying or ashing) and determine the difference in weight.

There are different procedures available for this application:

- Collect all data (tare, initial weight, and backweighing result) for each sample individually (menu setting "Weighing sequence: Individual weighing")
- Save the tare weights and initial weights for all samples first, then perform backweighing (menu setting "Combined weighing")
- Save the tare weights for all samples first, then determine the initial weight of each sample and, finally, perform backweighing (serial weighing)

### Features

- 4 different sequences for measuring the tare weights, initial sample weights and the backweights (backweighing result):
- Individual weighingConsecutive individual
- weighing
- Combined weighing
- Serial weighing
- Choice of weighing sequence by selecting this parameter in the Setup menu or by pressing the Wa.sea soft key (if the "Weighing sequence key" option is set)
- Perform up to 99 backweighing routines on a single sample
- Differential weighing with or without tare weighing (not necessary for measuring coatings or lamination layers)
- Define the number of decimal places displayed for calculated results
- Define whether autosaving weight values is dependent on the stability parameter
- Define whether the minimum load for autosave is dependent on the display
- List function, with Display page for lots:
   Lists all lots (up to 100 max.) with the number of samples in each lot and the processing status (tare weight, initial weight, backweighed residue ("backweight")
   View, create, rename or delete lots generated
   Enter or change a factor for calculation of results

Display page for samples: Lists all samples (up to 999 max.) with processing status View, delete, omit, or include samples

Display page for measured values: Shows date, time, ID and values measured


Display page for results: Values calculated for a sample (backweight, loss, ratio1, ratio2)

- Special display page for statistics lets you define whether lot statistics are dependent on backweight, loss, or ratio values
- Press a soft key to view the desired display page (lots, samples, values or results)
- To view lot, sample or measured value data, enter the ID and then press the corresponding soft key (Lot/Sample/Values)
- Define whether printer output is dependent on the processing status of the sample
- Printout can contain individual values, backweighed values and statistics
- User-definable printout format
- The configurations for the weighing sequence and results are saved separately for each lot


# Differential Weighing: Defining the Weighing Sequence

You can choose from among four sequences for measuring tare weights, initial sample weights and backweighed residue ("backweight") during differential weighing:


 Individual Weighing Tare weight, initial weight and backweight are measured in that order.



2. Consecutive Individual Weighing Several individual weighing routines (see above) are performed in series.




3. Combined Weighing The tare and initial weight, in that order, of each sample is measured first, then the backweight of each sample is measured.



4. Serial Weighing

First the tare weight for each sample is measured, then the initial weight of each sample is measured in the same order that their tare weights were measured, and then all backweights are measured.

Measured weights/values



You can define the weighing sequence in the Setup menu or by pressing the  $U \cong .seq$  (if the "Weighing sequence key" option is activated).

Factory Settings of the Parameters Weighing sequence: Group weighing

Tare weighing: Yes

Result with decimal point: 2 decimal places

Autosave values: No

Minimum load for autosave: 20 disits

Save statistics: No

Generate printout: Automatic after backweishins

Include sample ID in the text line: No

Wg. seq. key: Yes

Clear sample after individual weight, result + unload: **No** 

Last residual weight saved as the initial weight:  $\ensuremath{\mathsf{No}}$ 

### **Printout for Differential Weighing**

Generating Printouts Automatically The configured backweighing printout is generated automatically after backweighing, if one of the following settings is selected Setup: Application 1: Differential weighing: Generate printout:

Automatic after backweighing Auto after init.weigh + backweigh Auto after tare-, init- +backweigh.

Generating Printouts Manually

The individual printout is generated when the B key is pressed while there is a tare, initial or backweight on the balance, or when D is pressed to toggle applications.

You can generate the configured printout manually after backweighing if you press the *B* key while the display page for the results is shown.

To generate the statistics printout, press the a key

- when the display page for statistics is shown,

 when the samples with a desired number of backweighing operations is selected (for example, statistics on all samples with 2 backweighing operations). The following printout is generated:

Backweighing Printout (Example)

16.11.1999 14:55:12
Lot CH12345
Sample 14
ID CX88
T1 + 23.458 g
N1 + 125.572 g
R (3)+ 103.684 g
R + 82.57 %
D – 21.887 g
D – 17.43 %
Fact + 1.10345
D-Res - 24.15 o
Ratio1+ 21.11 %
Ratio2+ 121.11 %

Dotted line Date/time Lot ID Sample number Sample ID Tare weighing (with PT1 selected) Initial weight Backweight (residue as weight) Residue in percent Loss as a weight Loss in percent Calculation factor Calculated loss Ratio 1 Ratio 2 Dotted line

### Preparation

- Turn on the balance: press 🕪
- > Sartorius logo is displayed
- Select the Differential Weighing application in the Setup menu: press (Setup)
- Select the Application parameters: press the v soft key 2x, then the > soft key once
- Select Application 1 (basic settings): press the > soft key
- Select Differential weighing: press the ^ or v soft key, repeatedly, if necessary
- Confirm Differential weighing: press the > soft key

Differential – weighing	— Weighing sequence ') —	$\vdash$	Individual weighing Consecutive individual weighing Combined weighing Serial weighing
	— Tare weighing ————	T <sub>o</sub>	No Yes
	<ul> <li>Result with</li> <li>decimal point</li> </ul>	0	None 1 decimal place 2 decimal places 3 decimal places 4 decimal places 5 decimal places 6 decimal places
	– Autosave – – – – – – – – – – – – – – – – – – –	- o	Off On; first value at stability On; last value at stability <sup>2</sup> ) On; value bet. 70 – 130% at stabil. <sup>3</sup> )
	– Minimum load ––––– for autosave	- o	None 10 digits 20 digits 50 digits 100 digits 200 digits 500 digits 1000 digits
	<ul> <li>Save statistics</li> </ul>	L,	No Yes
	– Generate printout ––––	0	None Automatic after backweighing Autom. after initial and backweigh. Automatic after tare, initial and backweigh
	<ul> <li>Include sample ID</li> <li>in text line</li> </ul>	L,	No Yes
	— Wз. seakey ———	T <sub>o</sub>	No Yes
	<ul> <li>Clear sample after</li> <li>ind.wgh+res + unload +</li> </ul>		No Yes
	Last residual weight — saved as initial weight (ashing)	L o	No Yes

o = factory setting

- Setting can only be changed when the application is first run and when the אש. בפא key option is set to "No"
- <sup>2</sup>) The last value with the stability symbol is saved only during initial sample weighing. Tare and backweights are saved as the "first value at stability." This menu option enables you to perform filling functions during initial weighing.
- <sup>3</sup>) To autosave a value between 70 and 130% of the initialization value, the balance must be unloaded to below 30% or loaded to above 170% of this initialization value.

### Equations

Backweight in %:	backweight / initial weight · 100%
Loss in weight:	backweight – initial weight
Loss in %:	(backweight – initial weight) / initial weight · 100%
Calculated loss:	(backweight – initial weight) · factor
Ratio 1 in %:	(initial weight – backweight) / backweight $\cdot$ 100%
Ratio 2 in %:	initial weight / backweight · 100%

## Function of the CF Key

Weighing sequence	Status	Press CF key	Value deleted	Subsequent status
Individual	Tare weighing	-	-	_
weighing	Initial weighing	1 ×	Tare	Tare weighing
	Backweighing	1 ×	Initial weight	Initial weighing
		$2 \times$	Tare	Tare weighing
	Results displayed	1 x	Backweight	Backweighing
Consecutive individual weighing	As for individual we	eighing		
Combined	Tare weighing	1 x	Previous init. weight	Initial weighing
weighing		$2 \times$	Previous tare value	Tare weighing
	Initial weighing	1 ×	Tare	Tare weighing
	Backweighing	1 ×	Previous backweight	Backweighing
	Results displayed	1 x	Last backweight	Backweighing
Serial weighing	Tare weighing	1 x	Previous tare value	Previous tare weighing
J J	Initial weighing	1 x	Previous init. weight	Previous initial weighing
	Backweighing	1 x	Previous backweight	Previous backweighing
	Results displayed	1 ×	Last backweight	Backweighing


### **Soft Key Functions**

Create	Create a new lot	Values	Select/view the display page for values
Lot	Select/view the display page for lots	Sample	View the display page for samples
Ini.wt.	Save initial weight		
>Ini.⊎	Go to initial weighing function	Spl#	Select/create sample data record
Result	View display page for results	Backw.	Save backweight value
>Resul	Go to display page for results	>Backw	Go to backweighing function
M-ini	Input initial weight value	Omit	Omit/include sample
M-back	Input backweighed residue	Stat.	View display page for statistics
M-tare	Input tare value	Tare	Save tare value
Delete	Delete lot/sample	>Tare	Go to tare weighing function
		Wg.seq	Select weighing sequence

# Direct Selection of Lot/Sample/Value

When the measured values are displayed, you can enter numbers and letters to:

- \_ change the lot and sample directly (displayed in the text line)
- directly access the display pages for samples and values
- Enter lot/sample/value ID



(in this example, "CH0001", designates a certain lot)

- Press the corresponding soft key
- > Lot soft key: The lot corresponding to the ID entered is displayed (if the lot is not found, the display page for lots is shown)
- > Sample soft key: The display page is shown for samples in the active lot that contains the sample number entered
- > Values soft key: The values for the sample entered are shown
- > Spl# soft key: Change samples without the list function

### **Toggle between Differential Weighing** and Basic Weighing: Press 🗐

### **Direct Selection of the Weighing** Sequence

You can change the weighing sequence (individual weighing, combined weighing, etc.) directly during measurement by pressing the Wt.see key, if this function has been activated in the Setup menu [Application parameters: Application 1: Differential weighing: Weighing sequence key: Yes]

## List Function for Differential Weighing

The list function has 4 display pages: one each for lots, samples, values and results.

### **Display Page for Lots**

The display page for lots shows all of the lots that have already been created, as well as the number of samples in each lot and the processing status of the selected sample (tare, initial and backweight). On this display page you can create, rename, delete and print lots. You can also define a factor for calculation of loss; for instance, to have weight per unit area calculated (such as grams per square meter). You can also enter a lot ID alphanumerically to access a lot directly.

### **Display Page for Samples**

CX87

This display page shows the samples contained in a selected lot, as well as the processing status of the samples (tare, initial and backweight) and the sample IDs. You can also enter a sample ID alphanumerically to access a sample directly.

### **Display Page for Values**

This display page shows the date and time of sampling, as well as the sample ID and the values measured, for a selected sample.

### **Display Page for Results**

This display page shows the calculated values for a selected sample. These include backweighed residue, loss, loss calculated using a factor, and the ratio values. The  $\circ$  symbol indicates the value that is selected for display immediately following a backweighing procedure. To change this setting, use the  $\lor$  and  $\land$  soft keys to move the highlight bar to the desired value, and press  $\dashv$  to confirm.

### **Display Page for Statistics**

This page shows the characteristic data for a lot (date; time; statistics on, for example, the backweighed residue; number of samples) as well as the calculated values (mean value, standard deviation).


To select a set of statistics from a lot with different numbers of backweighing procedures: Press the J soft key to display the selected set of statistics:

LOTS:	792	Sm	pl.ava	ail.
1	1	Sa	møle	Т
122	1	Sa	møle	T, N
AB05	20	Sa	møles	T, N, R1
CH0001	10	Sa	mples	T > N
CH01234	2	Sa	mples	T, N, R1
<< DeleteCreate	0		V	Sample

SMPL: avail.792 Lot: CH0001 Sample 1: T.N.R(1)

Sample 2: T,N,R(1) Sample 3: T,N Sample 4: T,N Sample 5: T,N << [Delete] < ^	CX88 v Values
Sample 4: T,N Sample 5: T,N << Delete < ^	v Values
Sample 4: T,N Sample 5: T,N << Delete < ^	v Values
Sample 5: T,N << Delete < ^	v Values
<< Delete < ^	v Values
	v įvalues
VALUES: Lot: CH0001 Sm	101:2
Date,time: 16.11.1998	15:11:17
Name: ID	CX88
	324.72 9
Net initial wt: N1 +	414.45 9
<u>Backwøh'd res: R (1)+</u>	<u>393.55 a</u>
<< Result < ^	V
· · · · · ·	
RESULT: Lot: CH0001	Smp1:2
Residue: R +	20.74 9
oResidue: R +	80.48 %
Loss: D -	5.03 9
Loss: D -	19.52 %
Ratio1: DR +	24.25 %
< Values < n	V 4

	TICS:	Lot	: CH	6789		
Statis	tics o	n: R		1)	5	Spls
Statis	tics o	n: R	<	2)	3	Spls
Statis	tics o	n: R	<	*)	8	Spls
< <				~	~	Ļ
STATIS	TICS:	Lot	: CH	6789		
Date,t	ime:		04.	02.19	99 14	:31:30
Statis	tics o	n: I	R	(1)	>Re	sidue<
No.of	values	:	n			2
Mean v	alue:		Mea	n +	93.	28 %
Std. d	leviati	on: :	s		0.	01 %
						-



Selecting Display Pages in the List Function for Differential Weighing

## **View and Print Display Pages**

You can use the manual mode to print display pages (for lots, samples, values and results).

To view and print a display page for values:

- Show the display page for lots: press the Lot soft key
- Show the display page for samples: press the Sample soft key
- Show the display page for values: press the Values soft key
- Print the display page for values: press <a>[3]</a>

PRINT: Current		1	Smøl:1	
All sam				
< <	 <			

- $\bigcirc$  Select amount of data to be included on the printout: press the  $\lor$  or  $\land$  soft key
- Confirm print command: press the + soft key

The display pages for lots and samples can be printed when they are shown on the balance display.

- View the Display Page for Results:
  Show the display page for lots: press the Lot soft key
- Show the display page for samples: press the Same le soft key
- Show the display page for values: press the Values soft key
- Show the display page for results: press the Result soft key
- Print the display page for results: see instructions for printing the display page for values

You can manually print the display page for statistics when it is shown on the balance

- To view the display page for statistics:
  Select statistics: press the Stat.
  soft key
- For samples each with a different number of backweights:
   Select the kind of statistics: press the v or o soft key
- $\bigcirc$  Confirm selection: press the 4 soft key

**Deleting or Omitting a Lot or Sample** Lots can be deleted; samples can be deleted or omitted.


- You can choose between
- deleting the current lot and
- deleting all lots.

You can choose whether

- the active sample is deleted entirely, oronly the values from the active sample
- are deleted, orall samples are deleted completely, or
- only the values from all samples are deleted, or
- a sample is omitted

Deleting a Lot/Sample

- Activate the display page for lots/samples
- Select the desired lot/sample
- Select the "Delete" function: Press the **Delete** key
- Define the lot(s)/sample(s) to be deleted and confirm
- Select "Yes" to complete the delete function or "No" to cancel it



Example: Deleting all samples completely (in this case, 3 samples) Omit or Include Sample

- Activate the display page for samples
- Select the desired (or omitted) sample
- Delete: Press the Delete key
- Omit: Press the Omit key

<u>SMPL:</u>		<u>. 991</u> Linir(3	Lot:	MILK123	7
Samøle Samøle		T, N, R(3	3	CX8	38
Sam⊳le	3:	T, N, R (1	)	Comittee	Ð

Example: Sample 3 has been omitted

### **Additional Functions**

- In addition to the functions for:
- alphanumeric input,
- taring (not during alphanumeric input), and
- printing,

you can also access the following functions from this application:

- Calibration/Adjustment
- Press the Cal soft key
- > See the section entitled "Calibration/ Adjustment" for further instructions
- Setup (Parameter Settings)
- Press the Setup key
- > See the chapter entitled "Configuration" for further instructions
  - Turning Off the Balance
- Press the 🕪 key
- > The balance shuts off

# **Practical Examples**

Combined weighing; create lot, determine the difference in weight between initial weights and backweights of three samples (with autoprint of the formatted backweighing record)

Settings: factory settings

Step	Key (or instruction)	Display/Output
1. Turn on the balance/scale, if necessary		Max 6200 9 d= 0.019 0% <b>+ D.D.J.9</b> DIFF.WEIGHING: Combined weigh. Cal Start
2. Tare the balance/scale, if necessary	Tare	Max 6200 9 d= 0.019 0% 00% 00% 00% 00% 00% 00% 00% 00% 00%
3. Start combined weighing	Start soft key	Max 6200 9 d= 0.019 0% 00% 00% 00% 00% 00% 00% 00% 00% 00%
4. Select lot ID input	Lot soft key	LOT: create lot name Lot name: Factor: +1.00000
5. Enter lot ID	(ABC) (1) (9) (0) (·	<
6. Confirm input	<b>↓</b> soft key	<c ب="" ب<br="">LOTS: 999 Smpl avail. CH0001 O Samples</c>
<ol> <li>Activate weight readout (or toggle to combined weighing)</li> </ol>	ंद soft key Ыर. डल्व soft key	Image: Constraint of Constraints         Sample           Мах 6200 в         d= 0.01 в           0%         100%           0.0         0
8. Measure 1st tare weight	Place 1st empty container on balance/scale	Max 6200 з d= 0.01 у 0% + <b>72.0 79</b> COMB.WGH: CH0001 #1 avail. Ц↑↑ Cal Lot Wø.seq>Backw Tare
9. Save tare value	Tare soft key Remove the empty container	Max 6200 9 d= 0.019 0% 00% 00% 00% 00% 00% 00% 00% 00% 00%
10. Measure the initial weight (in this case: 24.52 g)	Fill the 1st container Place filled container	Max 6200 a d= 0.01a 0% <b>+ 24.529 N1</b> ComB.WGH: CH0001 #1 T ▲↑↑ Cal Lot Wa.seq>Backw Ini.wt

Step	Key (or instruction)	Display/Output
11. Save initial weight value	Ini.wt soft key Remove the filled container	Max 6200 9 d= 0.019 0% d= 0.019 100%
		LLUUS COMB.WGH: CH0001 #2 avail. ⊔++ Cal Lot W9.sem>Backw Tare
12. Measure the 2nd tare weight	Place 2nd empty container on balance/scale	Max 6200 9 d= 0.019 0% <b>+ 73.309</b> <u>ComB.wGH: CH0001 #2 avail. ⊔≁↑</u> Cal Lot W9.seq>Backw Tare
13. Save tare value	Tare soft key Remove the empty container	Max 6200 9 d= 0.019 0% 100% <b>0.0 0 9</b>
		COMB.WGH: CH0001 #2 T ₩++ Cal Lot W9.seq>Backw Ini.wt
14. Measure the initial weight (in this case: 22.43 g)	Fill the second container Place filled container on balance/scale	Max 6200 9 d= 0.019 0% 100%
	on balance/scale	+ <b>ĊĊ.┦Ĵ9</b> N1 COMB.WGH: CH0001 #2 T ₩↑↑ Cal Lot Wø.seq>Backw Ini.wt
15. Save initial weight value	lni.wt soft key Remove the filled container	Max 6200 a d= 0.01a 0% d= 0.01a 100%
		LLUU9 COMB.WGH: CH0001 #3 avail. ⊔↔ Cal Lot W9.seq>Backw Tare
16. Measure the third tare weight	Place 3rd empty container on balance/scale	Мах 6200 э d= 0.01э 0% <b>д д д д д д д д д д д д д д д д д д д</b>
17. Save tare value	Tare soft key Remove the empty container	Cal     Lot  W⊎.seq >Backw  Tare Max 6200 9 d= 0.019 0% d= 0.029 0% d= 0.019 0% d= 0.019 0% d= 0.019
		COMB.WGH: CH0001 #3 T ₩↓↓ Cal   Lot Wø.seq>Backw Ini.wt
18. Measure the initial weight (in this case: 25.79 g)	Fill the container Place filled container on balance/scale	Max 6200 9 d= 0.019 0% <b>+ 25.799</b> N1 <u>COMB.WGH: CH0001 #3 T</u> ■↑↑ Cal Lot W9.seq>Backw Ini.wt
19. Save initial weight value	Ini.wt soft key Remove the filled container	Max 6200 9 d= 0.019 0% = 100%
		COMB.WGH: CH0001 #4 avail. ⊔≁≁ Cal Lot Wø.seq>Backw Tare
20. Treat the sample		
21. Go to backweighing function	>Backw soft key	Max 6200 s d= 0.01s 0%

Step	Key (or instruction)	Display/Output
22. Save the 1st backweight is defined (the value to be displayed on the display page for results; in this case: backweighed residue in %)	Place 1st container on balance/scale Backw. soft key	Max 6200 9 d= 0.019 0% 100% + <b>79.28%</b> N1 COMB.WGH: CH0001 #1 >Residue< M↑↑ Cal Lot W9.seq >Tare Result
Configured backweighing printout is generated		$\begin{array}{cccccccccccccccccccccccccccccccccccc$
23. Save the 2nd backweight	Remove 1st container Place 2nd container Backw. soft key	Max 6200 a d= 0.01g 0%
Configured backweighing printout is generated		$\begin{array}{rrrrrrrrrrrrrrrrrrrrrrrrrrrrrrrrrrrr$
24. Save the 3rd backweight	Remove the 2nd container Place the 3rd container on the balance/scale Backw. soft key	Max 6200 9 d= 0.019 0% BO.50% ♪ + BO.50% ♪ N1 COMB.WGH: CH0001 #3 >Residue< ₩↑↑ Cal Stat. Lot W9.seq >Tare Result
Configured backweighing printout is generated		$\begin{array}{cccccccccccccccccccccccccccccccccccc$

# 25. Unload the balance/scale

Remove the 3rd container

# Checkweighing ½

### Purpose

This program is used to check whether a sample corresponds to a pre-set target value or is within a specific tolerance range. In addition to the display in the measured value line, the results are shown on the bar graph and can also be routed through the interface port via control lines for further electronic processing.

You can use the "Checkweighing" application in combination with a program chosen from Application 1 (e.g., counting, weighing in percent) and one from Application 3 (totalizing, formulation, statistics).

### **Available Features**

- Optional configuration in the Setup menu for long-term storage of target value and tolerance limits
- Optional balance configuration in Setup for automatically initializing this application and loading the values stored in long term memory for the target value and the upper and lower tolerance limits when you turn on the balance
- You can perform checkweighing
  - without entering a target value, but only upper and lower tolerance limits;
  - as differential checkweighing;
  - with symmetric or asymmetric limits which can be entered as percentages
- Enter target value and limits by placing a load on the balance or using the numeric keys
- Control in entering target and tolerance values, so that the upper limit ≥ the target ≥ the lower limit ≥ 1 display increment
- Accuracy of a weight readout or keyboard input as target/tolerance values corresponds to the display accuracy
- Optional balance configuration in the Setup menu for automatic output to the interface port (print application parameters) of target value and tolerance limits when initialization is completed
- Control range for the balance's data output port lines is 30% to 170% of the target value
- Optional configuration in the Setup menu for activation of control lines dependent on weight value (weight value within control range, stability reached)
- Toggling the display between weight readout and control (checkweighing) display by pressing the corresponding soft key. If the weight value exceeds tolerances, the measured value line shows the weight while the control display shows "LL" for "too low" or "HH" for "too high."
- Press the Show soft key to display target value and tolerance limits in the text line after initializing the application.

- Weight value in bar graph displayed in relation to upper and lower limits and target value.
- "OK" value counter displayed in the text line (e.g., n = 4). This counter shows the number of measured values that lie within the tolerance range.
- Optional automatic printout of weight value when it is within the control range at stability

After an automatic printout, the balance is blocked. Before you can generate the next printout, you must unblock the balance by unloading it (weight must be under 30% of the target) or by placing a load on the balance (bringing the weight up to at least 170% of the target).

 Press CF to delete the initialization parameters and end the Checkweighing program

### **Factory Settings**

Activation of port lines: Within checkweishing range

Type of checkweighing input: Tarset, minimum, maximum weisht

Weight display mode: Absolute value

Automatic printout of OK values: No

### **Soft Key Functions**

Param.	Begin input of target and
Show	tolerance values Display target and toler-
LLHH	ance values in turn during checkweighing Toggle to control display ("LL" for too light and
Diff.	"HH" for too heavy) Display difference between current value and target
Net	Display net weight

## Preparation

The checkweighing program often requires a target value for comparison with the current value. This target has a tolerance range, which is defined by absolute weight values. The tolerance range is defined as either an absolute value or a percentage with upper and lower limits. Percentage values can be symmetric or asymmetric to the target value. These values can be entered either by storing weights on the balance or by key input.

There are four control lines, called data output port lines, which are activated as follows: (see also the diagram at the right):


- lighter
- equal
- heavier
- set

The control range spans 30% to 170% of the target value. You can configure this parameter in the Setup menu (App: Application 2: Checkweighing: Activation of port lines:) to select whether the control lines are:


- activated within the control range
- always on
- activated at stability within the control range
- activated at stability

This makes it possible, for example, to connect a simple indicator for the weighing results (e.g., three different colors, one each for the weighing results: too light, O.K., too heavy). Response of Control Lines During Checkweighing

- Configurations:
- always on
- activated at stability



- Configurations:
- activated within control range
- activated at stability within control range



### **Output port specifications**

- When not in use, the voltage level is high: >2.4 V/+2 mA.
- When activated, the voltage level is low: <0.4 V/-2 mA.
- $\triangle$  The output ports are not protected against short circuits!

### Preparation

- Turn on the balance: Press
- > Sartorius logo is displayed
- Select the Checkweighing application in the Setup menu: Press Setup
- Select Application 2: Press the  $\vee$  soft key and then the  $\geq$  soft key
- Select the Application parameters: press the v soft key 2 x, then the > soft key
- Select Application 2 (control functions): Press the v soft key, then the > soft ke
- Select Checkweishins: press the ∧ or ∨ soft key, repeatedly, if necessary
- Confirm Checkweighing: press the > soft key

Checkweighing	- Activation	_	Within checkweighing range Always on Stability and checkweighing range At stability Stability + checkweighing range -> once
-	Type of	- 0 -	Target, min, max weight Min, max weight Target, min in %, max in %
_	Weight display mode	- 0 -	Absolute value Difference from the target
L	Automatic printout	- - 0	Yes No

o = factory setting

see also the "Application Parameters (Overview)" in the chapter entitled "Configuration"

• Save settings and exit the Setup menu: press the < < soft key

## Additional Functions

In addition to the functions for:

- alphanumeric input, (not during initialization),
- taring (not during alphanumeric input)
- printing, you can also access the following functions from this application:
  - Calibration/Adjustment
- Press the Cal soft key
- > See "Calibration/Adjustment" for further instructions
- Press (1)
- > See the section on the corresponding application program for further instructions
- Setup (setting parameters)Press Setup
- > See "Configuration" for further instructions
- Turning Off the Balance
- Press 🕼
- > The balance shuts off
- > The display goes blank

# **Practical Example**

Checkweighing samples of 170 g, with an allowable tolerance of -5 g and +10 g. Printout of upper and lower tolerance limits. Weighed values are printed out automatically when stability is reached and weight value is within the control range.

Settings (changes in the factory settings required for this example):

Setup: App: Application 2: Checkweighing: Automatic printout of OK values: Yes

Step	Key (or instruction)	Display/Output
<ol> <li>Turn on the balance and configure the settings as indicated above</li> </ol>	CU	
2. Delete previous setting if necessary	CF	
3. Prepare a container for the samples	Place empty container on the balance	Max4200 s d= 0.01s 0% <b>m</b> m <b>2 10.0 0 9</b> + <b>2 10.0 0 9</b> CHECKWEIGH: Initialize Cal Param. Start
4. Tare the balance	Tare	Max4200 9 d= 0.019 0% 100% CHECKWEIGH: Initialize Cal Param. Start
5. Enter initialization values	Param. soft key	CHECKWEIGH:     0.00 a A       Tarset:     Setp= +     0.00 a       Minimum:     Min = +     0.00 a       Maximum:     Max = +     0.00 a       <
6. Enter target value via the balance (here: 170 g)	Place ideal sample in container	CHECKWEIGH:     17000 %       Target:     Setp= +     0.00 %       Minimum:     Min = +     0.00 %       Maximum:     Max = +     0.00 %       <
7. Store target value and unload balance	✓ soft key Remove ideal sample from balance	CHECKWEIGH:     0.00 %       Target:     Setp= + 170.00 %       Minimum:     Min = + 0.00 %       Maximum:     Max = + 0.00 %       <
8. Enter value for lower limit (170 g – 5 g) and store	$ \underbrace{1}_{4} \underbrace{6}_{5} \underbrace{5}_{5} $	CHECKWEIGH:     0.00 ± Å.       Tarset:     Setp= + 170.00 ±       Minimum:     Min = + 165.00 ±       Maximum:     Max = + 0.00 ±       <

Ste	р	Key (or instruction)	Display/Output
9.	Enter value for upper limit (170 g + 10 g) and store	1 8 0 J soft key	Max4200 g → → → → → → → → → → → → → → → → → → →
10.	Weigh sample (in this case 169.48 g)	Place sample in container	Max4200 s d= 0.01s d= 0.01s f f f CHCKW.: n = 1 Set∞= +170.00 s Cal Param.Net Show N + 169.48 g
	If the weight value had been too low, the display would have shown the following:		Max4200 9 d= 0.019
11.	In this case, switch to net value display (here: 163.28 g)	Net soft key	Max4200 a d= 0.01a Max4200 a d= 0.01a H H H H H H H H H H H H H H H H H H H

12. Weigh next sample (if any)

Place sample in container

# Time-Controlled Functions

### Purpose

With this application program, you can configure the balance to perform certain functions (e.g., automatic printout of values, store value in totalization memory) at a given time or after a set interval.

You can use the "Time-Controlled Functions" application in combination with a program chosen from Application 1 (e.g., counting, weighing in percent) and one from Application 3 (e.g., totalizing, formulation).

### **Available Features**

- Time-controlled activation of balance functions:
- one time only, at a given time

(Setting= is displayed in the text line)

- repeatedly, at given intervals

(Interval = is displayed in the text line before the function is started. and Repeat = is displayed after the

function is started)

Functions that can be time-controlled include:

- Acoustic signal
- Lock in readout
- Automatic printout of values
- Store values for totalizing, formulation or statistics
- Print time in addition to weight value
- Store value independent of stability
- Tare the balance after printout of weight values
- Press the corresponding soft key to cancel time-controlled functions

Factory Settings Function after time interval: Automatic printout of	Soft Key Fu Stop	nctions Stop the application
values	Quit	Confirm performed function (e.g., "Lock in readout" or
Automatic function restart: <b>On</b>		"Beep")
Storage mode: Without stability	Interv	Store input interval for time- controlled functions
Print then tare: On	Set.	Store input time for one-time performance of function

### Preparation

- Turn on the balance: Press (10)
- Sartorius logo is displayed
- Select the "Time-controlled functions" application in the Setup menu: Press Setup
- Select the Application parameters: press the v key 2 x, then the > soft key
- Select Application 2 (control functions): press the  $\lor$  soft key, then the > soft key
- Select Time-controlled functions: press the ∧ or ∨ soft key
- Confirm Time-controlled functions: press the > soft key

Time-controlled — functions	Function after time interval		Beep Lock in readout Automatic printout of values Store value in applicat. 3 memory
_	Automatic Gunction restart	0	On Off
-			Without stability After stability After higher stability
L	Print then tare	0	Off On

o = factory setting

see also the "Application Parameters (Overview)" in the chapter entitled "Configuration'

Save settings and exit the Setup menu: press the << soft key

### Print Net Values without Printout of Time

Select the Setup menu:

Setup: Printout: Application-defined output: Auto print upon initialization: Off

### **Practical Example**

Document the amount of evaporation of a sample with defined surface, temperature and air pressure at preset intervals of 1 minute, 30 seconds.

Settings (changes in the factory settings required for this example):

Setup: App: Application 2: Time-controlled functions Setup: Balance functions: Taring: Without stability Setup: Print in weighing mode: Manual/auto print mode: Manual without stability

Step	Key (or instruction)	Display/Output
1. Turn on the balance and configure the settings as indicated above		
2. Delete stored values if necessary	CF	
3. Place container with sample on the balance and tare	Tare	Max4200 9 d= 0.019 0%
<ul><li>4. Enter time interval: 1 minute,</li><li>30 seconds</li></ul>		Max4200 9 d= 0.019 0% mmminumi
5. Store time interval	Interv soft key	Max4200 9 d= 0.019 0%
6. Begin documentation (Time remaining until the next printout is displayed in the text line)	Start soft key	Max4200 9 d= 0.019 0%
Printout of evaporation amount every 1 <sup>1</sup> / <sub>2</sub> minutes		Time: 15:19:50 N – 0.37 g Time: 15:21:20 N – 0.33 g
7. Stop the documentation procedure	Stop soft key	Time: 15:22:50 N – 0.30 g Time: 15:24:20 N – 0.40 g

# Totalizing $\Sigma$

### Purpose

This application program acts as a cumulative memory function.

You can use the "Totalizing" application in combination with a program chosen from Application 1 (e.g., counting, weighing in percent) and one from Application 2 (checkweighing, timecontrolled functions) as well as with the extra functions.

### **Available Features**

- Totalization of weight values and calculated values
- Optional configuration in the Setup menu for simultaneous storage of net and calculated values
- Optional configuration in the Setup menu for loading weight values and calculated values either from Application 1 (e.g., counting, weighing in percent) or from Application 2 (checkweighing, time-controlled functions)
- Totalization memory for up to 65535 values
- Simultaneous display in the text line of transaction counter and, e.g., the current total
- Optional configuration in the Setup menu for having the balance tare automatically after a value is stored in the totalization memory, if no preset tare has been entered
- Manual input of the number of individual weighing operations (target no. of operation nDef). Result printed and memory cleared after printout of nDef.
- Optional configuration in the Setup menu to add the current weight, with display accuracy, to the current total by pressing the M+ soft key and generate a printout of the result
- Optional configuration in the Setup menu for stability-dependent storage of the measured value: Stability range

- Optional automatic storage of measured values

Storage of measured value is indicated by  $\Rightarrow \dot{\bullet}$ .

**+ + indicates that you can place a load on the balance.** 

- Minimum load threshold for automatic storage
- Press the M soft key to delete the last value added to the totalization memory. The transaction counter value is reduced by one and a printout is generated.
- Press the MR soft key for information about number of transactions and the current total. By configuring the Setup menu, you can define whether the information is displayed and printed, or only printed, and whether the information comprises an intermediate or final evaluation (see the example)
- In the Info window you can choose which value is displayed in the text line during weighing
- Printout of the end result independent of which program is configured for Application 1 or Application 2. Configure the Setup menu to define which values are included on the printout (Printout of individual components)
- Press the key identified by MR (soft key label) for a printout of an intermediate evaluation after each addition or a final evaluation
- If you end the totalization process by pressing CF without having first pressed the MR soft key for a printout, a final evaluation is printed when you press CF
- Optional configuration in the Setup menu to clear the totalization memory and reset the transaction counter by pressing (F) or after an evaluation is printed out
- Totalization data and transaction counter data are stored in non-volatile memory
- Continue totalization after turning the balance off and back on

**Factory Settings** Automatic storage: **O f f** 

Minimum load for automatic storage: 20 digits

Source of data for auto storage: Application 1

Evaluated values: Net

Evaluation mode, MR key function: Intermediate evaluation, print

M+/M- function, then tare: O f f

Printout of individual components: On

Balance functions: Stability range: 2 disits

Printout: Application-defined output: Print on request, then tare: **0 f f** 

### Soft Key Functions

M٠

+	Add weight values or applica- tion values to the total in the totalization memory. The component or transaction counter value increases by one each time you press this hear
	key.

 M - Delete the last value added to memory. The transaction counter value decreases by 1. You cannot delete previous values by repeatedly pressing this key.

MRPrint or display an inter-<br/>mediate or final evaluation

**nDef** Store the input number of components


### Printout for Totalizing

The transaction or component counter is printed in front of each measured value (weight). When an intermediate or final evaluation is printed out, all results up to this point are included.

n		5	
Total	+	151.67	g

### Preparation

- Turn on the balance: Press
- > Sartorius logo is displayed
- Select the Totalizing application program in the Setup menu: Press Setup
- Anwendungsparameter wählen: 2 × Softkey ∨, Softkey > drücken
- Select the Application parameters: press the v soft key 2 x, then the > soft key
- Select Totalizing: press the A or the V soft key
- Select Totalizing: press the > soft key



# Additional Functions In addition to the functions for:

- alphanumeric input,
- taring (not during alphanumeric input),
- printing,
  - you can also access the following functions from this application:
  - Calibration/Adjustment
- Press the Cal soft key
- > See "Calibration/Adjustment" for further instructions
- Toggling to Another Application ● Press ⊕
- > See the section on the corresponding application program for further instructions
- Setup (setting parameters)Press Setup
- > See "Configuration" for further instructions
- Turning Off the Balance
- Press 🗤
- > The balance shuts off

o = factory setting

see also the "Application Parameters (Overview)" in the chapter entitled "Configuration"

• Save settings and exit the Setup menu: press the << soft key

**Practical Example** Totalize counted pieces

Settings (changes in the factory settings required for this example):

Setup: App: Application 1: Counting Setup: App: Application 3: Totalizing: Evaluated values: Net + calculated Setup: App: Application 3: Totalizing: Evaluation mode, MR function: Final evaluation, display + print

Step	Key (or instruction)	Display/Output
1. Turn on the balance and configure the settings as indicated above	(I/O)	
2. Delete old totalization data, if necessary	CF	
3. Tare the balance	Tare	Max4200 9 d= 0.019 0% 100% A 100% A TOTAL: Start with M+ Cal M+
4. Toggle to Application 1: Counting	(J)	Max4200 9 d= 0.019 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0% 0
5. Place the displayed number of parts on the balance (here: 10 pcs)	Place parts to be counted on the balance	Max4200 s d= 0.01s 0% mmm = <b>352.899</b> ∑ COUNTING: nRef = 10 pcs Cal
6. Initialize the Counting application	Start soft key	Max4200 9 d= 0.019 0% mmm <sup>a</sup> = • • • • • • • • • • • • • • • • • •
		nRef 10 pcs wRef 35.28900 g
7. Remove the reference sample quantity and toggle to Totalizing	Unload the balance	Max4200 9 d= 0.019 0% 100% & + DPCS TOTAL: Start with M+ Cal M+
8. Place a number of parts on the balance (here: 50 pcs)	Place parts on the balance	Max4200 9 d= 0.019 0% ####################################

Step	Key (or instruction)	Display/Output
9. Store piece count	M+ soft key	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
10. Unload the balance	Remove parts from the balance	
11. Place another load of parts on the balance (e.g., 60 pcs)	Place parts on the balance	Max4200 9 d= 0.019 0% HomeBoomBoomBoomBoomBoomBoomBoomBoomBoomB
12. Add piece count to stored total	M+ soft key	Max4200 9 d= 0.019 0%
		n + 2 N + 2117.34 g Qnt + 60 pcs
13. Repeat steps 10 and 11 as required		
<ul> <li>14. Display final evaluation ("Info" window) (here: 5 weighing operations; total weight: 8751.67 g; total quantity: 248 The o indicates which value is displayed in the text line; you can change this selection</li> </ul>	MR soft key )	TOTAL: oNet: n = 5 Net: Σ = + 8751.67 9 Calculated: n = 5 Calculated: Σ = + 248 pcs << v J
15. Print final evaluation	Ē	n 5 Total + 8751.67 g Total + 248 pcs

16.01.1997 11:16

# Formulation 🗄

### Purpose

With this application program you can add weight values and calculated values to a totalization memory as components of a formula.

You can use the "Formulation" application in combination with a program chosen from Application 1 (except Recalculation) and one from Application 2 (checkweighing, timecontrolled functions) as well as with the extra functions.

### **Available Features**

- Totalization of weight values and calculated values

- Weigh in different components to a total amount defined by pressing the Nom soft key and entering the value through the numeric keys
- Simultaneous storage of net and calculated values
- Optional configuration in the Setup menu for loading weight values and calculated values either from Application 1 (e.g., counting, weighing in percent) or from Application 2 (checkweighing, time-controlled functions)
- Totalization memory for up to 65535 values
- Transaction counter and current total displayed in the text line
- Balance tared after a value is stored
- Manual input of the number of individual weighing operations (target no. of operation nDef). Result printed and memory cleared after printout of nDef.
- Optional configuration in the Setup menu to add the current weight, with display accuracy, to the current total by pressing the M+ soft key and generating a printout of the result
- Optional configuration in the Setup menu for stability-dependent storage of the measured value: Stability range
- Optional automatic storage of measured values

Storage of measured value is indicated by  $\div \div$ .

★↓ indicates that you can place a load on the balance.

- Minimum load threshold for automatic storage
- Press the M soft key to delete the last value added to the totalization memory. The transaction counter value is reduced by one and a printout is generated.
- Printout of an evaluation of results, depending on the Application 1 or Application 2 parameters. Configure the Setup menu to define the information included on this printout.
- Press the key identified by MR (soft key) for a printout of an intermediate evaluation after each addition or a final evaluation
- A final evaluation is printed when the formulation routine is ended by pressing CF, if no final evaluation was
  - generated by pressing MR
- Optional configuration in the Setup menu to clear the totalization memory and reset the transaction counter by pressing CF or after an evaluation is printed out
- Totalization data and transaction counter data are stored in non-volatile memory
- Continue formulation after turning the balance off and back on

**Factory Settings** Automatic storage: 0 f f

Minimum load for automatic storage: 20 disits

Source of data for auto storage: Application 1

Evaluated values: Net

Evaluation mode, MR key function: Intermediate evaluation, print

Printout of individual components: On

Balance functions: Stability range: 2 disits

Printout: Application-defined output: Print on request, then tare: **0 f f** 

### **Soft Key Functions**

M+ Add weight values or application values to the total in the totalization memory. The component or transaction counter value increases by one each time you press this key.

M- Delete the last value added to memory. The transaction counter value decreases by 1. You cannot delete previous values by repeatedly pressing this key.

- **MR** Print or display an inter-mediate or final evaluation
- **nDef** Store the input number of component
- **Nom** Press to enter target component weight using the numeric keys

### Printout of Formulation Report

When an intermediate or final evaluation is printed out, all results up to this point are included.

Comp2 + 42.38 g Tot.cp+184.89 g

Comp2: Weight of the 2nd component Tot.cp: Total of all components

### Preparation

- Turn on the balance: Press
- > Sartorius logo is displayed
- Select the Formulation application program in the Setup menu: Press (Setup)
- Select Application parameters: press the v soft key 2 x, then the > soft key once
- Select Application 3 (data records): press the v soft key 2 x, then the > soft key once
- Select Formulation: press the ^ or the v soft key
- Select Formulation: press the > soft key

Formulation		Automatic o storage	Off On, first value at stability
		o	None 10 digits 20 digits 50 digits 100 digits 200 digits 500 digits 1000 digits
	-	Source of data for o auto storage	Application 1 Application 2
	_	Evaluated values o	Net Calculated Net + calculated
	-	Evaluation mode, o MR function	Intermediate evaluation, print Final evaluation, print
	L	Printout of individual $\Box_0$	No Yes

### **Additional Functions**

- In addition to the functions for:
- alphanumeric input,
- taring (not during alphanumeric input),
- printing,

you can also access the following functions from this application:

- Calibration/Adjustment
   Press the Cal soft key
- > See "Calibration/Adjustment" for further instructions
- Toggling to Another Application
- Press 💿
- > See the section on the corresponding application program for further instructions
  - Setup (setting parameters)
- Press (Setup)
- > See "Configuration" for further instructions
- Turning Off the Balance • Press
- > The balance shuts off

o = factory setting

see also the "Application Parameters (Overview)" in the chapter entitled "Configuration"

Save settings and exit the Setup menu: press the << soft key</p>

92

**Practical Example** Weighing in Components

Settings (changes in the factory settings required for this example): Setup: App: Application 3: Formulation: Automatic storage: On, first value at stability Setup: App: Application 3: Formulation: Minimum load for automatic storage: 100 digits Setup: App: Application 3: Formulation: Evaluation mode, MR function: Final evaluation, print

Ste	р	Key (or instruction)	Display/Output
1.	Turn on the balance and configure the settings as indicated above	CU	
2.	Delete old formulation data, if necessary	CF	
3.	Tare the balance	Tare	Max6200 9 d= 0.019 0%
4.	Place the empty container on the balance (here: 180.59 g)	Place load on the balance	Max6200 9 d= 0.019 0% 180.599 FORM.: Start with M+ Cal M+
5.	Tare the balance	Tare	Max6200 9 d= 0.019 0% mm 100% FORM.: Start with M+ Cal M+
6.	Weigh in the first component (here: 42.88 g)	Place components in container	Max6200 9 d= 0.019 0% mm + <b>42.889</b> FORM.: Start with M+ + Cal M+
7.	Store components in the formulation memory Balance is tared automatically	M+ soft key	Max6200 9 d= 0.019 0% mm = 100% FORM.: n=1 Σ= +42.88 9 +4 Cal MR M- M+
	Components are printed out automatically		 16.01.1997 14:04 Comp1 + 42.88 g
8.	Weigh in the next component (here: 50.80 g) Components are stored in the totalization memory at stability and printed out	Place components in container	Comp2 + 50.80 g
	Balance is tared automatically		Max6200 9 d= 0.019 0%
9.	Repeat step 7 as required		LLL         NET2           FORM.:         n=2         Σ=         +93.68         9         ↓↓           Ca1         MR         M-         M+
10.	Print final evaluation (here: with total weight of all components: 212.43 g)	MR soft key	n 2 Tot.cp+ 212.43 g 16.01.1997 14:10
11.	Delete old formulation data, if necessary	CF	

# Statistics x

### Purpose

With this application program you can have weight values and calculated values totalized and statistically evaluated.

The values determined for the evaluation are:

- average
- standard deviation
- variation coefficient
- sum of all values
- lowest value (minimum)
- highest value (maximum)
- difference between the minimum and the maximum

You can use the "Statistics" application in combination with a program chosen from Application 1 (e.g., counting, weighing in percent) and one from Application 2 (checkweighing, timecontrolled functions) as well as with the extra functions.

### **Available Features**

- Storage of weight values and calculated values
- Simultaneous storage of net and calculated values
- Optional configuration in the Setup menu for loading weight values and calculated values either from Application 1 (e.g., counting, weighing in percent) or from Application 2 (checkweighing, time-controlled functions)
- Totalization memory for up to 65535 values
- Simultaneous display in the text line of transaction counter and, e.g., the current total
- Optional configuration in the Setup menu for having the balance tare automatically after a value is stored in the totalization memory
- Manual input of the number of individual weighing operations (target no. of operation nDef). Result printed and memory cleared after printout of nDef.

- Optional configuration in the Setup menu to add the current weight, with display accuracy, to the current total by pressing the M+ soft key and generate a printout of the result
- Optional configuration in the Setup menu for stability-dependent storage of the measured value: Balance functions: Stability range
- Optional automatic storage of measured values

Storage of measured value is indicated by  $\Rightarrow \Leftarrow$ .  $\Rightarrow \Rightarrow$  indicates that you can place a load

• • indicates that you can place a load on the balance.

- Minimum load threshold for automatic storage
- Press the M soft key to delete the last value added to the totalization memory. The transaction counter value is reduced by one and a printout is generated.
- Press the MR: soft key for information about number of transactions and the current total. By configuring the Setup menu, you can define whether the information is displayed and printed, or only printed, and whether the information comprises an intermediate or final evaluation (see the example)
- In the Info window you can use the ♥,
   ↓ soft keys to choose which value is displayed in the text line during weighing
- Printout of the end result depending on the Application 1 or Application 2 parameters. Configure the Setup menu to define which values are included on the printout (Printout of individual components)
- Press MR for a printout of an intermediate evaluation after each addition or a final evaluation
- A final evaluation is printed when the statistics routine is ended by pressing CF, if no final evaluation was generated by pressing MR

- Optional configuration in the Setup menu to clear the totalization memory and reset the transaction counter by pressing (CF) or after an evaluation is printed out
- Totalization data and transaction counter data are stored in non-volatile memory
- Continue totalization after turning the balance off and back on

### Factory Settings Automatic storage: 0 f f

20 digits

Minimum load for automatic storage:

Source of data for auto storage: Application 1

Evaluated values: Net

Evaluation mode, MR key function: Intermediate evaluation, print

M+/M- function, then tare: O f f

Printout of individual components:  $\mathbf{O} \cdot \mathbf{f} \cdot \mathbf{f}$ 

Balance function: Stability range: 2 disits

Printout: Application-defined output: Print on request, then tare: **0 f f** 

# **Soft Key Functions**

- M+ Add weight values or application values to the total in the totalization memory. The component or transaction counter value increases by one each time you press this key.
- M Delete the last value added to memory. The transaction counter value decreases by 1. You cannot delete previous values by repeatedly pressing this key.
- MRPrint or display an inter-medi-<br/>ate or final evaluation
- **nDef** Store the input number of components

### Preparation

- Turn on the balance: Press
- > Sartorius logo is displayed
- Select the Statistics application program in the Setup menu: Press Setup
- Select Application parameters: press the v soft key 2 x, then the > soft key once
- Select Application 3 (data records): press the v soft key 2 x, then the > soft key once
- Select Statistics: press the ^ or the v soft key
- Select Statistics: press the > soft key

Statistics	Automatic o storage	Off On, first value at stability On, last value at stability On, value bet. 70 – 130% at stabil.
	— o —	None 10 digits 20 digits 50 digits 100 digits 200 digits 500 digits 1000 digits
_	Source of data for o auto storage	Application 1 Application 2
-	Evaluated values o	Net Calculated Net + calculated
_	Evaluation mode, o MR function	Intermediate evaluation, print Final evaluation, print Intermediate evaluation, display+print Final evaluation, display+print
_	M+/M– function, o then tare	Off On
	Printout of individual $\{o}$	No Yes

o = factory setting

see also the "Application Parameters (Overview)" in the chapter entitled "Configuration"

• Save settings and exit the Setup menu: press the < < soft key

# **Additional Functions**

In addition to the functions for:

- alphanumeric input,
- taring (not during alphanumeric input),
- printing, you can also access the following functions from this application:
- Calibration/Adjustment
  Press the Cal soft key
- > See "Calibration/Adjustment" for further instructions
- Toggling to Another Application ● Press (ഈ)
- > See the section on the corresponding application program for further instructions
- Setup (setting parameters)Press Setup
- > See "Configuration" for further instructions
- Press (₩)
- > The balance shuts off

**Practical Example** Totalize counted pieces and print out statistics

Settings (changes in the factory settings required for this example): Setup: App: Application 1: Counting: Average piece weight updating: Manual Setup: App: Application 3: Statistics: Evaluated values: Calculated Setup: App: Application 3: Statistics: Evaluation mode, MR function: Final evaluation, display + print

Step	Key (or instruction)	Display/Output
1. Turn on the balance and configure the settings as indicated above	(U)	
2. Delete old statistics data, if necessary	30	Max4200 9 d= 0.019
3. Tare the balance	Tare	Max4200 9 d= 0.019 0%
4. Toggle to Application 1: Counting		Max4200 9 d= 0.019 0% 00% 00% 00% 00% 00% 00% 00% 00% 00%
5. Place the displayed number of parts on the balance (here: 10 pcs)	Place parts to be counted on the balance	Max4200 9 d= 0.019 0% d= 0.019 100% d= 100% d= 100% d= 0.019 100% d= 100% d= 0.019 100% d= 0.019 10% d= 0.01910% d= 0
6. Initialize the Counting application	Start soft key	Ma×4200 9 d= 0.019 0% d= 0.019 100% d= 100% d= 0.019 100% d= 100% d= 0.019 100% d= 100% d= 0.019 100% d= 0.019 100% d= 0.019 100% d= 0.019
		wRef 10.62600 g
7. Remove the reference sample quantity and toggle to Statistics	Unload the balance	Max4200 9 d= 0.019 0% ■ 100% <b>D PCS</b> ■ STATI.: Start with M+ Cal   M+
8. Place a number of parts on the balance (here: 35 pcs)	Place parts on the balance	Max4200 9 d= 0.019 0% mmm

Step	Key (or instruction)	Display/Output
9. Store piece count	M+ soft key	Max4200 9 0% mmm <sup>™</sup> • • • • • • • • • • • • • • • • • • •
10. Unload the balance	Remove parts from the balance	
11. Place another load of parts on the balance (e.g., 29 pcs)	Place parts on the balance	Max4200 9 d= 0.019 0%
12. Add piece count to stored total	M+ soft key	Max4200 9 0% mmm <sup>2</sup> • • • • • • • • • • • • • • • • • • •
13. Repeat steps 11 and 12 as required		
<ul> <li>14. Display final evaluation ("Info" windo (here: 5 weighing operations; total quantity: 165)</li> <li>The o indicates which value is display in the text line; you can change this s</li> </ul>	yed	STATI.:     5       Calculated: n     5       Calculated: x     +     33.0 pcs       Calculated: s     +     3.2 pcs       Calculated: s     +     4.2 pcs       Calculated: s     +     165 pcs       oCalculated: Σ     +     165 pcs       <
15. Print final evaluation	Ē	n 5 Avg. + 33.0 pcs s + 3.2 pcs srel + 9.70 % Total + 165 pcs Min + 29 pcs Max + 37 pcs Diff + 8 pcs 16.01.1997 11:16

# **Additional Functions**

# Second Tare Memory (Preset Tare)

## Purpose

With this function you can store the weight currently on the balance as a tare weight, or use the numeric keys to enter a number for a preset tare weight.

You can use "Extra Functions" in combination with a program from Application 1 (e.g., counting, weighing in percent), one from Application 2 (checkweighing, time-controlled functions) and one from Application 3 (totalizing, formulation, statistics) as well as with the extra functions.

### **Available Features**

- Store a weight on the balance in the second tare memory (without numeric input)
- Store a numeric value in the second tare memory (input using the numeric keys)
- Label a net value as NET1 when there is a value stored in the second tare
- You can assign this function to the fourth or fifth soft key (from the right), i.e. F4 or F5

The soft key designation for this function is: PT1 < T1

- Optional configuration in the Setup menu for storing the current weight readout as the container tare weight. Any load subsequently placed on the scale that is more than 70% of the tare weight is automatically recognized as a container and the scale is tared automatically.
- Automatic printout when a value is stored or input (see "Configuration")
- Press (F) to delete the (preset) tare value

Factory Settings Container tare weight: No

Automatic printout: Off

## **Soft Key Functions**

**PT1**/**T1** Store weight as tare value

**PT1** Save tare weight entered using the numeric keys

Printout of the Data in the 2nd Tare Memory The printout shows either


- Net value N1
- Tare weight T1, or
- Manually entered tare value PT1

N 1	163.48	g
т1	138.73	g
PT1	150.00	g

- N1: Net weight /value) when a weight is stored in the tare memeory
- T1: Tare weight
- PT1: Preset tare value entered using the numeric keys

### Preparation

- Turn on the balance: Press
- > Sartorius logo is displayed
- Select Extra function (F4) or Extra function (F5) in the Setup menu: Press Setup
- Select Application parameters: press the v soft key 2 x, then the > soft key once
- Select Extra function (F4) or Extra function (F5): press the v soft key 3 x, then press the > soft key once
- Select 2nd tare memory
- Confirm 2nd tare memory



see also "Application Parameters (Overview)" in the chapter entitled "Configuration"

• Save settings and exit the Setup menu: press the << soft key

### Second Tare Memory in Legal Metrology

- Press the (i) PT1 soft key to enter information about the tare value using the number keys.
- The PT1 tare value is printed out with the net value.

**Practical Example** Determine the Contents of Bottles: Bottle weight = 400 g.

Settings (changes in the factory settings required for this example):

Setup: App: Extra function(F4): 2nd tare memory: Automatic printout: Tare/preset tare

Step	Key (or instruction)	Display/Output
1. If necessary: turn on the balance and enter the settings given above		
2. Enter bottle weight (here: 400 g)		Max4200 9 d= 0.019 0%
3. Store tare value	PT1 soft key	Max4200 9 d= 0.019 0%
		PT1 + 400.00 g
<ul><li>4. Determine content weight of bottles (here: contents = 650 g)</li></ul>	Place filled bottles on the balance	Max4200 9 07 mmmmmmm <b>+ 650.009</b> NET1 Cal   PT1/T1

# Individual Identification Codes (ID)

### Purpose

With this function you can assign identifiers to values for documentation and printouts.

You can use this extra function in combination with a program from Application 1 (e.g., counting, weighing in percent), one from Application 2 (checkweighing, time-controlled functions) and one from Application 3 (totalizing, formulation, statistics) as well as with the other extra functions.

### **Available Features**

- Store up to 4 IDs; these can be stored, changed or deleted individually.
- Each ID consists of a name and a value; both can be defined by the user.
- ID designations are configured in the Setup: Input menu.
- Each ID designation can have up to 20 characters; when you enter the value later, however, no more than 15 characters of the designation are displayed.
- The ID values are entered while the application program is active; press the I D soft key to toggle to the ID input mode.
- Each ID value can have up to 20 characters.
- Access 1 of the 4 IDs directly using the numeric keys. The other three can only be accessed by pressing the **I D** soft key to toggle to the identifier input mode.

- You can assign this function to the fourth or fifth soft key (from the right), i.e. F4 or F5.
- You can configure when the ID is included on the printout (see "Preparation," next page).
- You can configure the position of IDs on the individual or total printout.
- The designation is printed flush left; the value flush right. If the name and value together are too long for one line, the data is printed on two lines.
- Optional configuration in the Setup menu to delete a single character when entering an identifier by pressing CF.
   Setup: Device: Keys: CF function for input: Delete last character
- Press the Delete soft key to delete an ID

Factory Settings for ID Designations ID1: I D 1 ID2: I D 2

1D2: **ID2** 1D3: **ID3** 1D4: **ID4** 

Factory Settings for ID Values No values set

Factory Settings for Other Parameters Printout: Each time the print key is pressed

# Soft Key Functions

ID Toggle to "Identification codes" menu

Delete Delete input of selected ID

### Preparation

- Turn on the balance: Press
- > Sartorius logo is displayed
- Select Extra function (F4) or Extra function (F5) in the Setup menu: Press Setup
- Select Application parameters: press the v soft key 2 x, then the > soft key once
- Select Extra function(F4) or Extra function(F5): press the v soft key 3 × (or 4 ×), then the > soft key once
- Select Identification codes
- Confirm Identification codes

Identification —— Printout ——— codes Automatic, if configured
 Once after pressing print, if configured
 o Each time the print key is pressed
 Once for M+ function (app.3 memory)

o = factory setting

see also "Application Parameters (Overview)" in the chapter entitled "Configuration"

- Save settings for the printout: press the < soft key  $4 \times$
- Enter ID name: Select "Printout": press the ∨ soft key, then the ⊃ soft key
- Select "Identification #": press the ∨ soft key 5 ×, then the ⊃ soft key once
- Select ID1
- Enter name for **ID1** and confirm: use the numeric keys for numbers and/or the soft keys to enter letters
- Enter names for ID2, ID3 and ID4, if desired
- Save settings and exit the Setup menu: press the < < soft key</p>

**Example** See next page

# Example

Include company address and sample lot number on the printout. Each ID line begins with the name. Print this ID for each net value.

Settings (changes in the factory settings required for this example):

Setup: Application parameters: Extra function (F4): Identification codes Setup: Input: ID1: Company Setup: Input: ID2: Location Setup: Input: ID3: Street Setup: Input: ID4: Lot

Step	Press key(s) (or follow instructions)	Display/Output
1. If necessary, turn on the balance		
2. Select "Extra Function (F4)" in the Setup menu	(Setup) ♥ soft key2 ×, then > soft key once ♥ soft key 3 ×, then > soft key once	SETUP APPLICATION EXT.FCT.F4 OOff 2nd tare memory Identification codes Man. store in app.3 memory (M+) Product data memory << < < <
3. Select "Identification codes"	♀ or ∧ soft key; repeatedly, if necessary	SETUP     APPLICATION     EXT.FCT.F4       oOff     2nd     tare memory       Identification     codes       Man.     store     in       Product     data     memory       <
<ol> <li>Confirm "Identification codes" and exit this menu item</li> </ol>	⊃ soft key; then <soft 3="" key="" td="" ×<=""><td>APPLICATION EXT.FCT.F4 IDENTIFIER Printout</td></soft>	APPLICATION EXT.FCT.F4 IDENTIFIER Printout
5. Select ID1 (Printout: Identifier)	$\checkmark$ or > soft key $\lor$ soft key 5 ×, then > soft key, then $\lor$ soft key	SETUP         PRINTOUT         IDENTIFIER           Lot (L ID):         ID1:         ID1           ID1:         ID2:         ID2           ID3:         ID3         ID3           ID4:         ID4         ID4
6. Enter name for ID 1	(ABC) see also page 37	SETUP PRINTOUT IDENTIFIER

6. Enter name for ID 1 (in this case: COMPANY and confirm (ABC) ... see also page 37 (ABC), ↓ soft key

SETUP	PRINTOUT	IDENTIFIER
Lot (L ID):		
ID1:		COMPANY
ID2:		ID2
ID3:		ID3
ID4:		ID4
ABCDEF	IMNOPOR STUV	WX YZ/=-? :#*"&

Step		Key (or instruction) Display/Output
7. Repeat steps 5 and 6 for: ID2: LOCATION ID3: STREET ID4: LOT		SETUP     INPUT       ID1:     COMPANY       ID2:     LOCATION       ID3:     STREET       ID4:     LOT       Adj. time1:     Adj. time1
8. Save settings, exit the Setup menu and select input mode for ID values	<ul><li>&lt; soft key twice</li><li>I D soft key</li></ul>	ID: COMPANY LOCATION STREET LOT <<  Delete  v J
9. Enter name of company (here: Sartorius)	(ABC) See also page 37	ID: COMPANY SARTORIUS LOCATION STREET LOT <<  Delete  V J
10. Confirm	(ABC), +J soft key	ID: COMPANY SARTORIUS LOCATION STREET LOT <<  Delete  ^ v J
11. Repeat steps 9 and 10 for LOCATION: GOETTINGEN STREET: WEENDER LANDSTRASSE LOT: 15		ID: COMPANY SARTORIUS LOCATION GOETTINGEN STREET WEENDER LANDSTRASSE LOT 15 <<  Delete  ^ J
12. Place the first sample on the balance (here: 210.53 g)	Place load on balance	Max 6200 a 0% d= 0.01a + 210.539 Cal ID ID
13. Print weight value (if desired, perform further weighing operations and print results)	Ē	COMPANY SARTORIUS LOCATION GOETTINGEN STREET WEENDER LANDSTRASSE LOT 15 N + 210.53 g
14. When weighing is completed, delete each ID individually	ID soft key Delete soft key 4 times	ID: COMPANY SARTORIUS LOCATION GOETTINGEN STREET WEENDER LANDSTRASSE LOT 15

<< |Delete|

V

Ļ

# Saving Values Manually (M+)

### Purpose

With this function you can load weight values and calculation results directly from Application 1 (e.g., counting, weighing in percent) or Application 2 (checkweighing, time-controlled functions) into Application 3 (totalizing, formulation, statistics).

# Available Features

 You can assign this function to the fourth or fifth soft key (from the right), i.e. F4 or F5 The soft key designation for this function is: M+

 An Application 3 program (totalizing, formulation or statistics) must be running so you can display and print the result

## **Factory Settings**

There are no optional parameters

### Preparation

- Turn on the balance: Press
- > Sartorius logo is displayed
- Select Extra function (F4) or Extra function (F5) in the Setup menu: Press (Setup)
- Select Application parameters: press the v soft key 2 x, then the > soft key
- Select Extra function (F4) or Extra function (F5): press the  $\vee$  soft key 3 × (or 4 ×), then the > soft key once
- Select Man. store in app.3 memory (M+)
- Confirm Man. store in app.3 memory (M+)

See also "Application Parameters (Overview)" in the chapter entitled "Configuration"

• Save settings and exit the Setup menu: press the < < soft key

# **Product Data Memory**

### Purpose

With this function you can enter, store and load data records for initialization of applications, including user-defined data.

You can use this extra function in combination with a program from Application 1 (e.g., counting, weighing in percent), one from Application 2 (checkweighing, time-controlled functions) and the other extra functions for F4 and F5 (identification codes, 2nd tare memory).

### **Available Features**

- Store up to 300 data records.
- Data records can be created, stored or deleted individually.
- Press the ProDat soft key to display product data.
- Define a name for each data record of up to 15 alphanumeric characters.
- Optional configuration in the Setup menu to delete a single character when entering a data record name by pressing CF). Setup: Device: Keys: CF function for input: Delete last character.
- Data records are displayed in alphabetical order.
- Initialization data set for an application (such as wRef, nRef) is saved when you select the Store option. With several applications and extra functions active, you can select the desired parameters before saving the data to define initialization data.
- Use the alphanumeric keypad to search for and display individual data records.
- You can assign this function to the fourth or fifth soft key (from the right), i.e. F4 or F5.

- Error messages are displayed in the text line in plain English.
- Press the Delete soft key to delete a data record.

Data Battery-Backed Data Memory When the balance is disconnected from AC power, these balance-generated data will remain stored for approx. three months. In the standby mode, data are retained by the power supply.

## **Factory Settings**

No user-definable parameters.

Soft Key Functions ProDat Toggle to product data display Delete Delete selected data record Overwrite the initialization Load data with the selected data record Change Change the data in the stored data record Store Store the initialization data of the selected application under the chosen data record name. If data already exist for this data record, a prompt asks whether this data should be overwritten. No Answer no to cancel a "delete" or "overwrite" operation Yes Answer yes to perform the "delete" or "overwrite" operation New Create a new data record (after entering a data record name) and selecting an application,

if desired).

### Preparation

- Turn on the balance: Press 🕡
- > Sartorius logo is displayed
- Select Extra function (F4) or Extra function (F5) in the Setup menu: Press (Setup)
- Select Application parameters: press the v soft key 2 x, then the > soft key
- Select Extra function (F4) or Extra function (F5): press the v soft key 3 × (or 4 ×), then the > soft key
- Select Product data memory
- Confirm Product data memory

See also "Application Parameters (Overview)" in the chapter entitled "Configuration"

Save settings and exit the Setup menu: press the << soft key</p>

# **Practical Example**

Create a New Base Data Record for Initializing the Checkweighing Program, Including: Target Value, Minimum, Maximum

Settings (changes in the factory settings required for this example):

Setup: App: Extra function (F4): Product data memory Setup: App: Application 2: Checkweighing

Step		Key (or instruction) Display/Output
1. If necessary: turn on the balance and enter the settings given above	(V)	
2. In the Checkweighing application, toggle to the input mode for target, minimum and maximum values	Param. soft key	CHECKWEIGH:     0.00 a       Target:     Setp= +     0.00 a       Minimum:     Min = +     0.00 a       Maximum:     Max = +     0.00 a
3. Enter target: 170 g; minimum: 165 g; maximum: 180 g	see the Practical Example for Checkweighing, steps 5 through 9	CHECKWEIGH:     170.00 %       Target:     Setp= +     0.00 %       Minimum:     Min = +     0.00 %       Maximum:     Max = +     0.00 %
4. Toggle to display of product data (existing data records are displayed; in this example, 3 data records have been stored)	ProDat soft key	PROD. DATA:     PERCENT WGH       PERCENT MGH40     W××%     68.75 %       CALCULATION8     PRef     100 %       COUNTING13         <
5. Enter a name for the new data record (here: CHW01)	(ABC) ABCDEF soft key, C soft key GHIJKL soft key, H soft key STUUWX soft key, W soft key 0 1	PROD. DATA: CHW01 <<   <   New
6. Store current Checkweighing parameters as a data record	New soft key	PROD. DATA:     NEW:     KW01       CHECKNEIGH     Setp= +     170.00 s       Min = +     165.00 s       Max = +     180.00 s       Lim-=     0 %       Lim+=     0 %       <     Store
7. Confirm	Store soft key	PROD. DATA:       Data stored         CHW01       Setp= + 170.00 s         PERCENT WGH40       Min = + 165.00 s         CALCULATION8       Max = + 180.00 s         COUNTING13       Lim-= 0 %         Lim+= 0 %       %         <
8. Exit data record display	< ⊂ soft key	Max 6200 9 <b>H</b> <b>H</b> <b>H</b> <b>H</b> <b>H</b> <b>H</b> <b>H</b> <b>H</b>

# **SQmin Function**

### Purpose

To display the allowable minimum sample quantity "SQmin" in accordance with the United States Pharmacopeia (USP). According to USP guidelines, the uncertainty of measurement may not exeed 0.1 % of the sample quantity when substances are weighed with the highest degree of accuracy for volume determination. This additional function ensures that weight results lie within defined tolerance limits corresponding to the requirements of your quality assurance system.

### Features

The service technician will determine the required minimum sample quantity based on your quality assurance requirements at the location where the balance is set up. Afterwards, he will store this value in the balance. This setting cannot be changed by the user. Once he has finished programming the balance, the service technician will prepare a "Test in Accordance with the USP" certificate, on which he will record the measurements and the minimum sample quantity for the balance. If you use the SQmin function, you can be sure that the weight results will correspond to the specifications on the certificate and, therefore, USP guidelines.

 Displaying the minimum sample quantity: The value is shown in the next line for 4 seconds after the "SQmin" soft key is pressed or the value is constantly displayed in

place of the bar graph.

- This function can be assigned to either the fourth or fifth soft key from the right (F4 or F5). The soft key should then be labeled with SQmin.
- If the minimum sample quantity has not been reached: The SQm i n soft key will flash inversely. Weights will be marked with an asterisk "\*" in the printout.
- Header of GLP-complicant records: The minimum sample quantity entered for "SQmin" can be printed out in addition.

Factory-set parameters Display: Text display

Print in GLP header: Off

### Preparation

Turn on the balance: press

> Sartorius logo is displayed


Select Extra function (F4) or Extra function (F5) in the Setup menu: press (Setup)

Select Application parameters: press the  $\lor$  soft key twice, then press the  $\ge$  soft key once

Select Extra function (F4) or Extra function (F5): press the  $\lor$  soft key repeatedly, then press the > soft key

Select SQmin.

Confirm SQmin.



o = Factory setting

See also "Application Parameters (Overview)" in the chapter entitled "Configuration"

Store the settings and exit the Setup menu: press the << soft key.

**Example** Determining the weights of samples while monitoring the minimum sample quantity (here: SQmin: 30 mg)

Presettings (different from the factory settings): Setup: Application parameters: Additional function (F4): SQmin

Step		Press key(s) (or follow instructions)	Display/Output	
1.	Switch on the balance if necessary and enter the presettings as shown above	ĊIJ		
2.	Place the container into which the sample will be filled onto the weighing pan and tare the balance	Tare	Max 62009 0% 0 0% Cal	
3.	Weigh a sample (here: the minimum sample quantity has not been reached)	Place the sample on the weihing pan	Max 62009 0% • • • • • • • • • • • • • • • • • • •	
4.	Print out the weight	Ē	*N + 0.02 g	
5.	Weigh another sample (here: the minimum sample quantity has been exceeded)	Place the sample on the weighing pan	Max 62009 8% Maximum d= 0.019 100% + I6.389 Cal   SQmin	
6.	Print out the weight	Ē	N + 16.38 g	
7.	Display the minimum sample quantity for 4 seconds	SQmin soft key	Max 62009 0% 100% ♀	

8. If necessary, weigh further samples

# **DKD Uncertainty of Measurement**

### Purpose

Display of the dynamic uncertainty of measurement in conformance with the specifications listed on the DKD Calibration Certificate.

### Features

After Technical Service has prepared the balance:

- A service technician performs on-site DKD calibration of your balance to determine its uncertainty of measurement. On the DKD Calibration Certificate, the measurements and the uncertainty for the initial sample weight are recorded. Then the service technician enters this data in the balance.
- Display of the factor and the exponent entered; activation by accessing the Setup menu: Device information: DKD uncertainty of measurement
- Display of the uncertainty of measurement, for example: Absolute uncertainty of measurement: U = 0.54 9 Relative uncertainty of measurement: U\* = 0.00045 % Process accuracy: PA = 0.00013 %
- Display of up to 2 DKD uncertainty of measurement values: The first two calculated values that are actviated by selecting "Display" in the Setup menu are shown.
- This function can be assigned to a key identified by the fourth or fifth soft key (from the right, F4 or F5).
   The soft key is identified by U ✓ P Ĥ
- Resolution
   The absolute uncertainty of measurement is displayed with a 10 times higher resolution.

   The absolute uncertainty of measurement and the process accuracy are displayed with up to 5 decimal places (2 significant decimal places).
- Printout of the addend and the factor of the uncertainty of measurement when the power is turned on: In the Setup menu, select "Auto print upon initialization: All values."
- Display ----- (for U\* and PG) for:
  - Calculated net values (e.g., counting, weighing in percent, etc.)
  - Values greater than 100%
  - Net value equal to "zero"

### Preparation

Turn on the balance: press 🗤

> The Sartorius logo is displayed

In the Setup menu, select "Extra functions (F4)" or "Extra functions (F5)": press (Setup)

Select the Application parameters: press the  $\vee$  soft key 2 times, then the  $\supseteq$  soft key

Select Extra function (F4) or Extra function (F5): press the  $\vee$  soft key repreatedly, then press the > soft key

### Confirm DKD uncertainty of measurement

DKD Uncertainty of measurement	— Display ———	*	U (absolute) U* (relative) PA (process accuracy)
	– Print ––––––	*	U (absolute) U* (relative) PA (process accuracy)
	Process accuracy		lnput: 1 – 100, 5 decimal places

\* = An asterisk (\*) indicates an activated menu item. You can select up to 3 items. \* = factory setting

See also "Application Parameters (Overview)" in the chapter entitled "Configuration"

Save settings and exit the Setup menu: press the << soft key

### Example

Perform a weighing procedure with the "DKD uncertainty of measurement" application

Settings:

Setup: Application parameters: Extra function (F4): DKD uncertainty of measurement: Display: PA (process accuracy) Setup: Application parameters: Extra function (F4): DKD uncertainty of measurement: Print: PA (process accuracy) Setup: Application parameters: Extra function (F4): DKD uncertainty of measurement: Display: Input: 3.00000 (factory setting)

Step Press key(s) (or follow instructions)	Display/Output	
1. Turn on the balance, if not on, and configure the settings as indicated above	Ċ	
2. Place a container for a sample on the balance and tare	Tare	Max 12k9 d= 0.19 U = 0.08 9 PA = % 0 <b>0.0 9</b> Cal U/PA
3. Measure weight of sample	Add sample to container	Max 12k9 U = 0.16 9 PA = 0.024 % + <b>2000.29</b> Cal U/PA
4. Print weight	Ē	U 0.08 g PA 0.024 % N +2000.2 g

### 5. Weigh next sample (if any)

# **Combining Applications**

The following table summarizes the possibilities for combination of the application programs described here. Each line stands for one combination. The weighing function is generally available, and does not have to be combined with a calculating function.

Application 1 (basic settings)	Application 2 (checking and control functions)	Application 3 (data records and documenting functions)
Counting Counting	-	Totalizing Formulation
Counting Weighing in percent Weighing in percent Weighing in percent		Statistics Totalizing Formulation Statistics
Animal weighing Animal weighing	-	Totalizing Statistics
Recalculation Recalculation	-	Totalizing Statistics
Calculation Calculation Calculation		Totalizing Formulation Statistics
Density determination	–	Statistics
Density determination	Time-controlled functions	Statistics
Differential weighing Air buoyancy correction		- Totalizing
Air buoyancy correction Diameter determination Diameter determination Diameter determination	- - -	Statistics Totalizing Formulation Statistics
	Checkweighing Checkweighing Checkweighing	Totalizing Formulation Statistics
Counting	Checkweighing	Totalizing
Counting	Checkweighing	Formulation
Counting	Checkweighing	Statistics
Weighing in percent	Checkweighing	Totalizing
Weighing in percent	Checkweighing	Formulation
Weighing in percent	Checkweighing	Statistics
Recalculation	Checkweighing	Totalizing
Recalculation	Checkweighing	Statistics
Calculation	Checkweighing	Totalizing
Calculation	Checkweighing	Formulation
Calculation	Checkweighing	Statistics
Air buoyancy correction	Checkweighing	Totalizing
Air buoyancy correction	Checkweighing	Statistics
Diameter determination	Checkweighing	Totalizing
Diameter determination	Checkweighing	Formulation
Diameter determination	Checkweighing	Statistics
-	Time-controlled functions Time-controlled functions Time-controlled functions	Totalizing Formulation Statistics
Counting	Time-controlled functions	Totalizing
Counting	Time-controlled functions	Formulation
Counting	Time-controlled functions	Statistics
Weighing in percent	Time-controlled functions	Totalizing
Weighing n percent	Time-controlled functions	Formulation
Weighing in percent	Time-controlled functions	Statistics
Animal weighing	Time-controlled functions	Totalizing
Animal weighing	Time-controlled functions	Statistics
Recalculation	Time-controlled functions	Totalizing
Recalculation Calculation	Time-controlled functions	Statistics Totalizing
Calculation	Time-controlled functions	Formulation
Calculation	Time-controlled functions	Statistics
Air buoyancy correction	Time-controlled functions	Totalizing
Air buoyancy correction	Time-controlled functions	Statistics
Diameter determination	Time-controlled functions	Totalizing
Diameter determination	Time-controlled functions	Formulation
Diameter determination	Time-controlled functions	Statistics

### **Examples of Application Combinations**

### Checkweighing with statistical evaluation

You want to check a piece count, and have the results that lie within the tolerance range statistically evaluated and printed as a ISO/GLP-compliant record.

Settings (changes in the factory settings required for this example):

Setup: Application parameters: Application 1: Counting

Setup: Application parameters: Application 2: Checkweighing

Setup: Application parameters: Application 3: Statistics: Automatic storage: On, first value at stability

Setup: Application parameters: Application 3: Statistics: Source of data for auto storage: Application 2

Setup: Application parameters: Application 3: Statistics: Evaluated value: Calculated

Setup: Application parameters: Application 3: Statistics: Evaluation mode, MR function: Intermediate evaluation, display+print Setup: Application parameters: Printout configuration: ISO/GLP/GMP printout: Always

Key (or instruction) Display/Output Step 1. If necessary: turn on the balance (1/0) 0.019 100% Мах4200 0%∎ d٩ and enter the settings given above П <u>COUNTING:</u> nRef Start Cal Max4200 0% 0.019 100% 2. Place reference sample quantity Place parts on the balance 9 on the balance <u>UNTING:</u> Start 0.019 100% 3. Initialize the balance Start soft key Max4200 0% ž PCS COUNTING: ωRef 18.03.1997 09:41 SARTORIUS LA4200S Mod. 60419914 Ser.-no. Ver.-no. 01 - 35 - 18T D C – I D nRef 10 pcs 21.03500 g wRef n 1 Qnt 10 pcs 4. Remove reference sample quantity Unload the balance .019 4200 Мах ИХ∎ ∎ĭ00; PCS JNTING: E 5. Initialize Checkweighing 4200 .d= 0.019 ∎100%∧ Toggle to Checkweighing (Q1) 2 PCS

Start

Initialize \_\_\_\_\_Param

CHECKWEIGH:

Step	Key (or instruction)	Display/Output
<ol> <li>Enter target, minimum and maximum values (here: target: 10 pcs; minimum: 7 pcs; maximum: 12 pcs)</li> </ol>	Param. soft key 1 0, J soft key 7, J soft key 1 2	CHECKWEIGH:     0 pcs A       Target:     Setp= +     10 pcs       Minimum:     Min = +     7 pcs       Maximum:     Max =     12 pcs       <     ^     4
7. Store input	₊J soft key	Max4200 9d= 0.019 A Z CHCKW.: n = 0 Setp= +10 pcs II Cal     Param.Net  Show
		Setp + 10 pcs Min + 7 pcs Max + 12 pcs
8. Determine first unknown quantity	Place uncounted parts on the balance	Max4200 s     d= 0.01s       Handbook     Handbook       Handbook
9. Toggle to Statistics		Max4200 s d= 0.01s Maxada d= 0.01s ★ STATI.: Start with M+ Cal     MR   M-   M+
10. Initialize automatic storage	M+ soft key	Max4200 9 d= 0.019
11. Determine further unknown quantities Printout is generated automatically	Place parts to be counted on the balance	n 1 Qnt + 9 pcs
		n 4
12. End weighing series Statistics are evaluated Final GLP printout is generated		Avg. + 10.0 pcs s + 0.8 pcs srel + 8.00 % Total + 40 pcs Min + 9 pcs Max + 11 pcs
13. Delete initialization of the last application	- B	18.03.1997 10:26 Name:

### **Data Output Functions**

There are 3 options for data output:

- Output to the display and control unit
- Output to a printer (generate a printout)
- Output to a peripheral device (e.g., computer) via the interface port

#### **Output to the Display and Control Unit**

The display is divided into 9 sections. Information about the balance, the application being used and the sample weighed is output in the following sections:

- Line for metrological data
- Bar graph

Line for metrological data Bar graph

Unit

e= 0.19

Tare memory Calculated value

Application pictograms

Measured value line

Plus/minus sign

Stability indicator

Text line Soft key labels

- Plus/minus sign, stability symbol display
- Measured value line
- Weight unit display
- Data in tare memory; calculated value
- Application symbol display
- Text line
- Soft key labels

Line for Metrological Data (on balances verified for legal metrology)

This line shows:

- Max4200 g Maximum balance capacity (e.g., 4,200 g)
- Min Ø.5 g Minimum balance capacity; the weight must not go below this limit when the balance is used in legal metrology
  - Verification interval of the balance; irrelevant if the balance is not used in legal metrology (e.g., 0.1 g)
  - d=0.019 Readability: Indicates the actual scale interval (display increment of the balance) (e.g., 0.01 g)

Bar Graph (overview display) In the bar graph, weighing results are displayed either

0×. ∎100% . . . . as a percentage of the maximum balance capacity, or \_ in relation to a target value, with tolerance limits indicated. \_ 100% 02 ...... **1**+ You can turn off (blank) the bar graph display (Setup: Device: Display: Digit size: 13 mm + text display or 13 mm)

Plus/Minus Sign, Stability Symbol This section shows:

- "Busy" symbol
- Plus or minus sign
- Zero symbol (indicating the scale has been zeroed)

125.03	Measured Value Line This line shows: – The current weight value (bordered values are invalid in legal metrology)
35	- Calculated values (e.g., piece count)
=W* 18.3*0.9	– User input (e.g., lot number, equation)
ସ	Weight Unit Display This section shows: - The current weight unit (e.g., kg)
P C S	<ul> <li>Designation of other values (e.g., "pcs")</li> </ul>
	Tare Memory, Calculated Value This section shows:
	<ul> <li>Indication that value is calculated (not valid in legal metrology)</li> </ul>
NET1 NET2	<ul> <li>Indication that the tare memory contains application data</li> </ul>
∐1 ‰ % ⊗ ♀	Application Symbols This column shows: – Symbol for Application 1 (toggling between weight units, counting, weighing in percent, animal weighing, calculation)
20	<ul> <li>Symbol for Application 2 (checkweighing, time)</li> </ul>
Σ ¥ X	– Symbol for Application 3 (totalizing, formulation, statistics)
 0	<ul> <li>Symbol for current print job</li> </ul>
 三	<ul> <li>Symbol for ISO/GLP printout</li> </ul>
COUNTING: nRef = 10 pcs	Text Line This line contains: – Explanatory text about the application program (e.g., about "Counting")
Ref.wt. too light	- Explanation of error codes
Cal PT1/T1 S ID M+	Soft Key Labels This line shows – Texts (abbreviations) to indicate the function assigned to each key
4 < v ^ > >>	<ul> <li>Symbol for selecting and confirming parameter settings (see also "Operating Design")</li> </ul>
	Balance Information In the Setup menu, you can select Setup: Info: Device information for a display of balance information. The display includes:
SETUP INFO Version no.: 01-35-18	– Software version number
Bal. ver. no.: 00-20-13 Model: LA5200P Serial no.: 70906913	- Balance version number
<<	- Balance model
	- Balance serial number

- Date: next maintenance
- Service phone

### **Printouts**

### Purpose

This function enables you to print out weights, other measured values and IDs. You can format the printout to meet different requirements.

### Features

Line format: you can configure a data ID code with up to 6 characters at the beginning of each of the values to be printed

### Weight ID:

You can configure an extra line for identification of each weighed or calculated value using the code S ID

### Print application parameters:

You can generate a printout of the values configured for initialization of an application before printing the measured results

### **ISO/GLP-compliant printout:**

You can print out parameters relating to the weighing conditions

### Print animal weights:

Application-defined, automatic printout of animal weights or of animal weights plus calculated weights after averaging

### **Optimizing interfaces:**

Use the highest possible baud rate

- Turn off interfaces that are not in use
- Optimize the amount of data to be transfered

### **Configuring Printout Formats**

For a number of application programs, you need to set initialization values. All values upon initialization or only the main values can be automatically printed as soon as you have configured this in the Setup menu: Auto print upon initialization

Weights and calculated values can be printed as numeric values either with a preceding data ID code (numeric value with 22 characters) or without one (numeric value only 16 characters). See also the section on Line format in the chapter entitled "Data Output Functions".

You can generate an ISO/GLP print-out always or only for calibration/adjustment or turn off this option. See also page 116. Generating an ISO/GLP Printout In the Setup menu, you have a choice of three settings:

- No ISO/GLP printout generated (0 f f)
- ISO/GLP printout generated only for calibration/adjustment (Only for calibration/adjustment)
- Every printout is an ISO/GLP-compliant report (Always on)

Auto print checkweighing results: automatic printout of a weight when it lies within the preset limits at stability

Auto print with time-controlled functions: automatic printout of weights after a preset time has elapsed or at a defined time

Printout of intermediate or final evaluation from the application 3 memory (totalizing, formulation and statistics); generate by pressing the MR soft key

Generating Printouts Acceptable for Legal Metrology: You can configure the Setup menu of the balance to generate data records that are acceptable for legal metrology on a Sartorius printer:

- YDP02
- YDP03
- YDP011S
- YDP01IS Label
- YDP02IS
- YDP021S Label
- YDP041S
- YDP041S Label

### ISO/GLP-compliant Printout/Record

You can have the parameters pertaining to weighing conditions printed before (GLP header) and after (GLP footer) the values from the weighing series. These parameters include:

- Date
- Time at the beginning of a weighing series
- Balance manufacturer
- Balance model
- Model serial number
- Software version
- Lot number (weighing series no.)
- Time at the conclusion of the weighing series
- Field for operator signature

Operating the Balance with an ISO/GLPcapable Documentation Device (Printer)

ISO/GLP-compliant documentation requires a computer with special software. Contact Sartorius for a detailed description for creating this software.

### Setting:

Setup: Printout: ISO/GLP/GMP printout: Always on

The record is output to a Sartorius YDP03-0CE Data Printer or a computer.

End GLP printout:

Press CF

End GLP printout while application is active: This requires the following settings: Setup: Device: Keys: CF function in application: Clear only selected

• Press (CF)

applications

- > Text line: CF selected: clear application
- Press the GLP soft key

17.01.1997 16:12 SARTORIUS Mod. LA4200S Ser. no. 60419914 Ver. no. 01-35-18 ID 12345678901234
L ID 12345678901234 nRef 10 pcs wRef 1.35274 g Qnt + 235 pcs Qnt + 4721 pcs S ID 12345678901234 Qnt + 567 pcs 
Name:
17.01.1997 16:24 SARTORIUS Mod. LA4200S Ser. no. 60419914 Ver. no. 01-35-18 ID
17.01.1997 16:24 SARTORIUS Mod. LA4200S Ser. no. 60419914 Ver. no. 01-35-18

Name:

\_\_\_\_\_

Dotted line Date/time Balance manufacturer Balance model Balance serial number Software vers. (display and control unit) Balance ID no. Dotted line Weighing series no. Application initialization value Application initialization value Counting result Counting result ID for counting result Counting result Dotted line Date/time Field for operator signature Blank line Dotted line Record of Internal Calibration/Adjustment: Dotted line Date/time

Balance manufacturer Balance model Balance serial number Software vers. (display and control unit) Balance ID no. Dotted line Weighing series no. Calibration adjustment mode Beginning mode for calibration/adjustment Difference after calibration/adjustment Confirmation of completed calibration/adjustment routine Difference between current and target values after calibration Dotted line Date/time Field for operator signature Blank line Dotted line

### **Interface Description**

### Purpose

Your LA Reference balance comes equipped with an interface port for connection to a computer or other peripheral devices.

You can use an on-line computer to change, start and/or monitor the functions of the balance and the application programs. The interface port also has four control lines for the over/under checkweighing program. You can also connect a hand switch or foot switch.

### ▲ Warning When Using Pre-wired RS-232 Connecting Cables!

RS-232 cables purchased from other manufacturers often have incorrect pin assignements for use with Sartorius balances. Be sure to check the pin assignment against the chart below before connecting the cable, and disconnect any lines marked "Internally Connected" (e.g., pin 6). Failure to do so may damage or even completely ruin your balance and/or peripheral device.

### Available Features

Type of interface:	Serial interface
Operating mode:	Full duplex
Standard:	RS-232
Transmission rates:	150; 300; 600; 1,200; 2,400; 4,800; 9,600; 19,200 baud
Parity:	Space, odd, even
Character format:	1 start bit, 7-/8-bit ASCII, parity, 1 or 2 stop bits
Handshake:	2-wire interface: via software (XON/XOFF); 4-wire interface: via hardware handshake lines (CTS/DTR)
Operating mode:	SBI, xBPI*
Network address**:	0, 1, 2,, 30, 31
Data output format of the balance:	16 or 22 characters

\* xBPl operating mode: 9,600 baud, 8 bits, odd parity, 1 stop bit

\*\* Network address is only valid in the xBPI mode

### Factory Settings:

Transmission rate:	1,200 baud
Parity:	Odd
Stop bits:	1 stop bit
Handshake:	Hardware 1 character after CTS
Operating mode:	SBI
Network address:	0
Print manually/automatically:	Manual after stability
Stop automatic printing:	Not possible
Automatic printout, time-dependent:	After 1 display update
Tare after indiv. printout:	Off
Application initialization values:	Off
Line format:	For other applications/GLP (22 characters)

Preparation

• See page 122 for the pin assignment chart

Line Format (Data Output Format) You can output the values displayed in the measured value line and the weight unit with or without a data ID code

Example: Without data ID code 253 pcs +

Example: With data ID code 253 pcs Qnt +

Configure this parameter in the Setup menu (Setup: Printout: Line format).

The output with data ID code has 16 characters; without data ID code, 22 characters.

### Output Format With 16 Characters

Display segments that are not activated are output as spaces. Characters without a decimal point are output without a decimal point.

The following characters can be output, depending on the characters displayed on the balance:

### Normal Operation

Position	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
	+	*	D	D	D	D	D	D	D	D	*	υ	U	υ	CR	LF
or	-											*	*	*		
or	*		*	*	*	*	*	*	*	*						

*:	Space
D:	Digit or letter
U:	Unit symbol

- CR: Carriage return LF: Line feed

#### Special Codes F

Position	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
	*	*	*	*	*	*	-	-	*	*	*	*	*	*	CR	LF
or							Н	Н								
or							L	L								
or							С									

*:	Space
:	Weight
H:	Overload
HH:	Overload in checkweighing
L:	Underload
LL:	Underload in checkweighing
C:	Calibration/adjustment

Error Codes Position	1	2	2	4	E	c	7	8	0	10	11	10	12	14	15	16
FOSILION	1	Z	د	4	5	6	/	ö	9	10	11	ΙZ	13	14	15	10
	*	*	*	Е	r	r	*	*/#	#	#	*	*	*	*	CR	LF

\*. Space

# # #: Error code number

Data output	exar	nple:	+ 12	55.7	g											
Position	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
	+	*	*	*	1	2	5	5		7	*	g	*	*	CR	LF
Position 1: Position 2: Position 3-1 Position 11: Position 12- Position 15: Position 16:	-14:	2 V 2 U 0	pace Veigh pace Jnit s	it wit ymbo ge re	h a d ol or s	gn or ecima space	al poi		adin	g zerc	0S = S					

### Data Output With 1D Code

When data with an ID code is output, the ID code consisting of 6 characters precedes thedata with the 16-character format. These 6 characters identify the subsequent value.12345678910111213141516171819202122

	1	2	د	4	2	0	/	8	9	10	11	ΙZ	13	14	15	10	17	18	19	20	21	22
	1	1	1	1	1	1	+	*	D	D	D	D	D	D	D	D	×	U	U	U	CR	LF
		*	*	*	*	*	_											*	*	*		
							*		*	*	*	*	*	*	*	*						
1:		1D (	code	e cha	arac	ter1)						U:		Uni	t syr	nbol	1) see	e "To	oggli	ng		
*.		Spa	ice											betv	weer	ı We	ight	Unit	ts"	-		
•		•		1								CR	•			e retu						
D:		Diq	1t 01	r leti	ter							- UN	•	Can	iiayy							

1) depends on balance type; e.g., not all units and characters are available on balances verified for use in legal metrology

Special Codes

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
S	t	а	t	*	*	*	*	*	*	*	*	-	-	*	*	*	*	*	*	CR	LF
												Н	Н								
												L	L								
												С									
*: : H: H H:	0ve	ight erloa	d	che	eckw	veigl	ning				L: L L C:	:	Unc in c	lerlo lerlo heck brat	ad weig		g stme	nt			
Error	Cod	es																			
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
S	t	а	t	*	*	*	*	÷	Е	r	r	*	#	#	#	*	*	*	*	CR	LF

Space

\*:

# # #: Error code number

	acters 1 <sup>1</sup> )
Stat	Status
ID	ldentifier
LID	Weighing series no.
WID	Weight set number
Nom.	Exact calibration weight
S I D	Sample ID
NUM	Numeric input
т1	Application tare memory 1
Ν	Net weight (T1 = 0)
N 1	Net weight (T1# 0)
Qnt	Quantity
Prc	Percentage
nRef	Reference sample quantity
pRef	Reference percentage
wRef	Average piece weight
Wxx%	Reference percentage weight
mDef	Target value for animal weighing
Mul	Multiplication factor for ani- mal weighing
x-Net	Result in animal weighing
x – R e s	Calculated result in animal weighing
Res	Result using equation (Calculation)
Setp	Target value for checkweighing
Min	Lower limit for checkweighing
Max	Upper limit for checkweighing
Time	Time that a value was stored
Compxx	No. of components in formulation
Tot.cp	Total weight in formulation
n	Transaction counter
Total	Sum of all values
Avg	Average in statistics
	64 1 1 1 1 1 1
s	Standard deviation
s srel	Variation coefficient

### Data Input Format

You can connect a computer to your balance to send commands via the balance interface port to control balance functions and applications.

The commands sent are control commands and may have different formats; e.g., control commands can have up to 26 characters. Each character must be transmitted according to the settings configured in the Setup menu for data transmission.

Format for Control Command	Format	for	Control	Command
----------------------------	--------	-----	---------	---------

TOTTIAL TOT C		2011	inianus							
Format 1:	Esc	!	CR	LF						
Format 2:	Esc	!	#	_	CR	LF				
Format 3:	Esc	!	#	£t		(max. 20 &) &	_	CR	LF	
Format 4:	Esc	!		εt		(max. 20 &) &	_	CR	LF	

\_: CR:

LF:

max:

Esc: Escape

- !: Command character Number #:
- £t:
  - Number or letter

Underline (ASCII: 95) Carriage RETURN (optional) Line FEED (optional) depends on command character: i.e. parameter: once the max. length is reached, input received is cut off, rather than discarded as with keyboard input

### Format 1

!	Meaning
1	Weighing mode 1
L	Weighing mode 2
Μ	Weighing mode 3
N	Weighing mode 4
0	Block keys
Р	Print
R	Unblock keys
S	Restart
Т	Tare and zero
Ζ	Internal calibration/adjustment**
Q	Acoustic signal

!#Meaningf3Zerof4Tare (without zeroing)kF1Soft key 1*Function dependson setting inkF6Soft key 6*application programkF7Function keykF8Function keys3Function key CFx0Perform internal calibration**x1Print balance modelx2Print weighing platform serial numberx3Print weighing platform software versionx4Print display and control unit software versionx5Print operator ID x6x6Print weight set ("inventory") number	Form	at 2
f4       Tare (without zeroing)         f4       Tare (without zeroing)         kF1       Soft key 1*       Function depends          on setting in         kF6       Soft key 6*       application program         kF7       Function key         kF8       Function key         s3       Function key CF         x0       Perform internal calibration**         x1       Print balance model         x2       Print weighing platform serial number         x3       Print weighing platform software version         x4       Print display and control unit software version         x5       Print operator ID         x6       Print weight set ("inventory")	!#	Meaning
kF1       Soft key 1*       Function depends          on setting in         kF6       Soft key 6*       application program         kF7       Function key         s3       Function key         s3       Function key         x0       Perform internal calibration**         x1       Print balance model         x2       Print weighing platform serial number         x3       Print weighing platform software version         x4       Print display and control unit software version         x5       Print operator ID         x6       Print weight set ("inventory")	f3	Zero
on setting in         kF6       Soft key 6* application program         kF7       Function key         kF8       Function key         s3       Function key         x0       Perform internal calibration**         x1       Print balance model         x2       Print weighing platform serial number         x3       Print weighing platform software version         x4       Print display and control unit software version         x5       Print operator ID         x6       Print weight set ("inventory")	f4	Tare (without zeroing)
kF6Soft key 6*application programkF7Function keys3Function key CFx0Perform internal calibration**x1Print balance modelx2Print weighing platform serial numberx3Print weighing platform software versionx4Print display and control unit software versionx5Print operator ID x6x6Print weight set ("inventory")	kF1	Soft key 1* Function depends
kF7       Function key         kF8       Function key         s3       Function key         s3       Function key         x0       Perform internal calibration**         x1       Print balance model         x2       Print weighing platform serial number         x3       Print weighing platform software version         x4       Print display and control unit software version         x5       Print operator ID         x6       Print weight set ("inventory")		on setting in
kF8       Function key         s3       Function key         s3       Function key         x0       Perform internal calibration**         x1       Print balance model         x2       Print weighing platform serial number         x3       Print weighing platform software version         x4       Print display and control unit software version         x5       Print operator ID         x6       Print weight set ("inventory")	kF6	Soft key 6* application program
s3       Function key CF         x0       Perform internal calibration**         x1       Print balance model         x2       Print weighing platform serial number         x3       Print weighing platform software version         x4       Print display and control unit software version         x5       Print operator ID         x6       Print weight set ("inventory")	kF7	Function key
x0       Perform internal calibration**         x1       Print balance model         x2       Print weighing platform serial number         x3       Print weighing platform software version         x4       Print display and control unit software version         x5       Print operator ID         x6       Print weight set ("inventory")	kF8	Function key
x1       Print balance model         x2       Print weighing platform serial number         x3       Print weighing platform software version         x4       Print display and control unit software version         x5       Print operator ID         x6       Print weight set ("inventory")	s3	Function key CF
<ul> <li>x2 Print weighing platform serial number</li> <li>x3 Print weighing platform software version</li> <li>x4 Print display and control unit software version</li> <li>x5 Print operator ID</li> <li>x6 Print weight set ("inventory")</li> </ul>	x0	Perform internal calibration**
serial number         x3       Print weighing platform software version         x4       Print display and control unit software version         x5       Print operator 1D         x6       Print weight set ("inventory")	x1	Print balance model
software version         x4       Print display and control unit software version         x5       Print operator ID         x6       Print weight set ("inventory")	x2	
software versionx5Print operator 1Dx6Print weight set ("inventory")	x3	8 81
x6 Print weight set ("inventory")	x4	1 0
	x5	Print operator ID
	x6	
x7 Print batch number	x7	Print batch number

#### Format 3 (not allowed in the Setup menu) !# Meaning

z5	Input (GLP ) balance ID no. (20 characters max.)
z6	Input weight set ("inventory") number (14 characters max.)
z7	Input weighing series no. (20 characters max.)

### Format 4

!	Meaning
t	Text input in display

\* numbered from right to left

\*\* Internal calibration weight necessary

#### Synchronization

During data communication between the balance and an on-line device (computer), messages consisting of ASCII characters are transmitted via the interface. For error-free data communication, the parameters for baud rate, parity, handshake mode and character format must be the same for both units.

You can set these parameters in the Setup menu so that they match those of the on-line device. You can also define parameters in the balance to make data output dependent on various conditions. The conditions that can be configured are described under each of the application program descriptions.

If you do not plug a peripheral device into the balance interface port, this will not generate an error message.

#### Handshake

The balance interface (Sartorius Balance Interface = SBI) has transmit and receive buffers. You can define the handshake parameter in the Setup menu:

Hardware handshake (CTS/DTR)Software handshake (XON, XOFF)

Hardware Handshake With a 4-wire interface, 1 more character can be transmitted after CTS (Clear to Send).

Software Handshake The software handshake is controlled via XON and XOFF. When a device is switched on, XON must be transmitted to enable any connected device to communicate.

When the software handshake is configured in the Setup menu, the hardware handshake becomes active after the software handshake.

The data transmission sequence is as follows:

(transmitting device)	byte> byte> byte> < XOFF byte> byte>	(receiving
	 (Pause)	
	 XON byte> byte> byte>	

Transmitting Device:

Once XOFF has been received, it prevents further transmission of characters. When XON is received, it re-enables the transmitting device to send data.

### **Receiving Device:**

XOFF is transmitted after the 26th character has been stored. To prevent too many control commands from being received at one time, XON is not transmitted until the buffer is almost empty.

### Activating Data Output

You can define the data output parameter so that output is activated either when a print command is received or automatically and synchronous with the balance display or at defined intervals (see application program descriptions and auto-print setting).

Data Output by Print Command The print command can be transmitted by pressing  $\bigcirc$  or by a software command (Esc P).

#### Automatic Data Output In the "auto print" operating mode, data

In the auto print operating mode, data is output to the interface port without a print command. You can choose to have data output automatically at defined print intervals with or without the stability parameter. Whichever parameter you select, the data will be output as the readouts appear on the balance display. The display update frequency depends on both the model of the balance and the current operating status.

If you select the auto print setting, data will be transmitted immediately the moment you turn on the balance. In the Setup menu you can configure whether this automatic output can be stopped and started by pressing B.

### **Pin Assignment Chart**


### Female Interface Connector:

25-position D-Submini, DB25S, with screw lock hardware for cable gland

Male Connector Used: (please use connectors with the same specifications):

25-pin D-Submini, DB25S, with integrated shielded cable clamp assembly (Amp type 826 985-1C) and fastening screws (Amp type 164 868-1)

### Pin Assignment Chart:



- Pin 21: Ext. Supply Voltage Ground (GND)
- Pin 22: Not Connected
- Pin 23: Not Connected
- Pin 24: Ext. Supply Voltage Input + 15 ... 25 V
- Pin 25: +5 V Output
- \*) = See "Additional Functions" for information on changing pin assignments
- \*\*) = Hardware restart
- \*\*\*) = Restart of peripheral devices

# **Cabling Diagram**




Diagram for interfacing a computer or different peripheral devices to the balance using the RS-232/V24 standard and cables up to 15 m (50 ft.) long

Type of cable: AWG 24 specification

# Error Codes and Messages

Error codes and messages are displayed in the main display or text line for 2 seconds. The program then returns automatically to the previous status.

Display	Cause	Solution
No segments appear on the display	No AC power is available The AC adapter is not plugged in Automatic shutoff configured in Setup (code 8 7 4)	Check the AC power supply Plug in the AC adapter Press (10) to switch on the balance or select "no automatic shutoff" in Setup
Н	The load exceeds the balance capacity	Unload the balance capacity
LorErr 54	The weighing pan is not in place	Place the weighing pan on the balance
Err Ol > Display range	Data output not compatible with output format	Change the configuration in the Setup menu
Err O2 Cal. n. possible	Calibration/adjustment condition not met, e.g., – The balance was not tared – The balance is loaded	Calibrate only when zero is displayed Press Tare to tare Unload the balance
Err O∃ Cal.∕adj. interrupt	Calibration/adjustment could not be completed within a certain time	Allow the balance to warm up again and repeat the adjustment process
Err OS	Built-in calibration weight cannot be retracted	Contact your local Sartorius Service Center
Err O6 Int. wt. defective	Built-in calibration weight is defective	Contact your local Sartorius Service Center
Err 07 Function blocked	Function not allowed in balances verified for use in legal metrology	Contact your local Sartorius Service Center for information on having the settings changed
E <b>rr 08</b> * <>zero range	The load on the balance is too heavy to zero the readout	Check whether the "power-on zero range" is set
Err O9* < 0 not allowed	Taring is not possible when the gross weight is $\leq$ zero	Zero the balance
Err IO Tare fct. blocked	Tare key and 2nd tare memory are blocked when there is data in the tare memory for the formulation application	Press CF to clear the formulation application; the tare key and 2nd tare memory are then accessible
	Differential weighing: The tare key is blocked when a tare weight is stored for a specific sample	Differential weighing: Unload the balance or change to a different sample
Err II Tare2 blocked	<ul> <li>Tare memory not allowed</li> <li>Cannot load the sample tare weight</li> <li>Total weight in the tare memory exceeds the capacity of the balance</li> <li>Tare value exceeds the fine range of the verified balance</li> </ul>	Check the tare value entered
Err 12 Tare2 > Max.	Tare memory greater than weighing range or range limits	Check sample/container
Err ∣] Adjwt. >Max.	Internal adjustment is not possible because preload is too heavy	Reduce the preload or change the configuration
Err 30 Print fct. blocked	Interface port for printer output is blocked	Contact your local Sartorius Service Center

<sup>\* =</sup>  occurs only via the SBI interface (ESC f3\_/f4\_)

Display/Problem	Cause	Solution
Err 31 Print fct. blocked	Interface handshake interrupted (XOFF, CTS)	Transmit XON, then CTS
Ref.wt. too lisht	Error in storing reference weight (with the counting or weighing- in-percent application)	Weight too light or there is no sample on the balance
Cannot update	Reference updating not possible (with the counting application)	See "Counting" in "Operation" for reference updating criteria
Not a number xxxx Too low xxxx Too hish	Input wrong (with any application pro- gram), e.g., alphabetic input not allowed	Follow the instructions for the application programs
Too many char.	Input text too long	Allowable text lengths, incl. decimal point: – S ID, NUM, L ID, ID: max. 20 characters – W ID: max. 14 characters
Wrong line format	Configured printout, printout memory and 16-character format selected	Select the 22-character format
Limits unequal for unit	Unit entered for tolerance limits in check- weighing different from the appl. used	Adjust tolerance limits
Equation too long	Equation exceeds 28 characters informulation	Limit equation to 28 characters
<b>Err</b> $I\square x$ x = 1: x = 2: x = 3: x = 4: "Checkerboard" pattern displayed continuously	Key is stuck Key pressed when switching on the balance: (F1, F2, F5, F6), (F) ( $91$ ), (F3), (0, 3), (4, 9) (2, 5), (6), (7), (7), (7), (7), (7), (7), (7), (7	Release key or Contact your local Sartorius Service Center
Err 320	Operating program memory defective	Contact your local Sartorius Service Center
Err 340	Operating parameter (EEPROM) is wrong RAM lost data Factory settings deleted	Turn the balance off, then back on again. If this error remains displayed, please contact your local Sartorius Service Center
Err 341	Battery needs to be rechearged	Leave the balance power on for at least 10 hours
No WP	Weighing platform is defective	Contact your local Sartorius Service Center
blocked	Function blocked	none
The special code remains displayed	None of the keys has been pressed since the balance was turned on	Press a key
The weight readout changes constantly	Unstable ambient conditions Too much vibration, or the balance is exposed to a draft A foreign object is caught between the pan and the balance housing	Set up the balance in another area Change Setup configurations to adapt the balance to the ambient conditions Remove the foreign object
The weight readout is obviously wrong	The balance has not been calibrated/adjusted The balance was not tared before weighing The balance is not level The dust cover is caught under the weighing pan	Calibrate/adjust the balance Tare before weighing Level the balance See "Replacing the Dust Cover" in the chapter "Care and Maintenance"

Error Code/Message Displayed	Cause	Solution/Remarks
Differential weighing:		
SAMPLE: Confirm delete∕ omit	"SAMPLE: delete/omit" prompt on display page for samples	Select Yes to delete Select Omit to omit
SAMPLE: Include	"SAMPLE: include" prompt on display page for samples	Select Omit to include a sample already omitted
Cannot store	File manager: – Not possible to save data – No available memory	Delete lot(s)
Cannot load	File manager: – Not possible to load data – Memory capacity limit reached	Delete lot(s)
Only 30 backweighs possible	An attempt was made to save a 31st backweighing operation	None
LOT: already exists	Lot already exists on the display page for LOTS	Choose a different lot ID
No sample	The Sample key was pressed when the display page for lots was shown, but there are no samples in the lot selected	Save sample first
Out of ran⊴e	On the display page for LOTS or SAMPLES, an alphanumeric lot or samle ID was input and not found	Enter the correct lot or sample ID
Not enough memory space or 999 samples maximum	An attempt was made to save more than 999 samples using the numeric keys and the #Sp1 key	Use less memory or delete one or more lots
Sample omitted	An attempt was made to save data from an omitted sample	None
Value too small to accept		Place the particular weight on the balance
No choice available	<b>Factor</b> was selected while attempting to activate the display page for results No 2 <sup>nd</sup> resolution available	Selection not possible Contact your local Sartorius Service Center
CF not possible	Only one sample or certain portions of a sample can be deleted by pressing the $CF$ key. This message indicates that further delete functions are not possible.	Samples can be deleted one at a time on the display page for samples
Calculated statistics	Message output when statistics are being calculated. This process can take several seconds if there are many samples.	Goes out automatically
No statistics available	No valid backweights available in this lot	Goes out automatically
No net initial wts. available	In serial and combined weighing, no initial weights found	Measure initial weights

If any other errors occur, contact your local Sartorius Service Center!

### Care and Maintenance

### Service

Regular servicing by a Sartorius technician will extend the service life of your balance and ensure its continued weighing accuracy. Sartorius can offer you service contracts, with your choice of regular maintenance intervals ranging from 1 month to 2 years. The optimum maintenance interval depends on the operating conditions at the place of installation and on the individual tolerance requirements.

### Repairs

Repair work must be performed by trained service technicians. Any attempt by untrained persons to perform repairs may lead to hazards for the user.

### Cleaning

- Unplug the AC adapter from the wall outlet (mains supply). If you have an interface cable connected to the balance port, unplug it from the port.
- Clean the balance using a piece of cloth which has been wet with a mild detergent (soap).
- After cleaning, wipe down the balance with a soft, dry cloth
- ▲ Make sure that no dust or liquid enters the balance housing.
- ▲ Do not use any aggressive cleaning agents (solvents or similar agents)

#### **Cleaning Stainless Steel Surfaces**

Clean all stainless steel parts regularly. Remove the stainless steel weighing pan and thoroughly clean it separately. Use a damp cloth or sponge to clean any stainless steel parts on the balance. You can use any commercially available household cleaning agent that is suitable for use on stainless steel. Clean stainless steel surfaces by wiping them down. Then rinse the equipment thoroughly, making sure to remove all residues. Afterwards, allow the balance to dry. If desired, you can apply oil to the cleaned surfaces as additional protection.

Solvents are permitted for use only on stainless steel parts.

### Replacing the Dust Cover

Instructions for replacing a damaged dust cover

### For LA Series Balances with a Round Glass Draft Shield Remove the following parts from the balance:

- Draft shield cover
- Glass draft shield cylinder
- Weighing pan
- Pan support
- Shield disk: turn clockwise and lift off
- Old dust cover
   Place the new dust cover on the balance and press down on the front and back along the edges until it is seated firmly

Place the shield disk on the balance and turn it counterclockwise

Follow the above instructions in reverse order when placing the remaining parts back on the balance.

### For LA Series Balances with a Rectangular Weighing Pan and a Weighing Capacity ≤ 12 kg Remove the following parts from the balance:

- Weighing pan
- Pan draft shield (depending on balance model)
- Old dust cover

Place the new dust cover over the balance

Follow the above instructions in reverse order when placing the remaining parts back on the balance.

▲ The dust cover must not touch the weighing pan



### Safety Inspection

If there is any indication that safe operation of the balance is no longer warranted:

- Turn off the power and disconnect the equipment from AC power immediately
- > Lock the equipment in a secure place to ensure that it cannot be used for the time being.

Notify your nearest Sartorius Service Center. Repair work must be performed by trained service technicians.

We recommend having the power supply inspected by a certified electrician at regular intervals, according to the checklist given below:

- Insulating resistance: > 7 megaohms measured with a constant voltage of at least 500 volts at a 500 K-ohm load
- Leakage current: < 0.05mA measured with a properly calibrated multimeter

### Recycling

# Information and Instructions on Disposal and Repairs

Packaging that is no longer required must be disposed of at the local waste disposal facility. The packaging is made of environmentally friendly materials that can be used as secondary raw materials.



The equipment, including accessories and batteries, does not belong in your regular household waste. The EU legislation requires its Member States to collect

electrical and electronic equipment and disposed of it separately from other unsorted municipal waste with the aim of recycling it.

In Germany and many other countries, Sartorius AG takes care of the return and legally compliant disposal of its electrical and electronic equipment on its own. These products may not be placed with the household waste or brought to collection centers run by local public disposal operations – not even by small commercial operators.

For disposal in Germany and in the other Member States of the European Economic Area (EEA), please contact our service technicians on location or our Service Center in Goettingen, Germany:

Sartorius AG Service Center Weender Landstrasse 94–108 37075 Goettingen, Germany In countries that are not members of the European Economic Area (EEA) or where no Sartorius affiliates, subsidiaries, dealers or distributors are located, please contact your local authorities or a commercial disposal operator.


Prior to disposal and/or scrapping of the equipment, any batteries should be removed and disposed of in local collection boxes.

Sartorius AG, its affiliates, subsidiaries, dealers and distributors will not take back equipment contaminated with hazardous materials (ABC contamination) – either for repair or disposal. Please refer to the accompanying leaflet/manual or visit our Internet website (www.sartorius.com) for comprehensive information that includes our service addresses to contact if you plan to send your equipment in for repairs or proper disposal.

### **Overview**


### **General View of the Balances**

# LA310S (-OCE), LA230S (-OCE), LA230P (-OCE), LA120S (-OCE) -OCE identifies the precision balances as verified for legal metrology in the EU\*




Pos.	Designation	Order No. for replacement	Pos.	Designation	Order No. for replacement
1	Weighing pan	69 LA0006	11	Function keys	
2	Shield disk	69 A20003	12	Print key	
3	Shield plate	69 LA0008	13	Numeric keys	
4	Bushing (pan adapter)	69 LA0007	14	On/off key	
5	Leveling foot	69 B20005	15	Toggle key for alphabetic input	
6	Display and control unit		16	Display	
7	Metrological ID label		17	Data interface port	
	(only on balances verified for legal metro	logy)	18	Level indicator	
8	Lug for attaching an anti-theft	- 557			
	locking device		Not	shown:	
9	DC jack		ln-us	se dust cover	6960LA01
10	Tare key		Prote	ective caps and plugs (set)	69 B20009

### General Views of the Balances LA1200S (-OCE), LA620S (-OCE), LA220S (-OCE), LA620P (-OCE), LA5200D, LA3200D, LA2000P -OCE identifies the precision balances as verified for legal metrology in the EU\*




No.	Designation	Order no. for replacement	No.	Designation	Order no. for replacement
1	Draft shield cover	69 LP0002	12	Function keys	
2	Glass draft shield cylinder	69 14290	13	Print key	
3	Weighing pan	69 LP0004	14	Keys for numeric input	
4	Pan support – LA 3200D:	69 LP0006	15	On/off key	
	– LA 1200S, LA 620, LA 220S:	69 LP0005	16	Toggle key for alphabetic input	
5	Shield disk	69 LP0003	17	Weight display	
6	Leveling foot	69 B20005	18	Interface port	
7	Display and control unit		19	Level indicator	
8	Metrological ID label				
	(only on verified models or models a	cceptable	Not	shown:	
	for legal metrological verification)		ln-u	se dust covers:	
9	Lug for attaching an antitheft lockin	a device	- Fo	r weigh cell	6960FB01
10	DC jack	9		r control unit	6960LA02
11	Tare key		Prote	ective caps and plugs (set)	69 B20009

General Views of the Balances LA8200S (-OCE), LA8200P (-OCE), LA6200S (-OCE), LA4200S (-OCE), LA2200S (-OCE), LA820 (-OCE), LA420, LA2200P (-OCE), LA5200P (-OCE), LA12000S (-OCE), LA6200 (-OCE), LA4200, LA2200 (-OCE), LA12000P (-OCE) -OCE identifies the precision balances as verified for legal metrology in the EU\*



No.	Designation	Order no. for replacement	No.	Designation	Order no. for replacement
1	Weighing pan	69 LP0007	10	Function keys	
2	Pan draft shield		11	Print key	
	(depending on model)	69 LP0008	12	Keys for numeric input	
3	Shock absorber	69 LP0010	13	On/off key	
4	Leveling foot	69 B20005	14	Toggle key for alphabetic input	
5	Display and control unit		15	Weight display	
6	Metrological ID label		16	Interface port	
	(only on verified models or models acc	eptable	17	Level indicator	
	for legal metrological verification)				
7	Lug for attaching an antitheft locking	device	Not	shown:	
8	DCjack		ln-u	se dust covers:	
9	Tare key		- Fo	or weigh cell	6960FB02
	Ū.			or control unit	6960LA02
			Prot	ective caps and plugs (set)	69 B20009

### **General Views of the Balances LA64001S, LA34001S, LA16001S, LA34001P, LA34000** -OCE identifies the precision balances as verified for legal metrology in the EU\*



No.	Designation	Order no. for replacement	No.	Designation	Order no. for replacement
1	Weighing pan		8	Keys for numeric input	
	LA64001S, LA34001S, LA16001S,	Available	9	On/off key	
	LA34001P, LA34000:	on request	10	Toggle key for alphabetic input	
2	Leveling foot	69 LC0093	11	Weight display	
3	Display and control unit		12	Interface port	
4	Level indicator		13	DC jack	
5	Tare key		14	Metrological ID label	
6	Function keys			(only on verified models or models a	cceptable
7	Print key			for legal metrological verification)	

Not shown:

In-use dust cover for display and control unit

Available on request

# Specifications

### Standard Models

**General Specifications** 

AC power source/power requirements	AC adapter, 230 or 115 V, +15% 20%			
Frequency	48 – 60 Hz			
Allowable ambient operating temperature	0 +40 °C (273 313 K, 32 °F 104 °F)			
Operating temperature range	+ 10 + 30 °C			
Adaptation to ambient conditions	By selection of 1 of 4 optimized filter levels			
Display update (depends on the filter level selected)	0.1 – 0.4			
Power consumption	16 VA: maximum; 9 VA: average			
Hours of operation with fully charged YRB 06 Z external battery pack, approx.	14 h			
Selectable weight units	Grams, kilograms, carats, pounds, ounces, Troy ounces, Hong Kong taels, Singapore taels, Taiwanese taels, grains, pennyweights, milligrams, parts per pound, Chinese taels, Mommes, Austrian carats, Tola, Baht and Mesghal			
Selectable application programs	Mass unit conversion, counting, weighing in percent, animal weighing, recalculation, calculation, density determination, differential weighing, over/under checkweighing, time-controlled functions, totalizing, statistics, 2nd tare memory, IDs, product data memories			
Built-in interface	RS-232CFormat:7-bit ASCII, 1 start bit, 1 or 2 stop bitsParity:odd, even or spaceTransmission rates:150 to 19,200 baudHandshake:Software or hardware			

### Specifications of the Individual Models:

Model		LA310S	LA230S	LA230P	LA120S
Readability	mg	0.1	0.1	0.1/0.2/0.5	0.1
Weighing capacity	g	310	230	60/120/230	120
Tare range (subtractive)	g	- 310	- 230	- 230	- 120
Repeatability	≤±mg	0.2	0.1	0.1/0.2/0.5	0.1
Linearity	≤±mg	0.3	0.2	0.2/0.2/0.5	0.2
Sensitivity drift within +10 +30 °C	≤±/K	1 · 10 <sup>-6</sup>			
Response time (average)	S	2			
External calibration weight (of at least accuracy class)	g	200 + 100 (E2)	200 (E2)	200 (E2)	100 (E2)
Other allowable external calibration weights (of at least accuracy class)	g	200 (E2)	100, 150 (E2)	100, 150 (E2)	50 (E2)
Pan size	mm	Ø 90			
Dimensions (W $\times$ D $\times$ H)	mm	261 × 381 × 361			
Clearance above pan	mm	259			
Net weight, approx.	kg	8.7			
Dust and water protection rating according to EN 60529*		IP42			

\* = specially protected dust-tight and washdown resistant AC adapter; see the section on "Accessories"

Model		LA1200S	LA620S	LA220S	LA620P
Readability	g	0.001	0.001	0.001	0.001/0.002/0.005
Weighing capacity	g	1,200	620	220	120/240/620
Tare range (subtractive)	g	- 1,200	- 620	- 220	- 620
Repeatability (standard deviation)	≤±g	0.001	0.001	0.001	0.001/0.001/0.003
Linearity	≤±g	0.002	0.002	0.002	0.002/0.002/0.005
Sensitivity drift within +10 +30 °C	≤±/K	2 · 10 <sup>-6</sup>			
Response time (average)	S	1.5			
External calibration weight (of at least accuracy class)	g	1,000 (E2)	500 (E2)	200 (E2)	500 (F1)
Other allowable external calibration weights (of at least accuracy class)	g	-	300, 400, 600 (E2)	100 (E2)	200, 300, 400, 600 (F1)
Pan size	mm	Ø 130			
Dimensions ( $W \times D \times H$ )	mm	261 × 381 × 147			
Net weight, approx.	kg	8.3	6.6	6.6	6.6
Dust and water protection rating according to EN 60529*		IP54			

Model		LA5200D	LA3200D	LA2000P
Readability	g	0.001/0.01	0.001/0.01	0.001/0.01
Weighing capacity	g	1,010/5,200	1,010/3,200	1,010/2,000
Tare range (subtractive)	g	- 5,200	- 3,200	- 2,000
Repeatability	≤±g	0.001/0.01	0.001/0.01	0.001/0.01
Linearity	≤±g	0.002/0.01	0.002/0.01	0.002/0.01
Sensitivity drift within +10 +30 °C	≤±/K	2 · 10 <sup>-6</sup>	2 · 10 <sup>-6</sup>	2 · 10 <sup>-6</sup>
Response time (average)	S	2.5	1.5	1.5
External calibration weight (of at least accuracy class)	g	1,000 (E2)	1,000 (E2)	1,000 (E2)
Other allowable external calibration weights (of at least accuracy class)	g	2,000, 3,000 (E2)	2,000, 3,000 (E2)	-
Pan size	mm	Ø 130		
Dimensions ( $W \times D \times H$ )	mm	261 × 381 × 147		
Net weight, approx.	kg	8.4		
Dust and water protection rating according to EN 60529*		1P54		

\* = specially protected dust-tight and washdown resistant AC adapter; see the section on "Accessories"

Model		LA8200S	LA8200P	LA6200S	LA4200S	LA2200S
Readability	g	0.01	0.01/0.02/0.05	0.01	0.01	0.01
Weighing capacity	g	8,200	2,000/4,000/8,200	6,200	4,200	2,200
Tare range (subtractive)	g	- 8,200	- 8,200	- 6,200	- 4,200	- 2,200
Repeatability (standard deviation)	≤±g	0.01	0.01/0.01/0.03	0.01	0.01	0.01
Linearity	≤±g	0.02	0.02/0.02/0.05	0.02	0.02	0.02
Sensitivity drift within +10 +30 °C	≤±/K	2 · 10 <sup>-6</sup>				
Response time (average)	S	2	2	1.5	1.5	1.5
External calibration weight (of at least accuracy class)	g	5,000 (E2)	5,000 (F1)	5,000 (E2)	2,000 (E2)	2,000 (F1)
Other allowable external calibration weights (of at least accuracy class)	g	6,000, 7,000, 8,000 (E2)	-	6,000 (E2), 4,000 (E2)	3,000	1,000 (F1)
Pan size	mm	218 × 200				
Dimensions (W $\times$ D $\times$ H)	mm	261 × 381 × 86				
Net weight, approx.	kg	6.5				
Dust and water protection rating according to EN 60529*		1P54				

Model		LA820	LA420	LA2200P	LA5200P
Readability	g	0.01	0.01	0.01/0.02/0.05	0.01/0.02/0.05/0.1
Weighing capacity	g	820	420	400/800/2,200	1,200/2,400/3,800/5,200
Tare range (subtractive)	g	- 820	- 420	- 2,200	- 5,200
Repeatability (standard deviation)	≤±g	0.01	0.01	0.01/0.01/0.03	0.01/0.02/0.05/0.05
Linearity	≤±g	0.01	0.01	0.02/0.02/0.05	0.02/0.02/0.05/0.1
Sensitivity drift within +10 +30 °C	≤±/K	2 · 10 <sup>-6</sup>			
Response time (average)	S	1.5			
External calibration weight (of at least accuracy class)	g	500 (F2)	200 (F2)	2,000 (F2)	2,000 (F1)
Other allowable external calibration weights (of at least accuracy class)	g	600, 700, 800 (F2)	300, 400 (F2)	1,000 (F2)	3,000, 4,000, 5,000 (F1)
Pan size	mm	218 × 200			
Dimensions (W $\times$ D $\times$ H)	mm	261 × 381 × 86			
Net weight, approx.	kg	6.5			
Dust and water protection rating according to EN 60529*		IP54			

\* = specially protected dust-tight and washdown resistant AC adapter; see the section on "Accessories"

Model		LA12000S	LA6200	LA4200	LA2200	LA12000P
Readability	g	0.1	0.1	0.1	0.1	0.1/0.2/0.5
Weighing capacity	g	12,000	6,200	4,200	2,200	3,000/6,000/ 12,000
Tare range (subtractive)	g	- 12,000	- 6,200	- 4,200	- 2,200	-12,000
Repeatability (standard deviation)	≤±g	0.05	0.05	0.05	0.05	0.1/0.1/0.3
Linearity	≤±g	0.2	0.1	0.1	0.1	0.1/0.2/0.5
Sensitivity drift within +10 +30 °C	≤±/K	4 · 10 <sup>-6</sup>	4 · 10 <sup>-6</sup>	4 · 10 <sup>-6</sup>	2 · 10 <sup>-6</sup>	4 · 10 <sup>-6</sup>
Response time (average)	S	1	1	1	1	1
External calibration weight (of at least accuracy class)	kg	5 (F1)	5 (F2)	2 (F2)	2 (F2)	5 (F2)
Other allowable external calibration weights (of at least accuracy class)	kg	6 to 12 (F1)	4, 6 (F2)	3, 4 (F2)	1 (F2)	6, 7, 8, 9, 10, 11, 12 (F2)
Pan size	mm	218 × 200				
Dimensions (W $\times$ D $\times$ H)	mm	261 × 381 × 86				
Net weight, approx.	kg	6.5				
Dust and water protection rating according to EN 60529*		IP54				

Model		LA64001S	LA34001S	LA16001S	LA34001P	LA34000
Readability	g	0.1	0.1	0.1	0.1/0.2/0.5	1
Weighing capacity	g	64,000	34,000	16,000	8,000/16,000/ 34,000	34,000
Tare range (subtractive)	g	- 64,000	- 34,000	- 16,000	- 34,000	- 34,000
Repeatability	≤±g	0.1	0.1	0.05	0.05/0.05/0.1	0.5
Linearity	≤±g	0.5	0.2	0.2	0.2	0.5
Sensitivity drift within +10 +30 °C	≤±/K	3 · 10 <sup>-6</sup>	2 · 10 <sup>-6</sup>	2 · 10 <sup>-6</sup>	2 · 10 <sup>-6</sup>	2 · 10 <sup>-6</sup>
Response time (average)	S	1.5	1.5	1.5	1.5	1
External calibration weight (of at least accuracy class)	kg	10 (F1)	10 (F1)	10 (F1)	10 (F2)	10 (F2)
Other allowable external calibration weights (of at least accuracy class)	kg	5, 20, 25, 30 (F1)	15, 20, 25, 30 (F1)	11, 12, 13, 14, 15, 16 (F1)	15, 20, 25, 30 (F2)	15, 20, 25, 30 (F2)
Pan size	mm	300 × 400				
Dimensions ( $W \times D \times H$ )	mm	321 × 546 × 120				
Net weight, approx.	kg	16.0				
Dust and water protection rating according to EN 60529*		1P44				

\* = Specially protected dust-tight and washdown-resistant AC adapter; see the section on "Accessories."

### Models Verified by the Manufacturer, with EC Type Approval

**General Specifications** 

AC power source/power requirements	AC adapter, 230 or 115 V, +15	% 20%
Frequency	48 – 60 Hz	
Adaptation to ambient conditions	By selection of 1 of 4 optimize	d filter levels
Power consumption	16 VA: maximum; 9 VA: average	ge
Hours of operation with fully charged YRB 06 Z external battery pack, approx.	14 h	
Selectable application programs	calculation, density determinat	g, weighing in percent, animal weighing, recalculation, ion, differential weighing, checkweighing, time-controlled ing, statistics, 2nd tare memory, IDs, product data memories
Built-in interface	RS-232 C	
	Format:	7-bit ASCII, 1 start bit, 1 or 2 stop bits
	Parity:	odd, even or space
	Transmission rates:	150 to 19,200 baud
	Handshake:	Software or hardware

### Specifications of the Individual Models:

Model		LA310S-0CE	LA230S-0CE	LA230P-0CE	LA120S-0CE
Туре		isoTEST in conjunc	tion with BC BF		
Accuracy class*		I	I	I	I
Scale interval, d*	mg	0.1	0.1	0.1/0.2/0.5	0.1
Maximum weighing capacity, Max*	g	310	230	60/120/230	120
Verification scale interval, e*	g	0.001			
Minimum capacity, Min*	g	0.01			
Tare range (subtractive)		$\leq$ 100% of the max	imum capacity		
Application range according to CD*	g	0.01 - 310	0.01 - 230	0.01 – 230	0.01 - 120
Response time (average)	S	2			
Allowable operating temperature		273 313 K (0 +	40 °C, 32 °F 104 °	F) with isoCAL functio	n
Selectable weight units	Grams,	milligrams			
External calibration weight value (of at least accuracy class)	g	200 + 100 (E2)	200 (E2)	200 (E2)	100 (E2)
Other permissible external calibration weights (of at least accuracy class)	g	200 (E2)	100, 150 (E2)	100, 150 (E2)	50 (E2)
Pan size	mm	Ø 90			
Dimensions ( $W \times D \times H$ )	mm	261 × 381 × 361			
Net weight approx.	kg	8.7			
Dust and water protection rating according to EN 60529 <sup>1</sup> )		IP42			

<sup>1</sup>) = Specially protected dust-tight and washdown-resistant AC adapter; see the section on "Accessories."

\* CD = Council Directive 90/384/EEC for non-automatic weighing instruments used within the European Economic Area

Model		LA1200S-0CE	LA620S-0CE	LA220S-0CE	LA620P-0CE
Туре		isoTEST in conjunc	tion with BD BF		
Accuracy class*		I			
Scale interval, d*	g	0.001	0.001	0.001	0.001/0.002/0.005
Maximum weighing capacity, Max*	g	1,200	620	220	120/240/620
Verification scale interval, e*	g	0.01	0.01	0.01	0.01
Minimum capacity, Min*	g	0.1	0.02	0.02	0.02
Tare range (subtractive)		$\leq$ 100% of the max	. weighing capacity		
Application range according to CD*	g	0.1 - 1,200	0.02 - 620	0.02 - 220	0.02 - 620
Response time (average)	S	1.5			
Allowable operating temperature range	2	0 +40 °C (273	313 K, 32 °F 104 °I	F) with the isoCAL fun	ction 1)
Selectable weight units		Grams, kilograms			
External calibration weight value (of at least accuracy class)	g	1,000 (E2)			
Pan size	mm	Ø 130			
Dimensions (W $\times$ D $\times$ H)	mm	261 × 381 × 147			
Net weight, approx.	kg	8.3	6.9	6.9	6.9
Dust and water protection rating according to EN 60529 <sup>2</sup> )		1P54			

Model		LA8200S-0CE	LA8200P-0CE	LA6200S-0CE	LA4200S-0CE	LA2200S-0CE
Туре		isoTEST in conjunc	tion with BD BF			
Accuracy class*			I			I
Scale interval, d*	g	0.01	0.01/0.02/0.05	0.01	0.01	0.01
Maximum weighing capacity, Max*	g	8,200	2,000/4,000/8,200	6,200	4,200	2,200
Verification scale interval, e*	g	0.1	0.1	0.1	0.1	0.1
Minimum capacity, Min*	g	0.5	0.5	0.5	0.5	0.5
Tare range (subtractive)		$\leq$ 100% of the max. weighing capacity				
Application range according to CD*	g	0.5 - 8,200	0.5 - 8,200	0.5 - 6,200	0.5 - 4,200	0.5 - 2,200
Response time (average)	S	2	2	1.5	1.5	1.5
Allowable operating temperature range	2	0 +40 °C (273	313 K, 32 °F 104	°F) with the isoCAL	function <sup>1</sup> )	
Selectable weight units		Grams, kilograms				
Pan size	mm	218 × 200				
Dimensions (W $\times$ D $\times$ H)	mm	261 × 381 × 86				
Net weight. approx.	kg	6.5				
Dust and water protection rating according to EN 60529 <sup>2</sup> )		IP54				

1) = With the isoCAL function deactivated, the verified balance can only be used within the limited temperature range (can only be modified by the Sartorius Service Center): For balances of accuracy class ①: +15°C to +25°C (+59°F to +77°F) For balances of accuracy class ①: +10°C to +30°C (+50°F to +86°F)
 2) = Specially protected dust-tight and washdown-resistant AC adapter; see the section on "Accessories."
 \* CD = Council Directive 90/384/EEC for non-automatic weighing instruments used within the European Economic Area

Model		LA820-0CE	LA2200P-0CE	LA5200P-0CE	LA12000S-0CE	LA6200-0CE	LA2200-0CE
Туре		isoTEST in conj	junction with BD	BF			
Accuracy class*							
Scale interval, d*	g	0.01	0.01/0.02/ 0.05	0.01/0.02/ 0.05/0.1	0.1	0.1	0.1
Maximum weighing capacity, Max*	g	820	400/800/ 2,200	1,200/2,400/ 3,800/5,200	12,000	6,200	2,200
Verification scale interval, e*	g	0.1	0.1	0.1	1	1	0.1
Minimum capacity, Min*	g	0.5	0.5	0.5	5	5	5
Tare range (subtractive)		$\leq$ 100% of the	max. weighing c	apacity			
Application range according to CD*	g	0.5 - 820	0.5 - 2,200	0.5 - 5,200	5 - 12,000	5 - 6,200	5 - 2,200
Response time (average)	S	1.5	1.5	1.5	1	1	1
Allowable operating temperature range		0 +40 °C (27	3 313 K, 32 °l	F 104 °F) with	the isoCAL functi	ion1)	
Selectable weight units		Grams, kilograr	ns				
Pan size	mm	218 × 200					
Dimensions ( $W \times D \times H$ )	mm	261 × 381 × 86					
Net weight. approx.	kg	6.5					
Dust and water protection rating according to EN 60529 <sup>2</sup> )		IP54					

Model		LA12000P-0CE	LA34001S-0CE	LA16001S-0CE	LA34001P-0CE	LA34000-0CE
Туре		isoTEST in conjunction with BD BF	isoTEST in conjunction with BF BF			
Accuracy class*						
Scale interval, d*	g	0.1/0.2/0.5	0.1	0.1	0.1/0.2/0.5	1
Maximum weighing capacity, Max*	kg	3/6/12	34	16	8/16/34	34
Verification scale interval, e*	g	1	1	1	1	1
Minimum capacity, Min*	g	5	5	5	5	50
Tare range (subtractive)		$\leq$ 100% of the max	x. weighing capacity			
Application range acc. to CD*	g	5 - 12,000	5 - 34,000	5 - 16,000	5 - 34,000	50 - 34,000
Response time (average)	S	1	1.5	1.5	1.5	1
Allowable operating temperature range	-	0 +40 °C (273	. 313 K, 32 °F 104	4 °F) with the isoCAL	function <sup>1</sup> )	
Selectable weight units		Grams and kilograms	Grams and kilograms	Grams and kilograms	Grams and kilograms	Kilograms
Pan size	mm	218 × 200	300 × 400			
Dimensions (W $\times$ D $\times$ H)	mm	261 × 381 × 86	321 × 546 × 120	321 × 546 × 120	321 × 546 × 120	321×546×120
Net weight, approx.	kg	6.5	16.0	16.0	16.0	16.0
Dust and water protection rating According to EN 60529 <sup>2</sup> )		IP54	1P44	1P44	1P44	1P44

With the isoCAL function deactivated, the verified balances can be used within the limited temperature range (can only be modified by the Sartorius Service Center): For balances of accuracy class ①: +15°C to +25°C (+59°F to 77°F)
 For balances of accuracy class ①: +10°C to +30°C (+50°F to 86°F)

<sup>2</sup>) = Specially protected dust-tight and washdown-resistant AC adapter; see the section on "Accessories"
 \* CD = Council Directive 90/384/EWG for non-automatic weighing instruments used within the European Economic Area

# Accessories (Options)

	Order No.		Order No.
<b>Data printer,</b> suitable for use in legal metrology; with date, time, statistics and transaction counter functions	YDP03-0CE	<b>Weighing scoop</b> Made of chrome-nickel steel, 90 mm × 32 mm × 8 mm	641214
Paper rolls, for YDP03-0CE; 5 units, each with 50 m	6906937	<b>Ionizing blower</b> 220 V for electrostatically charged samples 110 V	YIB01-0DR YIB01-0UR
Ink ribbon cartridge, for YDP03-0CE	6906918	Stat Pen, unit to neutralize static electricity	
External rechargeable battery pack, with battery level indicator	YRB06Z	on samples (100V to 230V, 50/60Hz) Cable for connecting the weighing	YSTP01
<b>SartoConnect</b> data transfer software; with RS-232C standard cable; for direct input of weighing data into an application program (e.g., such as Excel)		cell to a separate display and control unit (length: 2.70 m) – for balances with a weighing capacity ≤ 64 kg	YCC01-19M3
with RS-232 C connecting cable, length 1 m with RS-232 C connecting cable, length 5 m with RS-232 C connecting cable, length 15 m	YSC01L YSC01L5 YSC01L15	Flow Rate Controller for pumps and feed units with analog or pulse interfaces	YFC02Z-V2
Foot switch, for activating the print, tare or F key; function can be selected by menu code; incl. T-connector	YFS01	Support arm, for raised display configuration – for balances with a weighing capacity $\leq$ 12 kg – for balances with a weighing capacity $\geq$ 16 kg	YDH01LP YDH02LP
Hand switch, for activating the print, tare or F key; function can be selected by menu code; incl. T-connector	YHS02	Bar code scanner (YCC01-0024M01 required)	YBR02FC
T-connector	YTC01	Cable for connecting the bar code scanner	YCC01-0024M01
for connecting two peripheral devices to the balance		Standard Operating Procedure (SOP)	YSL01E
Balance table for precise, reliable weighing operations	YWT01	<b>RS-232C interface cable</b> for connecting the balance to a PC with a 25-pin COM port; length approx. 1.5 m	7357312
Cast stone table, with damping device	YWT03	RS-232C interface cable	7357314
Remote display LCD; height of digits: 13 mm; reflective	YRD02Z	for connecting the balance to a PC with a 9-pin COM port; length approx. 1.5 m	
Density determination kit for all 0.1 mg models	YDK01	RS-232 USB interface cable	YCC01-USBM2
for all 1 mg/10 mg models	YDK01LP	AC adapter ING-2 with IP65 protection rating	
Draft shield chamber with sliding doors for 1-mg LA models	YDS01LP	for 230 V for 120 V	69 71899 69 71500
In-use dust cover - for models with a round weighing pan	Available on request	Antistatic pan for models with a readability of 0.1 mg	YWP01LA
<ul> <li>for models with a rectangular weighing pan (weighing capacity ≤ 12.1kg)</li> </ul>	Available on request	Hook for below-balance weighing for models LA34001S, LA16001S, LA34001P, LA34000	69EA0040
<b>3-segment checkweighing display</b> red/green/red, for over/under checkweighing (light/heavy); incl. T-connector	YRD11Z	<b>Calibration weights</b> for all LA balances; extensive assortment; available with certification	Information on request
Carrying case, for all models, up to 12.1 kg	YDB01LP		
Weighing bowls/pans/trays: Made of chrome-nickel steel; without pouring spout; for all models with a weighing capacity >400 g; – 1,000 ml capacity – 500 ml capacity	641211 641212		

### **Declarations of Conformity**

The CE Mark on Sartorius Equipment

In 1985, the Council of the European Community approved a resolution concerning a new approach to the technical harmonization and standardization of national regulations. The organization for monitoring compliance with the directives and standards concerning the CE marking is governed in the individual EU Member States through the implementation of the EC Directives adopted by the respective national laws. As of December 1993, the scope of validity for all EC Directives has been extended to the Member States of the European Union and the Signatories of the Agreement on the European Economic Area.

Sartorius complies with the EC Directives and European Standards in order to supply its customers with weighing instruments that feature the latest advanced technology and provide many years of trouble-free service.

The **C€** mark may be affixed only to weighing instruments and associated equipment that comply with the applicable Directive(s):

### Council Directive 89/336/EEC "Electromagnetic compatibility (EMC)"

1. Electromagnetic compatibility:

1.1 Reference to 89/336/EEC: Official Journal of the European Communities, Nr. 2001/C105/03

#### EN 61326-1

Electrical equipment for measurement control and laboratory use EMC requirements

Parts 1: General requirements Defined immunity to interference: Industrial areas, continuous, un-monitored operation Limitation of emmissions: Residential areas Class B

### Important Note:

The operator shall be responsible for any modifications to Sartorius equipment and for any connections of cables or equipment not supplied by Sartorius and must check and, if necessary, correct these modifications and connections. On request, Sartorius will provide information on the minimum operating specifications (in accordance with the Standards listed above for defined immunity to interference).

### Council Directive 73/23/EEC "Electrical Equipment Designed for Use within Certain Voltage Limits" Applicable European Standards:

### EN 60950

Safety of information technology equipment including electrical business equipment

### EN 61010

Safety requirements for electrical equipment for measurement, control and laboratory use Part 1: General requirements

If you use electrical equipment in installations and under ambient conditions requiring higher safety standards, you must comply with the provisions as specified in the applicable regulations for installation in your country.

Weighing Instruments for Use in Legal Metrology: Directive 90/384/EEC "Non-automatic weighing instruments" This Directive regulates the determination of mass in legal metrology.

For the respective Declaration of Conformity for weighing instruments that have been verified by Sartorius for use as legal measuring instruments and that have an EC Type-Approval Certificate, see the page after next.

This Directive also regulates the performance of the EC verification by the manufacturer, provided that an EC Type-Approval Certificate has been issued and the manufacturer has been accredited by an officer or a Notified Body registered at the Commission of the European Community for performing such verification.

The legal basis allowing Sartorius to perform EC verification is constituted by the EC Council Directive No. 90/384/ EEC on non-automatic weighing instruments that has been in effect since January 1, 1993, in the Internal Market as well as by the Certificate of Accreditation of the Sartorius AG Quality Management System issued by the Metrology Department of the Regional Administration Office of Lower Saxony, Germany ("Niedersächsisches Landesverwaltungsamt -Eichwesen") on February 15, 1993.

For information on the CC mark on Sartorius equipment and legal regulations currently applicable in your country, and to obtain the names of the persons to contact, please ask your local Sartorius office, dealer or service center.

### "New Installation" Service

Initial verification is covered in our "New Installation" service package. In addition to initial verification, this package provides you with a series of important services which will guarantee that you achieve optimal results with your weighing instrument:

- Installation
- Startup
- Inspection
- Training
- Initial verification

If you would like Sartorius to perform initial verification of your weighing instrument, contact an authorized service representative.

### "EC Verification" – A Service Offered by Sartorius

Our service technicians are authorized to perform verification\* of your weighing instruments that are acceptable for legal metrological verification and can inspect and verify the metrological specifications at the place of installation within the Member States of the European Union and the Signatories of the Agreement on the European Economic Area.

# Subsequent Verifications within the European Countries

The expiration date of the verification depends on the national regulations of the country in which the weighing instrument is used. For information on verification and legal regulations currently applicable in your country, and to obtain the names of the persons to contact, please contact your local Sartorius office, dealer or service center.

\* in accordance with the accreditation certificate issued to Sartorius AG

# **CE** Declaration of Type Conformity to Directive No. 90/384/EEC

This declaration is valid for non-automatic electromechanical weighing instruments for use in legal metrology. These weighing instruments accepted for legal metrological verification have an EC Type-Approval Certificate. The model(s) concerned is(are) listed below along with the respective type, accuracy class, and number of the EC Type-Approval Certificate:

Model Weighing instrument type		Accuracy Class	EC Type Approval No.		ction with Test tificate
				Туре	Certificate No
LA0CE	iso-TEST		D97-09-018	BC BF	D09-96.30
LA0CE	iso-TEST	(D, (D)	D97-09-018	BD BF	D09-96.30
LA0CE	iso-TEST		D97-09-018	BF BF	D09-96.30

SARTORIUS AG declares that its weighing instrument types comply with the requirements of the Council Directive on non-automatic weighing instruments, no. 90/384/EEC of 20 June 1990; the associated European Standard "Metrological aspects of non-automatic weighing instruments," No. EN 45501; the amended, currently valid versions of the national laws and decrees concerning legal metrology and verification in the Member States of the European Union, the EU, and the Signatories of the Agreement on the European Economic Area, which have adopted this Council Directive into their national laws; and with the requirements stipulated on the Type-Approval Certificate for verification. This Declaration of Type Conformity is valid only if the ID label on the weighing instrument has the CE mark of conformity and the green metrology

Sartorius AG 37070 Goettingen, Germany Signed in Göttingen, 29.05.2006

Dr. G. Maaz President of the Mechatronics Division

sticker with the stamped letter "M" (the twodigit number in large print stands for the year in which the mark has been affixed):



If these marks are not on the ID label, this Declaration of Type Conformity is not valid. Validity can be obtained, for example, by submitting the weighing instrument for final action to be taken by an authorized representative of SARTORIUS AG. The period of validity of this Declaration of Type Conformity shall expire upon any tampering with, repair or modification of this weighing instrument or, in some Member States, on the date of expiration. This declaration applies only to the weighing instrument without peripheral devices.

The operator of this weighing instrument shall be responsible for obtaining an authorized renewal of the verification, such as subsequent or periodic verification, of the weighing instrument for use as a legal measuring instrument.

Elected. :.V. J. Rehwald

Head of the Production Department Mechatronics / Weighing Technology Division

LOP-3.225\_an2e\_2005.06.09.doc P106eb01.doc

	~3~
	EG-Bauartzulassung EC type-approval certificate
Zulassungsinhaber:	Sartorius AG
Issued to:	Weender Landstr. 94-108 37075 Göttingen
Rechtsbezug: In accordance with:	§ 13 des Gesetzes über das Mess- und Eichwesen (verification act) vom/dated 23. März 1992 (BGBI. I S. 711), zuletzt geändert am (last amended on) 25.11.2003 (BGBI. I S. 2304), in Verbindung mit Richtlinie (in connection with council directive) 90/384/EWG, geändert durch (amended by) 93/68/EWG
Bauart: In respect of:	Nichtselbsttätige elektromechanische Waage mit oder ohne Hebelwerk Nonautomatic electromechanical weighing instrument with or without leverwork
Тур / туре:	iso-TEST
	Genauigkeitsklasse/ <i>class</i> (), (), (), (), () Max 2,1 g 300 t Option: Mehrteilungswaage, Mehrbereichswaage <i>Multi-interval instrument, multiple range instrument</i>
Zulassungsnummer: Approval number:	D97-09-018 6. Revision
Gültig bis: Valid until:	26.06.2007
Anzahl der Seiten: Number of pages:	16
Geschäftszeichen: Reference No.:	PTB-1.12-4023683
Benannte Stelle: Notified Body:	0102
Im Auftrag By order	Braunschweig, 22.05.200
UTISCH!	Siegel Seal

Die Hauptmerkmale, Zulassungsbedingungen und Auflagen sind in der Anlage enthalten, die Bestandteil der Revision der EG-Bauartzulassung ist. Hinweise und eine Rechtsbehelfsbelehrung befinden sich auf der ersten Seite der Anlage The principal characteristics, approval conditions and special conditions, if any, are set out in the Annex which forms an integral part of this Revision of the EC type-approval certificate. For notes and information on legal remedies, see first page of the Annex.

# Physikalisch-Technische Bundesanstalt

Braunschweig und Berlin



PTB

Ausgestellt für: Issued to:	Sartorius AG Weender Landstraße 94 – 108 37075 Göttingen Bundesrepublik Deutschland		
Prüfgrundlage: In accordance with:	EN 45501 (1992), Nr.8.1, OIML R 76-1 (1992)		
Gegenstand: <i>Object:</i>	Lastaufnehmer mit Wägezelle und Auswerteelektronik mit digitalem Ausgang als Modul einer elektromechanischen Waage zum Anschluß an geeignete Anzeige- und Bedienterminals Load receptor with load cell and electronic device with digital output as module of an electromechanical weighing instrument for connection to suitable display- and operator-terminals Typ / type BA BF, BC BF, BD BF, BF BF, HC BF, MA BF und MD BF		
Kennummer: Serial number:			
Prüfscheinnummer: Test certificate number:	D09-96.30 7. Revision / Revision 7		
Datum der Prüfung: Date of Test:			
Anzahl der Seiten: Number of pages:	12		
Geschäftszeichen: Reference No.:	1.14 – 02001430		
Benannte Stelle: Notified Body:	0102		
Im Auftrag By order	AU THE SAME	Braunschweig, 2002-11-13 Siegel <sub>Seal</sub>	

392 00 e-rb

Hinweise siehe erste Seite der Anlage, die Bestandteil des Prüfscheines ist. For notes, see first page of the Annex which forms an integral part of the test certificate.

Plates and Markings			
	alternative		Example terminal YAC02LA
	type BC BF external electronics		T
Type BF BF		ed P unlocked	
only S P	T S unlocked	<u>s</u>	
unlocked For variants for use in haz (recognizable at a"-XCE" in the K Descriptive plate with CE-c	zardous areas the model name)	TMK	
M Mark for EC verification (g S Protective seal, not for acc			ith model designation ccess switch
YAC02FC,TN, TN-X, TN	terminals isi, YAC01LA, YAC01LA, YALPro front-mounted, raised PC with Sartorius Win Scale Y	post-mounted) or positioned	FC, I separately.
	12345678 10°C / +40°C	weighing instrument	K
	tax 2200 g d= 0,1 g lin 5 g e= 0,1 g lel designation T	]	
Weighing         module           LA2200-0CE         BD BF D09-96.           12345678         IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	12345678		
PPBF290506e		5T + BC BF, BD BF, BF BF oval certificate D97-09-018	+ EC Test certificate D09-96.30

# Index

	Page
Accessories (options)	140
Acoustic signal	39
Additional functions	97
Animal weighing	57
Antitheft device	11
Application filter	16
Application programs	49
Applications menu	22
Applications, combining	111
Applications, configuring	22
Auto print functions	31
	ا د
Auto start application	40
with power-on	49
Auto zero	16
Balance menu	16
Balance, automatic shutoff	21
Balance, installation	8
Balance-specific information	34
Bar code scanner	38
Bar graph	113
Basic weighing functions	35
Below-balance weighing	35
Block printout	48
<b>C</b> abling diagram	123
Cabling diagram	
Calculation	61
Calibration/adjustment	40
Calibration/adjustment, automatic	46
Care and maintenance	127
Checkweighing	79
Cleaning the balance	127
Combining applications	110
Configuring applications	22
Configuration	12
Configuring printouts	32
Connecting to AC power	10
Contents	2
Contrast, display	21
Control port	38, 80
Counting	51
<b>D</b> ata output functions	113
Data ID codes	99
Data input format	131
Data interface port	118
Data output format	118
Data output, following	
print command	121
Data output, initialize	121
Declaration of conformity	141
Density determination	63
Display	4, 39,
	113
Display backlighting	120
Display, remote	9
DKD uncertainty of measurement	9 108
Dustcover, replacing	
Dustover, replacing	127

	Page
EC type-approval certificate	143
Emulation MP8 interface	39
Enter/change password	18
Equipment supplied	9
Error codes and messages	124
External calibration	46
Factory settings	20, 34,
	98
FlexPrint	31
Formulation	90
General password	Appendix
General view of balances	129
Sellerar view of bulances	125
Handshake mode	121
dentifiers	99
Input	5,14
Intended use	2
Installation	7
Interface port	, 117
Interface port, input/output	118
Internal calibration	45
ISO/GLP printout/record	
isoCAL function	116 47
Keypad	3, 39
Language setting	12
Leveling the balance	11
Line format	31, 115
Manual storage – M+	104
Manual/automatic print mode	30
Menu – reset factory settings	20, 34,
wente – reset factory settings	
	39
Menu parameters – read only	30
Metrological data, in display	113
MP8 interface emulation	39
<b>O</b> perating design	3
Operation	35
Options	140
Overview of Application menu	23
<b>P</b> arameter settings	22
0	
Parameters in menu – read only	30
Password, enter/change	18
Password, general	Appendix
Pin assignment chart	123
Plates and Markings	145
Power-on mode	39
rower-on mode	97
Preset tare (2nd tare memory)	30
Preset tare (2nd tare memory) Print application parameters	
Preset tare (2nd tare memory) Print application parameters Print manually/automatically	30
Preset tare (2nd tare memory) Print application parameters	

	Page
Recycling instructions	128
Reference sample updating	52
Remote display	9
Repairs	127
Replacing the dust cover	127
Reset factory settings – menu	20, 34,
	39
Safety inspection	127
Safety precautions	3, 10
Second tare memory (preset tare)	97
Service	127
Soft keys	4
Software handshake	121
Specifications	133
SQmin function	106
Statistics	93
Storage and shipping conditions	7
Symbols in display	113
Synchronization	121
Time-controlled functions	84
Toggling between weight units	49
Totalizing	86
Totalizing	00
Universal remote control switch	38
Unpacking the balance	7
User data, input	5
User password	Appendix
Warmun time	10
Warmup time Warnings and safety precautions	3
Weighing in percent	5 54
Weighing series number	120
Weight set number	16, 120
Workstation number	120
	120

### **Entering the General Password**

# Enter/Change Password Select the Setup menu: Press ↓

- > SETUP SELECTION is displayed
- Select the user input function: Press the **Input** soft key
- > The password prompt is displayed:

SETUP	PASSW.CHECK				
Enter	passuc	ord:			
<<					لہ

- Enter the General Password (see below)
- Confirm password:
   Press the +J soft key
- > User data is displayed

- Select the password setting function: Press the  $\lor$  soft key repeatedly until
- > Enter password: is displayed, together with the current password setting
- Define a new password: Enter letters/numbers for the new password (8 characters max.) To delete the current password: press
   and confirm
- To confirm the new password: press the J soft key
- Exit the Setup menu: Press the < < soft key
- > Restart your application

General Password: 40414243

Sartorius AG Weender Landstrasse 94–108 37075 Goettingen, Germany

Phone +49.551.308.0 Fax +49.551.308.3289 www.sartorius.com

Copyright by Sartorius AG, Goettingen, Germany. All rights reserved. No part of this publication may be reprinted or translated in any form or by any means without the prior written permission of Sartorius AG. The status of the information, specifications and illustrations in this manual is indicated by the date given below. Sartorius AG reserves the right to make changes to the technology, features, specifications and design of the equipment without notice.

Status: June 2006, Sartorius AG, Goettingen, Germany

Printed in Germany on paper that has been bleached without any use of chlorine W1A000 · KT Publication No.: WLA6004-e06063